

**MARYLAND DEPARTMENT OF THE ENVIRONMENT
LAND AND MATERIALS ADMINISTRATION – OIL CONTROL PROGRAM**

1800 Washington Boulevard, Suite 620 • Baltimore, Maryland 21230-1719
(410) 537-3442 • 1-800-633-6101 • <http://www.mde.maryland.gov>

Report of Observations

Date	May 4, 2026	Facility ID	7874
Type of Inspection / Observations	Joint MDE/EPA Piscataway Creek Site Visit	Case #	2026-0420-PG
Site / Facility Name	Joint Base Andrews – [REDACTED] Fuel Hydrant Loop Release	Permit #	2022-OPT-5217 24OGR-1768
Address	[REDACTED] Andrews AFB	MDEnviroScreen	31.1
Point of Contact (POC)	[REDACTED]	POC Phone	[REDACTED] [REDACTED]
POC Email	[REDACTED] [REDACTED]	POC Fax	-

Remarks: On May 4, 2026, Maryland’s Department of the Environment (MDE) Oil Control Program (OCP) Remediation Division case manager Chris King met with [REDACTED] of the Joint Base Andrews (JBA) team and Kevin Heym, On Scene Coordinator for Environmental Protection Agency (EPA) Region 3, to view Piscataway Creek to [REDACTED] the base perimeter fencing. OCP and EPA personnel did not observe containment on base during this site visit.


MDE and EPA personnel were escorted by [REDACTED] to Piscataway Creek to [REDACTED] the base perimeter fencing. [REDACTED] noted that weekly surface water sampling was being completed on this date. Upon arrival at the creek, three locations were observed by EPA and MDE personnel, including [REDACTED] and Sample [REDACTED] location. Absorbent booms [REDACTED] perimeter fence exhibited evidence of iron oxidizing bacteria. Based on the evidence of iron oxidizing bacteria, MDE personnel noted that the absorbent materials should be replaced. Petroleum absorption was not observed. Neither petroleum sheen nor petroleum odors were noted along Piscataway Creek to [REDACTED] the perimeter fencing during the site visit.

Photographs Taken: Yes No

**MDE/LMA/OCP
Report of Observation**

NOTES

- Report the following conditions to the Department immediately, but not later than 2 hours after the detection, at **410-537-3442** during normal business hours, or to the Emergency Response Division hotline at **1-866-633-4686**:
 - Evidence of a spill, release, or discharge of oil;
 - A release detection method, monitoring results, or investigation of an alarm indicates that a spill, release, or discharge may have occurred;
 - Investigation of an inventory variation reveals a leak;
 - If a storage tank system fails a test for tightness,;
 - Two consecutive inconclusive precision tightness test results;
 - A storage system (aboveground or underground) is determined to be leaking;
 - Test failure of spill catchment basins, containment sumps, or test of a cathodic protection resulting determination the system is inadequate;
 - Presence of liquid phase hydrocarbons; absorbed or free product in soil; vapors in soil, basement, sewer or utility line; or waters of the State;
 - Unusual operating conditions exist, such as erratic behavior of product dispensing equipment, the sudden loss of a regulated substance from a storage tank system, unexplained presence of water in a storage tank, or liquid in the interstitial space of a secondary containment system.
- Reports should **not** be made via voice messages to OCP case managers.
- Operating without a permit or in violation of a permit, regulation, or law may result in the assessment of civil or administrative penalties and or other legal sanctions.

MDE Representative: Chris King Phone: 410-537-4152 Email: christopherj.king@maryland.gov	Emailed: <input checked="" type="checkbox"/> Email: [REDACTED] Person Interviewed (print): [REDACTED]
Signature: 	Signature:
Date: May 5, 2026	Date: