
SOURCE WATER ASSESSMENT

FOR THE TOWN OF THURMONT FREDERICK COUNTY, MD



Prepared By
Maryland Department of the Environment
Water Management Administration
Water Supply Program
February 2000



TABLE OF CONTENTS

Page Summary
Introduction
Well Information
Hydrogeology2
Source Water Assessment Area Delineation
Potential Sources of contamination
Water Quality Data
Susceptibility Analysis
Management of the WHPA13
References
Sources of Data
Figures

SUMMARY

The Water Supply Program has conducted a Source Water Assessment for the Town of Thurmont. The major components of this report as described in Maryland's Source Water Assessment Plan (SWAP) are 1) delineation of an area that contributes water to the source, 2) an inventory of potential sources of contamination, and 3) determining the susceptibility of the water supply to contamination. Recommendations for management of the assessment area conclude this report.

The sources of Thurmont's water supply are unconfined fractured-rock aquifers. Thurmont is currently using four of the six wells comprising its water system. The Source Water Assessment area was delineated using hydrogeologic mapping and fracture trace analysis.

Potential point sources of contamination within the assessment area were identified from field inspections and contaminant inventory databases. The Maryland Office of Planning's 1997 land use map for Frederick County was used to identify non-point sources of contamination.

The susceptibility analysis is based on the existing water quality data for the Town of Thurmont's water system, the presence of potential sources of contamination in the assessment area, well integrity, and the inherent vulnerability of the aquifer. The combination of these factors cause Thurmont's wells to be susceptible to contamination by nitrate, radon, volatile organic compounds, synthetic organic compounds, and (well No. 3 only) microbiological contaminants.

INTRODUCTION

The Town of Thurmont is located approximately 15 miles north of the City of Frederick, in Frederick County. Thurmont's water supply system serves a population of 4091 and has 1984 service connections. Thurmont presently obtains its water supply from four wells (Nos. 2, 3, 4, and 7), and has a fifth well (No. 8) which will be put into service in the near future (Figure 1). A sixth standby well (No. 5) may eventually be used again if supply needs warrant putting it back into service. Thurmont abandoned the use of Well No. 5 due to petroleum contamination in 1983.

WELL INFORMATION

A review of the well completion reports and sanitary surveys of Thurmont's water system indicate that Well Nos. 5, 7, and 8 meet the State's well construction standards and that Well Nos. 2, 3, and 4 were installed prior to the 1973 Regulations went into effect. Table 1 contains a summary of the well construction data.

PLANT	SOURCE NAME	PERMIT	TOTAL	CASING	AQUIFER
			DEPTH	DEPTH	
02	THURMONT 2	n/a	192	73	FREDERICK LIMESTONE
03	THURMONT 3	FR690518	105	29	FREDERICK LIMESTONE
03	THURMONT 4	FR720327	294	70	FREDERICK LIMESTONE
04	THURMONT 5	FR738626	400	32	FREDERICK LIMESTONE
05	THURMONT 7	FR738820	197	73	GETTYSBURG SHALE
06	THURMONT 8	FR940883	160	130	GETTYSBURG SHALE

Table 1. Town of Thurmont Well Information.

The four production wells (2, 3, 4, and 7) are currently used at average rates of 120, 275, 400, and 300 gallons per minute (gpm) respectively. Well No. 8 has an approximate rated capacity of 300 gpm, but is currently only permitted for a maximum of 162 gpm and has a similar pump capacity. The capacity of Well 5 is 240 gpm.

HYDROGEOLOGY

Thurmont's wells draw water from two distinct aquifers, the Frederick Limestone and the Gettysburg Shale (Table 1). The western portion of Thurmont is underlain by the

Frederick Limestone, a dark-gray, thin-bedded clayey limestone (Nutter, 1973). This formation is a prolific aquifer due to solution-enlarged fractures and channels that readily transport water. The eastern side of Thurmont is underlain by the Gettysburg Shale, which consists chiefly of westward-dipping beds of red shale and siltstone and some sandstone (Meyer and Beall, 1958). The well log of No. 7 shows that limestone sections were encountered in the well at various depths.

Seventy-two hour pump tests were conducted for both the Frederick Limestone and Gettysburg Shale as required for the Ground Water Appropriation and Use Permit (GAP). Based on the pumping tests the transmissivities of the Frederick Limestone and Gettysburg Shale were found to be 547 ft²/day and 720 ft²/day respectively.

SOURCE WATER ASSESSMENT AREA DELINEATION

For ground water systems, a Wellhead Protection Area (WHPA) is considered the source water assessment area for the system. A WHPA was originally delineated in 1995 for Well Nos. 2, 3, 4, 7, and 8 using hydrogeologic mapping and fracture trace analysis. The source water assessment area was modified from the original WHPA to include a Zone 1 for Well 5 and Zone 3 for Well 3.

Hydrogeologic mapping identifies the physical and hydrologic features that control ground water flow (EPA, 1991). In Thurmont, hydrogeologic mapping was used to identify geologic formation boundaries and watershed boundaries. In this setting, it is assumed that ground water divides coincide with watersheds.

Fracture traces are surface expressions of vertical, closely spaced joints and fractures in the bedrock below. Highly developed fracture systems in bedrock aquifers readily transmit water; thus fracture trace analysis is commonly used to locate high yield wells in fractured bedrock aquifers. A well intercepting a fracture, or fracture zone, will demonstrate a drawdown pattern that is greatest along the trace of the fracture(s). Earth Data, Inc. mapped fracture traces near Thurmont's wells in February 1995 using aerial photographs (Fig. 2). Fracture traces were not mapped around Well No. 2 because the well is located in a highly developed area where any fracture trace would be difficult to identify.

Delineation Zones

Zone 1: The Zone 1 WHPA is an area around a well that is considered most vulnerable to contamination. A one-year time of travel (TOT) is the criterion defined for Zone 1 for wells in unconfined Coastal Plain aquifers in MDE's Source Water Assessment Plan. Because TOT cannot be precisely modeled in a heterogeneous aquifer such as this one, a buffer zone surrounding the fracture traces is considered Zone 1 for Thurmont's WHPA. Three Zone 1 WHPAs were delineated and encompass the fracture traces around well Nos. 3, 4, 5, 7, and 8 (Fig. 2). Since fracture traces could not be mapped around Well No. 2, the fourth Zone 1 WHPA is a

500 foot radius circle around this well. This radius is slightly larger than one obtained by using a volumetric flow equation with a 1-year TOT.

Zone 2: The Zone 2 WHPA is a larger area around a well through which any contaminant present could ultimately reach the well. The Zone 2 WHPA for Thurmont's wells is the combination of watershed boundaries and geologic boundaries surrounding all the wells. The western boundary of the WHPA is the contact between the Frederick Limestone and the Harper's Formation. The other boundaries are roughly the watershed of the wells.

Zone 3: The Zone 3 WHPA is the area between the 10 year TOT boundary and ultimate recharge area to a well. The likelihood that a contaminant in this area would reach the well depends on many factors including, but not limited to, soil attenuation and travel times from the recharge area to the stream and eventually downstream to the well. In this case Zone 3 is the ultimate recharge area for Well No. 3, which was determined to be under the direct influence of surface water in 1994. A dye trace investigation (Steinfort, 1993) indicated that a small portion of the water captured by Well No. 3 is directly from Hunting Creek. The Hunting Creek watershed is mapped as Zone 3 (Fig. 3).

POTENTIAL SOURCES OF CONTAMINATION

Several potential point sources of contamination were identified during the original mapping of Thurmont's WHPA. The list of point sources has been revised in this report based on field inspections by MDE employees, updated databases, and an interview with the Town of Thurmont's operator Mr. Gary Dingle on November 3, 1999. Several commercial or industrial establishments that have Underground Storage Tanks (USTs), Leaking Underground Storage Tanks (LUSTs), or are classified as Controlled Hazardous Substance Generators (CHS) are identified on Figure 2. Miscellaneous potential contaminant sites include pesticide dealers, buildings with chemical storage, and maintenance facilities for vehicles and machinery. Table 2 lists the facilities identified and their potential sources of contaminants. This is based on generalized categories and often the potential contaminant depends on the specific chemicals and processes being used at the facility. The potential contaminants for an activity may not be limited to those listed. Potential contaminants are grouped as Volatile Organic Compounds (VOC), Synthetic Organic Compounds (SOC), and Heavy Metals (HM).

Two incidents of ground water contamination are known to exist within the WHPA. MDE is overseeing the cleanup of petroleum contaminated ground water due to a LUST at the Exxon station. Well No. 5 was shut down in 1983 due to high levels of benzene and other gasoline byproducts associated with the Exxon LUST. MDE's Oil Control Program reports that the Exxon is continuing its remediation efforts at the LUST site and are currently expanding their treatment system to increase the effectiveness of the contaminant removal.


Well Nos. 7 and 8 have been contaminated with Trichloroethylene (TCE) from an unidentified source. A MDE inspector examined the Keilholtz Trucking, Moore Business Forms, Thurmont Shoe, NVR Wood Products, and a former dryer cleaning business (now a residence) for possible ground water discharge points in the WHPA as the source of the TCE contamination. A source was not identified; however, during the inspection it was noted by several local businesspeople that a former dry cleaning operator had used farmland near Well Nos. 7 and 8 to dispose of waste. The site has been referred to MDE's Brownfields Assessment Division for further investigation. Funding for the project is currently being investigated. The pertinent information in this report has been forwarded to Brownfields staff.

At the State Highway Administration complex a 2,000 gallon diesel tank was removed. This tank was observed to have a small pinhole. A monitoring well was installed, but no contaminants have been detected. Several other UST sites within the WHPA have had their tanks either removed or permanently sealed with no reported problems.

ID	Type	Site Name	Address	Potential Contaminant	
1	UST	Sheetz	428 N Church St.	VOC	
2	UST	Direct to You Gas	Corner Church and Emmitsburg Sts	VOC	
3	UST	Amoco	227 N Church St	VOC	
4	UST	Delauter Contractors	122 Park Ln	VOC	
5	UST	Keilholtz trucking Service	300 Eyler Rd	VOC	
6	UST	Thurmont Shoe Company	rec (47117 ord an urrangise has been	VOC	
7	UST	Texaco	res can structured to ear institute	VOC	
8	LUST	Mountaingate Exxon	s presentant sections but is his con-	VOC	
9	LUST	State Highway Administration	I facility in the facility of the contract of	VOC	
10	CHS	Bogley Chevrolet	111 Frederick Rd	VOC,SOC,HM	
11		Mountaingate Exxon	di da objecta o cultura e nie rengimal	VOC,SOC,HM	
12	CHS	State Highway Administration	acilities for vehicles and machinery	VOC,SOC,HM	
13	CHS	Beards Trash Service	14627 Roddy Rd	VOC,SOC,HM	
14	CHS	Gelwicks Trash Service	ntial contiminant depends on the sp	VOC,SOC,HM	
	CHS	Moore Business Forms	Carroll St Ext	VOC,SOC,HM	
	CHS	Thurmont Shoe Company	Forecast contaminants are grouped i	VOC,SOC,HM	
17	CHS	Nu Look Cleaners	Thurmont Shop Center	VOC	
18	CHS	Lawyers Thurmont Express	Lombard St	VOC	
19	CHS	Orchard Village Dry Cleaners	209 Tippin Drive	VOC	
20	MISC	Thurmont Cooperative	36 Walnut St	SOC	
21	MISC	Firemans Activity Bldg	THE SERVE CONTINUES IN THE SERVE OF THE SERV	VOC,M,HM	
22	MISC	Electric Substation	COURT WERE CONDUCTED ON THE CASE OF THE	VOC,SOC,HM	
23	MISC	Electric Substation		VOC,SOC,HM	
		NVR Wood Products	Carroll St Ext	SOC,VOC	
25	MISC	Mountaingate Service Center		VOC,SOC,HM	

Table 2. Potential Contaminant Point Sources within Thurmont WHPA. (See figure 2 for locations).

Based on the Maryland Office of Planning's 1997 Land Use map, the land use within WHPA Zones 1 and 2 is split evenly between residential, commercial and agricultural, and forest (Chart 1). WHPA Zone 3 is predominantly forested with small pockets of residential, commercial, and agricultural areas (Fig 3.). Table 3 outlines the distribution of land use within the WHPA Zone 3.



A review of the Maryland Office of Planning's Frederick County Sewer map shows that 72% of the land area in WHPA Zones 1 and 2 is in the sewer service area (Fig. 4). The remaining 28% of land area that is not currently sewered is predominantly agricultural (160 acres), with smaller areas of residential (57 acres), commercial (33 acres), and forested land (48 acres).

Within WHPA Zone 3, 94% of the land is not sewered. The large majority of the unsewered area is forested (87%) and agricultural (9%), with only 3% being low-density residential.

Land Use	Total Area (Acres)	Percentage of Total WHPA	
Low Density Residential	166	2	
Medium Density Residential	156	2	
Commercial	54	1	
Open Urban Land	14	0	
Cropland	496	7	
Pasture	79	1	
Orchards/Vineyards/ Horticulture	95	1	
Forest	6041	85	
Water	42	1	

Table 3. Land Use Summary for Thurmont WHPA Zone 3.

WATER QUALITY DATA

Water Quality data was reviewed from the Water Supply Program's database for Safe Drinking Water Act contaminants. All data reported is from the finished (treated) water unless otherwise noted. The treatment currently in use in Thurmont includes disinfection, ion exchange for softening, filtration for microorganism removal (well Nos. 3 and 4 only), and aeration for organics removal (well No. 7 and 8 only).

A review of the monitoring data since 1993 for Thurmont's finished water indicates that the system's water supply meets drinking water standards with a few exceptions. Of the inorganic compounds tested, Nitrate was the only contaminant detected (Table 4). Radon-222 was the only radiological contaminant present at a level of concern (Table 4). Volatile organic compounds have been detected in Well Nos. 2, 5, 7, and 8 (Table 5). Microbiological contaminants were present in Well Nos. 3 in samples collected in 1992 (Table 6). No synthetic organic compounds were detected above 50% of the Maximum Contaminant Level (MCL) in three sets of samples since May 1994.

Inorganic Compounds (IOCS)

The MCL for Nitrate is 10 ppm. Nitrate was detected at 5.9 ppm in Well 2 in September of 1993, but has not been detected above 50% of the MCL since (Table 4a). Nitrate has been detected at levels below the 50% MCL threshold in Well Nos. 3, 4, and 7 as well.

Radionuclides

There is currently no MCL for Radon-222, however EPA has proposed a MCL of 300 pCi/L or an alternate of 4000 pCi/L. MDE is currently evaluating which MCL to adopt into State regulations. Radon-222 has been detected at levels commonly associated with the bedrock aquifers of the Piedmont in all of Thurmont's production wells (Table 4).

Volatile Organic Compounds

VOCs have been detected in Well No. 2 since 1993 (Table 5a). Trichlorobenzene and p-Dichlorobenzene were both detected above 50% of their respective MCLs in November 1993, but neither has been detected since. Trichloroethylene (TCE) was detected only once in January of 1995 well below the MCL. As previously mentioned TCE has been detected in the raw water of well 7, and treatment for this contaminant is in place. Raw water samples were collected in June 1999 (Table 5b) and are indicative of the TCE levels found in wells 7 and 8.

Microbiological Contaminants

Well 3 is classified as a "Ground Water Under the Direct Influence of Surface Water" (GWUDI) source as defined in COMAR and the Surface Water Treatment Rule. During the evaluation of this well for surface water influence, raw water bacteriological samples were collected that showed the presence of fecal coliform contamination (Table 6). Turbidity was not higher than 3 NTUs. All of Thurmont's remaining wells were tested and were negative for fecal coliform.

CONT ID	CONTAMINANT NAME	MCL	SAMPLE DATE	RESULT
1040	NITRATE	10 (ppm)	14-Sep-93	5.9 (ppm)
1040	NITRATE	10	12-Nov-93	3.9
1040	NITRATE	10	08-Mar-94	3.4
1040	NITRATE	10	12-Apr-94	4.2
1040	NITRATE	10	04-Jan-95	3.6
1040	NITRATE	10	07-Aug-96	2.4
1040	NITRATE	10	26-Mar-97	2.7
1040	NITRATE	10	21-Sep-98	3.5
1040	NITRATE	10	24-Nov-98	4.1
4004	RADON-222	300 (pCi/L)**	09-Apr-97	130 (pCi/L)

Table 4a. IOC and Radiological results for Thurmont Plant 2 (Well 2) finished water since Sep. 1993.

CONT ID	CONTAMINANT NAME	MCL	SAMPLE DATE	RESULT
1040	NITRATE	10 (ppm)	14-Sep-93	4.4 (ppm)
1040	NITRATE	10	12-Nov-93	3.3
1040	NITRATE	10	07-Mar-94	3.2
1040	NITRATE	10	08-Mar-94	. 2
1040	NITRATE	10	12-Apr-94	3.6
1040	NITRATE	10	28-Feb-95	2.6
1040	NITRATE	10	07-Aug-96	1.8
1040	NITRATE	10	26-Mar-97	2.1
1040	NITRATE	10	21-Sep-98	2.5
4004	RADON-222	300 (pCi/L)**	16-May-94	805 (pCi/L)
4004	RADON-222	300	09-Apr-97	640

Table 4b. IOC and Radiological results for Thurmont Plant 3 (Wells 3 and 4) finished water since Sep. 1993.

CONT ID	CONTAMINANT NAME	MCL	SAMPLE DATE	RESULT*
1040	NITRATE	10 (ppm)	14-Sep-93	4.6 (ppm)
1040	NITRATE	10	12-Nov-93	3.6
1040	NITRATE	10	08-Mar-94	3.5
1040	NITRATE	10	13-Apr-94	4.3
1040	NITRATE	10	04-Jan-95	3.3
1040	NITRATE	10	24-Oct-95	3.5
1040	NITRATE	10	07-Aug-96	2.1
1040	NITRATE	10	26-Mar-97	2.7
1040	NITRATE	10	24-Nov-98	3
4004	RADON-222	300 (pCi/L)**	16-May-94	-10 (pCi/L)
4004	RADON-222	300	09-Dec-96	325
4004	RADON-222	300	09-Apr-97	-20

^{*}Negative values for results indicate the contaminant is not present above the detection limit (negative value) for the analysis method.

**Lowest of proposed Radon-222 MCLs.

Table 4c. IOC and Radiological results for Thurmont Plant 5 (Well 7) finished water since Sep. 1993.

CONT ID	CONTAMINANT NAME	MCL (PPB)	SAMPLE DATE	RESULT (PPB)*
2969	p-DICHLOROBENZENE	75	12-Nov-93	44
2969	p-DICHLOROBENZENE	75	08-Mar-94	-0.5
2969	p-DICHLOROBENZENE	75	04-Jan-95	-0.5
2969	p-DICHLOROBENZENE	75	03-Apr-95	-0.5
2969	p-DICHLOROBENZENE	75	05-Jul-95	-0.5
2969	p-DICHLOROBENZENE	75	02-Oct-95	-0.5
2969	p-DICHLOROBENZENE	75	09-Apr-97	-0.5
2969	p-DICHLOROBENZENE	75	21-Sep-98	-0.5
2378	1,2,4-TRICHLOROBENZENE	70	12-Nov-93	50
2378	1,2,4-TRICHLOROBENZENE	70	08-Mar-94	-0.5
2378	1,2,4-TRICHLOROBENZENE	70	04-Jan-95	-0.5
2378	1,2,4-TRICHLOROBENZENE	70	03-Apr-95	-0.5
2378	1,2,4-TRICHLOROBENZENE	70	05-Jul-95	-0.5
2378	1,2,4-TRICHLOROBENZENE	. 70	02-Oct-95	-0.5
2378	1,2,4-TRICHLOROBENZENE	70	09-Apr-97	-0.5
2378	1,2,4-TRICHLOROBENZENE	70	21-Sep-98	-0.5
2984	TRICHLOROETHYLENE	5	12-Nov-93	-0.5
2984	TRICHLOROETHYLENE	5	08-Mar-94	-0.5
2984	TRICHLOROETHYLENE	5	04-Jan-95	1
2984	TRICHLOROETHYLENE	5	03-Apr-95	-0.5
2984	TRICHLOROETHYLENE	5	05-Jul-95	-0.5
2984	TRICHLOROETHYLENE	5	02-Oct-95	-0.5
2984	TRICHLOROETHYLENE	5	09-Apr-97	-0.5
2984	TRICHLOROETHYLENE	5	21-Sep-98	-0.5

Table 5a. VOC results for Thurmont Plant 2 (Well 2) since November 1993.

CONT ID	CONTAMINANT NAME	MCL (PPB)	SAMPLE DATE	RESULT (PPB)*
2984	TRICHLOROETHYLENE	5	09-Mar-90	-0.5
2984	TRICHLOROETHYLENE	5	07-Jun-90	-0.5
2984	TRICHLOROETHYLENE	5	05-Sep-90	-0.5
2984	TRICHLOROETHYLENE	5	16-Oct-90	-0.5
2984	TRICHLOROETHYLENE	5	26-Feb-91	-0.5
2984	TRICHLOROETHYLENE	5	29-Jun-94	-0.5
2984	TRICHLOROETHYLENE	5	04-Jan-95	-0.5
2984	TRICHLOROETHYLENE	5	26-Mar-96	-0.5
2984	TRICHLOROETHYLENE	5	09-Apr-97	-0.5
2984	TRICHLOROETHYLENE	5	14-Jun-99	22.4 (R)
2984	TRICHLOROETHYLENE	01, 05	29-Jun-99	30.9 (R)
2984	TRICHLOROETHYLENE	g to let tri5 mater	29-Jun-99	-0.5

⁽R) Denotes raw water data.

Table 5b. VOC results for Thurmont Plant 5 (Well 7) since November 1993.

^{*}Negative values for results indicate the contaminant is not present above the detection limit (negative value) for the analysis method.

CONDITIONS	SAMPLE DATE	TEMPERATURE (°C)	РН	TURBIDITY (NTU)	TOTAL COLIFORM (COLONIES/10 0ML	FECAL COLIFORM (COLONIES/100 ML)
WET WEATHER	24-Feb-92	13.1	7.7	3	1.1	-1.1
WET WEATHER		7.7	7	1.8	3.6	-1.1
WET WEATHER	26-Feb-92	13.5	7.2	1.8	-2	-2
WET WEATHER	27-Feb-92	13.7	7.4	1.8	8	-2
WET WEATHER	02-Nov-92	12.9	7	0.7	-2	-2
WET WEATHER	03-Nov-92	13.3	7.1	0.52	1600	17
WET WEATHER	04-Nov-92	12.9	7.1	0.26	1600	17
WET WEATHER	05-Nov-92	13.4	7.1	0.9	300	4
DRY	18-Nov-91		7.5	0.25	-2	-2
DRY	13-Oct-92	10	7	0.15	4	-2

Table 6. Ground Water Under the Direct Influence of Surface Water Monitoring Data for Thurmont Well No. 3.


SUSCEPTIBILITY ANALYSIS

Thurmont's wells draw water from unconfined fractured rock aquifers, and are therefore vulnerable to any activity on the land surface that occurs within the WHPA. In order to determine susceptibility to each group of contaminants the following criteria were considered: 1) the presence of potential contaminant sources within the WHPA, 2) water quality data and 3) the aquifer conditions.

Inorganic Compounds

Nitrate is present in all of Thurmont's wells below the MCL. Sources of nitrate can generally be traced back to land use. Fertilization of agricultural fields and residential lawns, and septic systems are two non-point sources that are generally associated with nitrate loading in ground water. Nitrate is also found in precipitation throughout Maryland, which is the primary recharge of unconfined aquifers, due to reactions with atmospheric nitrogen (Bolton, 1996). Agricultural land makes up 31% (Table 3a) and non-sewered residential and commercial areas make up approximately 7% of WHPA Zones 1 and 2 based on 1997 land use. Trends in nitrate concentration in Thurmont's wells show that they peaked in 1993, were on a decline until 1996 and have been slowly on the rise since (Chart 2).

The fluctuations in nitrate concentration may be attributable to many factors including residential development, changes in agricultural practices, and seasonal variations in nitrate concentration in ground water recharge. Samples are collected annually, however they have not been consistently collected during the same time of year (Table 4). Currently, it appears that nitrate concentration is on the rise in Thurmont's water supply. Due to this and the numerous potential sources of nitrate the water supply is considered susceptible to this contaminant.



Radionuclides

Radon is present in Thurmont's water supply, however determining the susceptibility of the wells to this contaminant is difficult due to many factors. An MCL for radon has not been adopted yet for Maryland. The US EPA has proposed two MCLs, 300 pCi/L and 4000pCi/L, for drinking water. The higher concentration is allowable if the state adopts a cooperative program to reduce concentrations of radon in indoor air. which is the primary health concern. The source of radon in ground water can be traced back to the natural occurrence of uranium in rocks. Radon is prevalent in ground water throughout the Piedmont region of Maryland due to radioactive decay of uranium bearing minerals in the bedrock (Bolton, 1996). However, large amounts of radon may be ingested with water without any health effects. The health effects and risks of radon in drinking water are reviewed in Cross, Harley, and Hoffman (1985). The EPA also has information on proposed regulations for radon in indoor air and drinking water on their web site (http://www.epa.gov/OGWDW/radon.html). Currently, it appears that Thurmont's water supply is susceptible to radon due to the natural occurrence of this contaminant in aquifer material. However, the consequences of this are unknown at this time.

Volatile Organic Compounds

The wells are susceptible to VOCs due to several potential contaminant sources identified within the WHPA that could potentially impact these wells. Validating their susceptibility is the presence of TCE, and benzene byproducts in Well Nos. 2, 5, 7, and 8. The source of contamination in Well No. 5 has been identified and remediation efforts are ongoing. No specific source of VOCs has been linked to the contamination of Well Nos. 7 and 8.

Microbiological Contaminants

The presence of fecal coliform in Well No. 3 indicates its susceptibility to pathogenic microorganisms. Pathogenic protozoa, viruses, and bacteria normally associated with surface water can contaminate this well due to its direct connection with Hunting Creek. Sources of these pathogens are generally improperly treated wastewater, waste material from mammals, and urban runoff in developed areas. Within WHPA Zones 1 and 2, there is no large discharge of wastewater. A small percentage of this area has individual septic systems, which may provide a source of fecal contamination if they fail. The watershed of Hunting Creek (Zone 3) is primarily forested (Fig. 3), which protects Hunting Creek from major fecal contamination. However, in town closer to Well No. 3 runoff from developed areas is a potential source of contaminants to the Creek. As a GWUDI source, Well No. 3 is susceptible to pathogens. However, there is little threat of major contamination based on the land use of the WHPA.

Synthetic Organic Compounds

Determining the susceptibility of Thurmont's wells to SOCs is not straightforward because these contaminants have not been detected in routine monitoring samples over a 5 year period. However, several potential sources of SOCs are present within the Thurmont WHPA (Table 2). This, together with the fact that the wells pull from unconfined fractured rock aquifers, causes the water supply to be susceptible to SOCs. Continued monitoring of these contaminants is important to ensure the safety of the water supply.

MANAGEMENT OF THE WHPA

With the information contained in this report, the Town of Thurmont is in a position to protect its water supply by staying aware of the area delineated for wellhead protection, keeping track of potential contaminant sources, and evaluating future development and land planning. Specific management recommendations for consideration are listed below:

Form a Local Planning Team

- Thurmont should form a local planning team to begin to implement the Town's wellhead protection plan. The team should represent all the interests in the community, such as the water supplier, home association officers, the County Health Department, local planning agencies, local business, developers, farmers and residents within and near the WHPA. The team should work to reach a consensus on how to protect the water supply.
- A management strategy adopted by Thurmont should be consistent with the level of resources available for implementation. By consulting with other jurisdictions involved in this process, Thurmont can benefit from lessons learned by others. There are at least two other nearby municipalities actively involved in wellhead protection (Walkersville and Middletown). MDE remains available to assist in anyway we can help the process.

Public Awareness and Outreach

- Conducting education outreach to the facilities listed in Table 2. Important topics include: (a) in ground storage of materials in tanks and piping, (b) waste streams that may go into dry wells, septic tanks or other ground water discharge points, (c) reporting of spills, (d) material and chemical storage, and (e) monitoring well installation.
- The Consumer Confidence Report should list that this report is available to the general public through their county library, contacting the town office or by contacting MDE.
- Road signs at the WHPA boundaries is an effective way of keeping the relationship of land use and water quality in the public eye, and help in the event of spill notification and response.

Monitoring

- Thurmont should monitor Well No. 5 for organic compounds that had previously contaminated the well if it intends to use it to accommodate future growth.
- Continue to monitor for all Safe Drinking Water Act contaminants as required by MDE.

Planning/New Development

- Review the State's model wellhead protection zoning ordinances for potential
 adoption. Compare the wellhead protection boundaries with the Town limits to
 determine how to coordinate with Frederick County Department of Planning.
 Frederick County Planning has a draft ordinance for wellhead protection; MDE
 recommends that communities within the County encourage this Department to adopt
 the ordinance.
- Evaluate the areas most likely to be prone to forming sinkholes. Manage stormwater runoff and review new development including storage of chemicals to keep away from sinkholes. Carroll County is developing educational guidance on sinkhole formation and mitigation measures, which may be useful to Thurmont.

Land Acquisition/Easements

• The availability of loans for purchase of and or easements for the purpose of protecting water supplies is available from MDE. Loans are offered at zero percent interest and zero points.

Contingency Plan

- Thurmont should have a Contingency Plan for its water system. COMAR 26.04.01.22 requires all community water systems to prepare and submit for approval a plan for providing a safe and adequate drinking water supply under emergency conditions.
- Develop a spill response plan in concert with the Fire Department and other emergency response personnel.

Contaminant Source Inventory Updates/Inspections

- Thurmont should conduct its own detailed field survey of the WHPA to ensure that there are no other potential sources of contamination.
- Consider regular inspections of certain high risk facilities.
- Mr. Gary Dingle, the operator of Thurmont's water system, stated that his biggest concern is that the source of TCE present in Well Nos. 7 and 8 has never been identified. Treatment to remove TCE is in place and has been effective, as shown by the finished water quality data. However, this is a valid concern particularly because without removal or control of the source contaminant levels may rise beyond the capability of the treatment system. We are aware that Thurmont has been in contact Mr. William Burris of the State's Waste Management Administration to assist and cooperate in their proposed Brownfields project. We encourage the Town to support this investigation to determine the best way to protect Well Nos. 7 and 8 from further contamination.

Changes in Use

Thurmont should notify MDE if well No. 5 is put back into service. Drilling a new well outside the current WHPA would modify the area, therefore Thurmont should contact the Water Supply Program if a new well is being proposed.

Because the fill behave the curve to the field serve.

REFERENCES

- Bolton, David W., 1996, Network Description and Initial Water-Quality Data from a Statewide Ground-Water-Quality Network in Maryland: Maryland Geological Survey Report of Investigations No. 60, 167 pp.
- Cross, F.T., N.H. Harley, and W. Hofmann, 1985, Health effects and risks from ²²²Rn in drinking water: Health Physics, vol. 48, no.5, p. 649-670.
- Earth Data Incorporated, 1995, MDE Wellhead Protection Fracture Trace Study:
 Delineation of Wellhead Protection Areas using Fracture Trace Analysis for Thurmont, Maryland, 13 pp.
- MDE, Public Drinking Water Program, 1996, A Wellhead Protection Plan for the Town of Thurmont, 10 p.
- MDE, Water Supply Program, 1999, Maryland's Source Water Assessment Plan, 36 p.
- Meyer G. and R.M. Beall, 1958, The Water Resources of Carroll and Frederick Counties: Department of Geology, Mines and Water Resources Bulletin 22, 355 pp.
- Nutter, L.J., 1973, Hydrogeology of the Carbonate Rocks, Frederick and Hagerstown Valleys, Maryland: Maryland Geological Survey Report of Investigations No. 19, 70 pp.
- Steinfort, Duvall et al., 1993, Findings of an Investigation of Surface Water Influence from Hunting Creek on Thurmont's Municipal Wells 3 and 4, as Determined Using Flourometric Methods and Streamflow Discharge, MDE Compliance Monitoring Division and Water Quality Monitoring Program Internal Report, 10 pp.
- U.S. Environmental Protection Agency, 1991, Delineation of Wellhead Protection Areas in Fractured Rocks: Office of Ground Water and Drinking Water, EPA/570/9-91-009, 144 pp.

OTHER SOURCES OF DATA

Water Appropriation and Use Permit Nos. FR69G021 and FR88G004 Public Water Supply Inspection Reports
MDE Water Supply Program Oracle® Database

MDE Waste Management Sites Database
Department of Natural Resources Digital Orthophoto Quarter Quadrangles for Blue
Ridge Summit SE and Catoctin Furnace NE
USGS Topographic 7.5 Minute Quadrangles Blue Ridge Summit and Catoctin Furnace
Maryland Office of Planning 1997 Frederick County Land Use Map
Maryland Office of Planning 1996 Frederick County Sewer Map

FIGURES

(found in pocket)




Figure 4. Sewer Service Area Map of Thurmont Wellhead Protection Area




Figure 2. Thurmont Wellhead Protection Area with Potential Contamination Sites

Legend

Town wells

Fracture Trace

Wellhead Protection Area

Zone 1

Zone 2

Zone 3


Potential Contamination Sites

- o¹ Underground Storage Tank (UST)
- 8 Leaking UST
- ▲ 10 Hazardous Waster Generators
- □²⁰ Miscellaneous

500 0 500 1000 Feet



Base Map: USGS Topographic 7.5 Minute Quadrangles - Blue Ridge Summit, Catoctin Furnace






Figure 3. Land Use Map of Thurmont Wellhead Protection Area

