



Facts About...

Washington Hill Property
(Voluntary Cleanup Program)

Site Location

The 5.573-acre Washington Hill Property is located at 1951 East Fayette Street in Baltimore City, Maryland. The property is zoned for residential use and is currently a vacant, grassy lot. The property is bounded to the north by East Fayette Street with a construction staging facility and Johns Hopkins Hospital facilities beyond, to the south by East Baltimore Street with churches and row homes beyond, to the east by North Washington Street with elementary schools and row homes beyond, and to the west by North Wolfe Street with a commercial facility and residential row homes beyond.

Site History

The site was initially developed prior to 1890. From development until the 1970s, the site has been used as residential row homes, two public school facilities, and several small commercial industries including a printer, two tin shops, a painter, an auto shop, and several clothes cleaners/laundries. In the early 1970s, the row homes were razed and a residential multi-family housing community, consisting of 12 two-story buildings, was constructed. In 2005, the housing community was razed and the site has remained a vacant lot.

Environmental Investigations and Actions

In October 2002, a Phase I environmental site assessment was conducted, which covered the subject property and an adjacent property not involved in this application and no recognized environmental conditions (RECs) were identified.

In July 2008, a Phase I environmental site assessment was conducted, which identified RECs associated with historic property use, including a printer, several potential dry cleaners, a painter, and an automotive repair shop.

In July 2008, a Phase II environmental site assessment was conducted, which included the collection of surface soil and subsurface soil samples for analysis of select priority pollutant metals, volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), pesticides, herbicides, and polychlorinated biphenyls (PCBs). Groundwater samples were collected for analysis of VOCs. Soil samples exceeded residential clean up standards for arsenic, chromium, lead, mercury, and benzo(a)pyrene. Groundwater samples exceeded residential clean up standards for benzene and methyl tert butyl ether.

In October 2008, three soil gas samples were collected and analyzed for the presence of elemental mercury. All samples were non-detect for elemental mercury. In November 2008, one soil gas sample was collected and analyzed for VOCs. This sample was diluted and the results were determined to be unusable.

In December 2008, the Department requested one additional soil sample to be analyzed for priority pollutant metals and SVOCs and three additional soil gas samples for VOCs.



Current Status

On August 26, 2008, Gateway at Washington Hill, LLC, the prospective purchaser, submitted an application to the Voluntary Cleanup Program as an inculpable person seeking a No Further Requirements Determination for future residential use of the property. The applicant withdrew from the program on May 1, 2009 prior to the submission of the additional sampling results.

Contact

For additional information, please contact the Land Restoration Program at 410-537-3493.

Last Update: June 2009