

# Brownfield Master Inventory (BMI) Report - Active Sites, By County

10/6/2016

## Talbot

**BMI #:** MD0415 Doc National Marine Fisheries Serv. ( )

South Morris Street Ext

Oxford

Assoc. Entity:

VCP Status:

### Site Status

Assessment Ongoing: No    Remediation Ongoing: No    Determination:

FIS:                      Factsheet: No Fact Sheet Available.

### Regulatory Interest

Brownfield:	State Master*:	Voluntary Cleanup Program (VCP):
Site Assessment:	Non Master*:	National Priority List (NPL):
Formerly Used Defense Site (FUDS):	Federal Facility: Yes	Groundwater Investigation Site (GWI):

**BMI #:** MD0597 Louis Charlie/Merrimac Cleaners ( )

106 - 108 North Washington Street

Easton

Assoc. Entity:

VCP Status:

### Site Status

Assessment Ongoing: Yes    Remediation Ongoing: No    Determination:

FIS:                      Factsheet: <http://www.mde.state.md.us/programs/Land/MarylandBrownfieldVCP/mapping/Documents/Louis%20Charlie-Merrimac%20Cleaners.pdf>

### Regulatory Interest

Brownfield:	State Master*:	Voluntary Cleanup Program (VCP):
Site Assessment: Yes	Non Master*:	National Priority List (NPL):
Formerly Used Defense Site (FUDS):	Federal Facility:	Groundwater Investigation Site (GWI):

**BMI #:** MD1192 Cordova Elementary School ( )

Church Street (Route 309) and Skipton Cordova Road    Cordova

Assoc. Entity:

VCP Status:

### Site Status

Assessment Ongoing: No    Remediation Ongoing: No    Determination:

FIS:                      Factsheet: No Fact Sheet Available.

### Regulatory Interest

Brownfield: Yes	State Master*:	Voluntary Cleanup Program (VCP):
Site Assessment:	Non Master*:	National Priority List (NPL):
Formerly Used Defense Site (FUDS):	Federal Facility:	Groundwater Investigation Site (GWI):

\* State Master and Non Master Lists replaced by Brownfield Master Inventory

# Brownfield Master Inventory (BMI) Report - Active Sites, By County

10/6/2016

## Talbot

**BMI #:** MD1193 Tidewater Tractor ( )  
Route 50, south of Route 404

Wye Mills

Assoc. Entity:

VCP Status:

### Site Status

Assessment Ongoing: No    Remediation Ongoing: No    Determination:  
FIS:                      Factsheet: No Fact Sheet Available.

### Regulatory Interest

Brownfield: Yes	State Master*:	Voluntary Cleanup Program (VCP):
Site Assessment:	Non Master*:	National Priority List (NPL):
Formerly Used Defense Site (FUDS):	Federal Facility:	Groundwater Investigation Site (GWI):

**BMI #:** MD1249 Former SHA Eastern Regional Lab ( SHA Eastern Regional Lab)  
7857 Ocean Gateway, Route 50

Easton

Assoc. Entity:

VCP Status:

### Site Status

Assessment Ongoing: No    Remediation Ongoing: Yes    Determination:  
FIS:                      Factsheet: <http://www.mde.state.md.us/programs/Land/MarylandBrownfieldVCP/mapping/Documents/FmrSHAERL.pdf>

### Regulatory Interest

Brownfield:	State Master*:	Voluntary Cleanup Program (VCP):
Site Assessment:	Non Master*:	National Priority List (NPL):
Formerly Used Defense Site (FUDS):	Federal Facility:	Groundwater Investigation Site (GWI): Yes

**BMI #:** MD1592 Former McCord Laundry and Cleaning, Inc. (Brick Row)  
114 South Washington Street

Easton

Assoc. Entity: Lincoln County Land and Cattle Co.

VCP Status:

### Site Status

Assessment Ongoing: Yes    Remediation Ongoing: No    Determination:  
FIS:                      Factsheet:

### Regulatory Interest

Brownfield:	State Master*:	Voluntary Cleanup Program (VCP): Yes
Site Assessment:	Non Master*:	National Priority List (NPL):
Formerly Used Defense Site (FUDS):	Federal Facility:	Groundwater Investigation Site (GWI):

\* State Master and Non Master Lists replaced by Brownfield Master Inventory

# Brownfield Master Inventory (BMI) Report - Active Sites, By County

10/6/2016

## Talbot

**BMI #:** MD1592 Former McCord Laundry and Cleaning, Inc. (Brick Row)

114 South Washington Street

Easton

Assoc. Entity: Eastern Shore Land Conservancy, Inc.

VCP Status:

### Site Status

Assessment Ongoing: Yes    Remediation Ongoing: No    Determination:

FIS:                      Factsheet:

### Regulatory Interest

Brownfield:	State Master*:	Voluntary Cleanup Program (VCP): Yes
Site Assessment:	Non Master*:	National Priority List (NPL):
Formerly Used Defense Site (FUDS):	Federal Facility:	Groundwater Investigation Site (GWI):

**BMI #:** MD1592 Former McCord Laundry and Cleaning, Inc. (Brick Row)

114 South Washington Street

Easton

Assoc. Entity: Eastern Shore Land Conservancy, Inc.

VCP Status:                      RP

### Site Status

Assessment Ongoing: Yes    Remediation Ongoing: No    Determination:

FIS:                      Factsheet:

### Regulatory Interest

Brownfield:	State Master*:	Voluntary Cleanup Program (VCP): Yes
Site Assessment:	Non Master*:	National Priority List (NPL):
Formerly Used Defense Site (FUDS):	Federal Facility:	Groundwater Investigation Site (GWI):

**BMI #:** MD1592 Former McCord Laundry and Cleaning, Inc. (Brick Row)

114 South Washington Street

Easton

Assoc. Entity: Eastern Shore Land Conservancy, Inc.

VCP Status:                      RP

### Site Status

Assessment Ongoing: Yes    Remediation Ongoing: No    Determination:

FIS:                      Factsheet:

### Regulatory Interest

Brownfield:	State Master*:	Voluntary Cleanup Program (VCP): Yes
Site Assessment:	Non Master*:	National Priority List (NPL):
Formerly Used Defense Site (FUDS):	Federal Facility:	Groundwater Investigation Site (GWI):

\* State Master and Non Master Lists replaced by Brownfield Master Inventory

# Brownfield Master Inventory (BMI) Report - Active Sites, By County

10/6/2016

## Talbot

**BMI #:** MD1717 Mansfield Septic (Wastewater Recycling, Inc. )  
9786 Klondike Road

Easton

Assoc. Entity:

VCP Status:

### Site Status

Assessment Ongoing: No    Remediation Ongoing: No    Determination:

FIS:                      Factsheet: <http://www.mde.state.md.us/programs/Land/MarylandBrownfieldVCP/mapping/Documents/Mansfield.pdf>

### Regulatory Interest

Brownfield:	State Master*:	Voluntary Cleanup Program (VCP):
Site Assessment: Yes	Non Master*:	National Priority List (NPL):
Formerly Used Defense Site (FUDS):	Federal Facility:	Groundwater Investigation Site (GWI):

**BMI #:** MD1752 Blizzard Property (Former SHA Cordova Storage Yard)  
Lewistown Road

Cordova

Assoc. Entity:

VCP Status:

### Site Status

Assessment Ongoing: No    Remediation Ongoing: No    Determination:

FIS:                      Factsheet:

### Regulatory Interest

Brownfield:	State Master*:	Voluntary Cleanup Program (VCP):
Site Assessment:	Non Master*:	National Priority List (NPL):
Formerly Used Defense Site (FUDS):	Federal Facility:	Groundwater Investigation Site (GWI):

**BMI #:** MD1759 Glebe Park Drive (Airport Industrial Park, Glebe Park Industrial Park)  
Glebe Park Drive at Airpark Drive

Easton

Assoc. Entity:

VCP Status:

### Site Status

Assessment Ongoing: Yes    Remediation Ongoing: No    Determination:

FIS:                      Factsheet:

### Regulatory Interest

Brownfield:	State Master*:	Voluntary Cleanup Program (VCP):
Site Assessment:	Non Master*:	National Priority List (NPL):
Formerly Used Defense Site (FUDS):	Federal Facility:	Groundwater Investigation Site (GWI):

\* State Master and Non Master Lists replaced by Brownfield Master Inventory