

## Part 70 Compliance Certification Report due April 1<sup>st</sup>

Your facility is currently operating under your Part 70 Operating Permit issued by the Air and Radiation Management Administration (ARMA). This permit requires an annual Compliance Certification due by April 1 each year. To complete the compliance certification, both an ARMA form and a federal Compliance Certification form are to be used. The ARMA form is to be used for certifying plant-wide conditions (Section III of your Part 70 Permit) and the federal form is to be used for certifying plant-specific conditions (Section IV of your Part 70 Permit).

Regarding the federal form, please note that sections A and B of the certification form are only required to be completed once; however, sections C and D must be completed for each permit condition of each emission unit. Deviations from permit conditions must be reported on form E. Please make as many copies of form C, D, and E as necessary.

The federal form and instructions are located at:

<https://www.epa.gov/title-v-operating-permits/epa-issued-operating-permits>

The ARMA form for Section III is located at:

[http://www.mde.state.md.us/assets/document/air/Section\\_III\\_Com\\_Cert.pdf](http://www.mde.state.md.us/assets/document/air/Section_III_Com_Cert.pdf)

Please ensure that your certification is received by ARMA on or before April 1<sup>st</sup>. Completed forms should be mailed to:

Maryland Department of the Environment  
Air and Radiation Management Administration  
1800 Washington Boulevard, Suite 715  
Baltimore MD 21230-1720  
Attn: Laramie Daniel, Compliance Program

A copy of your annual compliance certification must also be sent electronically to the Environmental Protection Agency at the following e-mail address:

**R3\_APD\_Permits@epa.gov**

Failure to meet this deadline is a violation of your Part 70 Permit. If you have any questions, please call your ARMA contact at 410-537-3231.

Sincerely,



Pars Ramnarain, Chief  
Process Compliance Division  
Air and Radiation Management Administration