

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L01 | 3500 Hampshire Glen Ct | 3/2/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 3/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 3/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 3/30/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 4/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 5/2/2006 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 5/8/2006 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 5/15/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 5/22/2006 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 5/31/2006 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 6/5/2006 | | 0.38 J | ND(0.50) | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 6/15/2006 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 6/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 6/26/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 7/10/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 7/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 7/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 7/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 8/7/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 8/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 8/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 9/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 9/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 9/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 9/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 10/2/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 10/10/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L01 | 3500 Hampshire Glen Ct | 10/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 10/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 10/30/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 11/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 11/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 11/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 11/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 12/4/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 12/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 12/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 1/8/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 2/21/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 3/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 4/2/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 4/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 4/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 5/15/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 6/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 7/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 7/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 8/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 8/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 9/4/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 9/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 11/12/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 11/26/2007 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L01 | 3500 Hampshire Glen Ct | 12/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 1/7/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L01 | 3500 Hampshire Glen Ct | 2/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 3/3/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L01 | 3500 Hampshire Glen Ct | 4/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 5/5/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 6/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 7/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 8/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 9/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 10/6/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 11/3/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 12/1/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 1/5/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 2/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 3/4/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 4/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 5/5/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 6/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 7/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 8/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 8/31/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 10/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L01 | 3500 Hampshire Glen Ct | 12/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 3/10/2006 | | ND(0.50) | ND(0.50) | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 3/24/2006 | | 0.59 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 3/27/2006 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L25 | 3501 Hampshire Glen Ct | 4/3/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 4/10/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 4/24/2006 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 5/1/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 5/8/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 5/15/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 5/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 6/6/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 6/15/2006 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 6/23/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 6/29/2006 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 7/14/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 7/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 7/27/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 8/2/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 8/10/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 8/22/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 9/1/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 11/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 12/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 1/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 7.9 |
| M35P356L25 | 3501 Hampshire Glen Ct | 2/22/2007 | | ND(1.0) | ND(1.0) | ND(1.0) | ND(1.0) | ND(1.0) | NA | ND(5.0) | ND(5.0) | ND(5.0) | ND(25) |
| M35P356L25 | 3501 Hampshire Glen Ct | 3/15/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 4/12/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 5/15/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 6/8/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L25 | 3501 Hampshire Glen Ct | 7/24/2007 | | 0.089 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 8/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 9/17/2007 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 10/17/2007 | | 0.14 J | 0.086 J | 0.68 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 11/1/2007 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 12/11/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 1/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 2/26/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L25 | 3501 Hampshire Glen Ct | 10/9/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 3/3/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 3/16/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 3/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 3/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 4/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 4/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 4/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 4/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 5/1/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 5/8/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 5/15/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 5/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 5/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 6/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 6/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 6/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 6/26/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 7/5/2006 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L02 | 3502 Hampshire Glen Ct | 7/10/2006 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 7/17/2006 | | 0.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 7/24/2006 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 7/31/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 8/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 8/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 8/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 9/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 9/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 9/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 9/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 10/2/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 10/9/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 10/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 10/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 10/30/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 11/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 11/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 11/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 11/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 12/4/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 12/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 12/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 1/8/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 2/5/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 2/21/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L02 | 3502 Hampshire Glen Ct | 3/5/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 3/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 4/2/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 4/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 4/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 5/14/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 5/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 6/11/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 6/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 7/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 7/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 8/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 8/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 9/5/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 9/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 10/1/2007 | | 0.069 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 10/15/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 10/29/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 11/12/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 11/26/2007 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L02 | 3502 Hampshire Glen Ct | 12/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 1/7/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L02 | 3502 Hampshire Glen Ct | 2/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 3/3/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L02 | 3502 Hampshire Glen Ct | 4/7/2008 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 5/5/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 6/2/2008 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L02 | 3502 Hampshire Glen Ct | 7/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 8/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 9/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 10/6/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 11/3/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 12/1/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 1/5/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 2/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 3/4/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 4/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 5/4/2009 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 6/1/2009 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 7/6/2009 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 8/3/2009 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 8/31/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 10/5/2009 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 11/2/2009 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L02 | 3502 Hampshire Glen Ct | 12/7/2009 | | 0.082 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 3/2/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 3/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 3/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 3/30/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 4/3/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 4/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 4/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 4/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L24 | 3503 Hampshire Glen Ct | 4/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/1/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/1/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/1/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/8/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/8/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/8/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/15/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/15/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/15/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/22/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/22/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/22/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/31/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/31/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/31/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/5/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/5/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/5/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/12/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/12/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/19/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/19/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/19/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/26/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/26/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L24 | 3503 Hampshire Glen Ct | 6/26/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/10/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/10/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/10/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/17/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/17/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/17/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/24/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/24/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/24/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/31/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/31/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/31/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 8/7/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 8/7/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 8/7/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 8/28/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 8/28/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 8/28/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 9/11/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 9/11/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 9/11/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 10/30/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 10/30/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 10/30/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 11/6/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 11/6/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L24 | 3503 Hampshire Glen Ct | 11/6/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 11/13/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 11/13/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 11/13/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 11/20/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 11/20/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 11/20/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 12/4/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 12/4/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 12/4/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 12/11/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 12/11/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 12/11/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 12/18/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 12/18/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 12/18/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 1/22/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 1/22/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 1/22/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 3/5/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 3/5/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 3/5/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 3/19/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 3/19/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 3/19/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 4/30/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 4/30/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L24 | 3503 Hampshire Glen Ct | 4/30/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/11/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/11/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/11/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/25/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/25/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/25/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/9/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/9/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/9/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/23/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/23/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/23/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 8/6/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 8/6/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 8/6/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 8/20/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 8/20/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 8/20/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 9/5/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 9/5/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 9/5/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 9/17/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 9/17/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 9/17/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 10/1/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 10/1/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L24 | 3503 Hampshire Glen Ct | 10/1/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 10/15/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 10/15/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 10/15/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 10/29/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 10/29/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 10/29/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 11/12/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 11/12/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 11/12/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 11/26/2007 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L24 | 3503 Hampshire Glen Ct | 11/26/2007 | PI | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L24 | 3503 Hampshire Glen Ct | 11/26/2007 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L24 | 3503 Hampshire Glen Ct | 12/10/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 12/10/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 12/10/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 1/7/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L24 | 3503 Hampshire Glen Ct | 1/7/2008 | PI | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L24 | 3503 Hampshire Glen Ct | 1/7/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L24 | 3503 Hampshire Glen Ct | 2/5/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L24 | 3503 Hampshire Glen Ct | 2/5/2008 | PI | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L24 | 3503 Hampshire Glen Ct | 2/5/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L24 | 3503 Hampshire Glen Ct | 3/3/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L24 | 3503 Hampshire Glen Ct | 3/3/2008 | PI | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L24 | 3503 Hampshire Glen Ct | 3/3/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L24 | 3503 Hampshire Glen Ct | 4/7/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 4/7/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L24 | 3503 Hampshire Glen Ct | 4/7/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/5/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/5/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/5/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/2/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/2/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/2/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/22/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/22/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/22/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 9/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 9/8/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 9/8/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 12/1/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 12/1/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 12/1/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 1/5/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 1/5/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 1/5/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 2/2/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 2/2/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 2/2/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 3/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 3/4/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 3/4/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 4/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 4/6/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L24 | 3503 Hampshire Glen Ct | 4/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/4/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 5/4/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/1/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/1/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 6/1/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/6/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 7/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 8/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 8/3/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 8/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 8/31/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 8/31/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 8/31/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 10/5/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 10/5/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 10/5/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 11/2/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 11/2/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 11/2/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 12/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 12/7/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L24 | 3503 Hampshire Glen Ct | 12/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 3/3/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 3/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L03 | 3504 Hampshire Glen Ct | 3/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 3/30/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 4/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 4/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 4/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 4/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 5/1/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 5/8/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 5/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 5/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 5/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 6/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 6/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 6/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 6/26/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 7/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 7/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 7/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 7/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 8/7/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 8/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 8/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 9/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 9/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 9/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 9/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 10/2/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L03 | 3504 Hampshire Glen Ct | 10/9/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 10/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 10/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 10/30/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 11/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 11/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 11/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 11/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 12/7/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 12/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 12/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 1/8/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 2/21/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 3/5/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 3/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 4/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 5/14/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 5/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 6/11/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 6/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 7/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 7/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 8/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 9/5/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 9/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 10/15/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L03 | 3504 Hampshire Glen Ct | 10/29/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 11/12/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 11/26/2007 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L03 | 3504 Hampshire Glen Ct | 12/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 1/7/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L03 | 3504 Hampshire Glen Ct | 2/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 3/3/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L03 | 3504 Hampshire Glen Ct | 4/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 5/5/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 6/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 7/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 8/6/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 9/9/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 10/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 11/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 12/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 1/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 2/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 3/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 4/20/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 5/5/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 6/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 7/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 8/4/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 9/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 10/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L03 | 3504 Hampshire Glen Ct | 12/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L23 | 3505 Hampshire Glen Ct | 3/3/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 3/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 4/3/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 4/10/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 4/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 5/1/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 5/8/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 5/15/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 5/22/2006 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 5/31/2006 | | 0.45 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 6/5/2006 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 6/12/2006 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 6/19/2006 | | 0.58 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.080 J | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 7/5/2006 | | 0.75 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.15 J | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 7/10/2006 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 7/31/2006 | | 0.97 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 8/7/2006 | | 0.55 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 8/14/2006 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 8/21/2006 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 8/28/2006 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 9/6/2006 | | 0.82 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 9/11/2006 | | 0.56 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 9/25/2006 | | 0.98 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.11 J | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 10/2/2006 | | 0.94 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 10/9/2006 | | 1.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.18 J | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L23 | 3505 Hampshire Glen Ct | 10/16/2006 | | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.16 J | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 10/23/2006 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 10/30/2006 | | 0.83 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.089 J | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 11/6/2006 | | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.13 J | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 11/13/2006 | | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.16 J | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 11/20/2006 | | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.11 J | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 11/27/2006 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.11 J | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 12/4/2006 | | 0.85 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 12/18/2006 | | 0.78 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 1/22/2007 | | 0.87 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 2/5/2007 | | 0.95 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 2/21/2007 | | 0.64 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 3/5/2007 | | 0.85 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 3/19/2007 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.076 J | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 4/2/2007 | | 0.91 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 4/16/2007 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 4/30/2007 | | 0.84 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 5/14/2007 | | 0.53 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 5/30/2007 | | 0.37 J | ND(0.50) | 0.072 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 6/11/2007 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 6/25/2007 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 7/9/2007 | | 0.5 | ND(0.50) | 0.070 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 8/20/2007 | | 3.2 | ND(0.50) | 0.059 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 10/29/2007 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 11/12/2007 | | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 11/26/2007 | | 1.4 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L23 | 3505 Hampshire Glen Ct | 12/10/2007 | | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L23 | 3505 Hampshire Glen Ct | 1/7/2008 | | 1.8 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L23 | 3505 Hampshire Glen Ct | 2/6/2008 | | 1.4 | ND(0.5) | 0.055 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L23 | 3505 Hampshire Glen Ct | 3/3/2008 | | 1.4 | ND(0.5) | 0.083 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L23 | 3505 Hampshire Glen Ct | 4/7/2008 | | 0.87 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 5/5/2008 | | 0.63 | ND(0.50) | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 6/2/2008 | | 0.52 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 7/7/2008 | | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 9/8/2008 | | 0.79 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 10/6/2008 | | 0.91 | ND(0.50) | 0.084 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 11/3/2008 | | 0.66 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 12/1/2008 | | 0.46 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 1/5/2009 | | 0.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 2/2/2009 | | 0.69 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 3/4/2009 | | 0.63 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 4/9/2009 | | 0.67 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 5/4/2009 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 7/6/2009 | | 0.25 J | ND(0.50) | 0.072 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 8/4/2009 | | 0.36 J | ND(0.50) | 0.080 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 8/31/2009 | | 0.28 J | ND(0.50) | 0.089 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 10/7/2009 | | 0.33 J | ND(0.50) | 0.052 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L23 | 3505 Hampshire Glen Ct | 11/2/2009 | | 0.41 J | ND(0.50) | 0.055 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/3/2006 | | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.23 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/20/2006 | | 2.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.42 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/28/2006 | | 2.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.36 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/31/2006 | | 2.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.35 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/4/2006 | | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.32 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/7/2006 | | 2.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.36 J | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L04 | 3506 Hampshire Glen Ct | 4/11/2006 | | 3.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.46 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/13/2006 | | 3.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.44 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/18/2006 | | 3.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.46 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/21/2006 | | 4.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.55 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/25/2006 | | 5.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.51 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/2/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/2/2006 | PI | 7.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.52 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/2/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/9/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/9/2006 | PI | 10.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.63 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/9/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/16/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/16/2006 | PI | 8.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.56 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/16/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/23/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/23/2006 | PI | 12.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.68 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/23/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/30/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/30/2006 | PI | 19.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.92 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/30/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/6/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/6/2006 | PI | 14.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.73 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/6/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/16/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/16/2006 | PI | 14.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.86 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/16/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/20/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L04 | 3506 Hampshire Glen Ct | 6/20/2006 | PI | 17.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.88 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/20/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/27/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/27/2006 | PI | 11.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.2 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/27/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/6/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/6/2006 | PI | 7.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.3 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/6/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/11/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/11/2006 | PI | 5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.9 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/11/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/18/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/18/2006 | PI | 6.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.85 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/18/2006 | PM | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/25/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/25/2006 | PI | 7.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.81 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/25/2006 | PM | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/1/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/1/2006 | PI | 6.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.89 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/1/2006 | PM | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/15/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/15/2006 | PI | 4.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.89 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/15/2006 | PM | 0.95 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/22/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/22/2006 | PI | 4.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.96 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/22/2006 | PM | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/29/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L04 | 3506 Hampshire Glen Ct | 8/29/2006 | PI | 5.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.2 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/29/2006 | PM | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/5/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/5/2006 | PI | 6.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.1 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/5/2006 | PM | 2.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/12/2006 | PI | 5.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.1 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/12/2006 | PM | 2.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/19/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/19/2006 | PI | 5.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.2 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/19/2006 | PM | 3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/26/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/26/2006 | PI | 7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.7 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/26/2006 | PM | 3.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/2/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/2/2006 | PI | 6.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.4 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/2/2006 | PM | 3.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/10/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/10/2006 | PI | 6.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.3 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/10/2006 | PM | 4.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/17/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/17/2006 | PI | 5.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.1 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/17/2006 | PM | 4.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/24/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/24/2006 | PI | 5.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.1 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/24/2006 | PM | 5.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/30/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L04 | 3506 Hampshire Glen Ct | 10/30/2006 | PI | 5.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.1 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/30/2006 | PM | 5.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/6/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/6/2006 | PI | 5.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.94 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/6/2006 | PM | 5.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/13/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/13/2006 | PI | 4.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.94 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/13/2006 | PM | 5.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/20/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/20/2006 | PI | 4.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.95 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/20/2006 | PM | 4.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/20/2006 | PM2 | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/4/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/4/2006 | PI | 3.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.92 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/4/2006 | PM | 4.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/12/2006 | PI | 7.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.81 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/12/2006 | PM | 4.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/18/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/18/2006 | PI | 5.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.41 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/18/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 1/8/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 1/8/2007 | PI | 4.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.29 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 1/8/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 1/22/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 1/22/2007 | PI | 4.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.18 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 1/22/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L04 | 3506 Hampshire Glen Ct | 2/5/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 2/5/2007 | PI | 5.9 | ND(0.50) | 13.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.41 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 2/5/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 2/21/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 2/21/2007 | PI | 6.6 | ND(0.50) | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.33 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 2/21/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/5/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/5/2007 | PI | 4.7 | ND(0.50) | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.28 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/5/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/19/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/19/2007 | PI | 2.9 | ND(0.50) | 0.65 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.22 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/19/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/2/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/2/2007 | PI | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.25 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/2/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/16/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/16/2007 | PI | 3.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.20 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/16/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/30/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/30/2007 | PI | 3.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.19 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/30/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/14/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/14/2007 | PI | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.19 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/14/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/30/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/30/2007 | PI | 5.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.26 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/30/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L04 | 3506 Hampshire Glen Ct | 6/11/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/11/2007 | PI | 4.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.16 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/11/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/25/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/25/2007 | PI | 4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.20 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/25/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/10/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/10/2007 | PI | 7.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.24 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/10/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/23/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/23/2007 | PI | 9.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.35 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/23/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/6/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/6/2007 | PI | 5.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.26 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/6/2007 | PM | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/5/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/5/2007 | PI | 4.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.24 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/5/2007 | PM | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/17/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/17/2007 | PI | 17.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/17/2007 | PM | 0.81 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/1/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/1/2007 | PI | 7.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/1/2007 | PM | 0.67 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/15/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/15/2007 | PI | 32.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.2 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/15/2007 | PM | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L04 | 3506 Hampshire Glen Ct | 10/29/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/29/2007 | PI | 10.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.31 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/29/2007 | PM | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/12/2007 | PE | 14.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.38 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/12/2007 | PI | 18.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.31 J | 0.58 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/12/2007 | PM | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/26/2007 | PE | 10.3 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.27 J | ND(5) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/26/2007 | PI | 12.1 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.34 J | ND(5) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/26/2007 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/10/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/10/2007 | PI | 7.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.29 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/10/2007 | PM | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 1/7/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L04 | 3506 Hampshire Glen Ct | 1/7/2008 | PI | 10.6 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.36 J | ND(5) |
| M35P356L04 | 3506 Hampshire Glen Ct | 1/7/2008 | PM | 0.19 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L04 | 3506 Hampshire Glen Ct | 2/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 2/4/2008 | PI | 9.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.45 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 2/4/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/3/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/3/2008 | PI | 12.5 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.43 J | ND(5) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/3/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/7/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/7/2008 | PI | 5.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.32 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/7/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/5/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/5/2008 | PI | 6.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.29 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/5/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L04 | 3506 Hampshire Glen Ct | 6/2/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/2/2008 | PI | 29.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.53 | 0.99 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/2/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/7/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/7/2008 | PI | 25.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.56 | 1.1 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/7/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/22/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/22/2008 | PI | 35.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.74 | 1.8 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/22/2008 | PM2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/8/2008 | PI | 17.2 | 0.42 J | 0.69 | 0.61 | 3.4 | ND(0.50) | ND(0.50) | 0.45 J | 1.3 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/8/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/6/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/6/2008 | PI | 33.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.6 | 1.4 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/6/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/3/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/3/2008 | PI | 64.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.38 J | 1.2 | 3.7 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/3/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/1/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/1/2008 | PM | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/1/2008 | PM2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/15/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/15/2008 | PI | 50.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.65 | 1.5 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/15/2008 | PM2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 1/5/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 1/5/2009 | PI | 42.8 | 0.15 J | 0.22 J | 0.33 J | 3.2 | ND(0.50) | ND(0.50) | 0.68 | 2.9 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 1/5/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L04 | 3506 Hampshire Glen Ct | 1/19/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 1/19/2009 | PI | 25.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.5 | 1.5 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 1/19/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 21.1 |
| M35P356L04 | 3506 Hampshire Glen Ct | 2/2/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 2/2/2009 | PI | 35.9 | 0.15 J | 0.24 J | 0.41 J | 3.5 | ND(0.50) | ND(0.50) | 0.67 | 2.3 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 2/2/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 2/10/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 2/10/2009 | PI | 30.1 | 0.74 | 0.97 | 1.5 | 14.9 | 0.22 J | ND(0.50) | 0.59 | 2.4 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 2/10/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 2/16/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 2/16/2009 | PI | 86 | 0.35 J | 0.39 J | 0.5 | 6.5 | ND(0.50) | 0.39 J | 1.4 | 5 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 2/16/2009 | PM2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/4/2009 | PI | 60.4 | 0.59 | 0.67 | 0.92 | 10.9 | 0.20 J | 0.33 J | 1.1 | 4 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/4/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/23/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/23/2009 | PI | 37.2 | 1.4 | 1.8 | 3.1 | 38.4 | 0.82 | 0.29 J | 1.1 | 3 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 3/23/2009 | PM2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/6/2009 | PI | 25.4 | 0.73 | 0.72 | 1.3 | 18.6 | 0.28 J | ND(0.50) | 0.71 | 1.9 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/20/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/20/2009 | PI | 95.2 E | 0.34 J | 0.33 J | 0.44 J | 6.3 | ND(0.50) | 0.54 | 1.7 | 5.5 | 13.8 |
| M35P356L04 | 3506 Hampshire Glen Ct | 4/20/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/4/2009 | PI | 80.6 | 0.25 J | 0.23 J | 0.14 J | 4.9 | ND(0.50) | 0.55 | 1.7 | 5.1 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/4/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L04 | 3506 Hampshire Glen Ct | 5/18/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/18/2009 | PI | 42.2 | ND(0.50) | ND(0.50) | ND(0.50) | 0.45 J | ND(0.50) | 0.33 J | 0.93 | 2.3 | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 5/18/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/1/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/1/2009 | PI | 5.4 | ND(0.50) | 0.099 J | ND(0.50) | 2.1 | ND(0.50) | 0.11 J | 0.32 J | 0.39 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/1/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/15/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/15/2009 | PI | 3.9 | ND(0.50) | ND(0.50) | ND(0.50) | 0.41 J | ND(0.50) | ND(0.50) | 0.22 J | 0.23 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 6/15/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/7/2009 | PI | 3.5 | ND(0.50) | ND(0.50) | ND(0.50) | 0.38 J | ND(0.50) | ND(0.50) | 0.20 J | 0.27 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/21/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/21/2009 | PI | 4.5 | ND(0.50) | ND(0.50) | ND(0.50) | 0.65 | ND(0.50) | ND(0.50) | 0.20 J | 0.26 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 7/21/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/4/2009 | PI | 0.65 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/4/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/18/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/18/2009 | PI | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.18 J | 0.14 J | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 8/18/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/1/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/1/2009 | PI | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/1/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/15/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/15/2009 | PI | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 9/15/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L04 | 3506 Hampshire Glen Ct | 10/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/7/2009 | PI | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/19/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/19/2009 | PI | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 10/19/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/3/2009 | PI | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/23/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/23/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 11/23/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/7/2009 | PI | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/21/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/21/2009 | PI | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 12/21/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 1/4/2010 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 1/4/2010 | PI | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L04 | 3506 Hampshire Glen Ct | 1/4/2010 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/2/2006 | | 57.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.27 J | ND(0.50) | 5.3 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/9/2006 | | 31.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.16 J | ND(0.50) | 2.1 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/18/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/18/2006 | PI | 30.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.18 J | ND(0.50) | 2.7 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/18/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/25/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/25/2006 | PI | 27.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.3 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/25/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/3/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/3/2006 | PI | 28.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/3/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/8/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/8/2006 | PI | 26.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/8/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/14/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/14/2006 | PI | 32.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.6 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/14/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/21/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/21/2006 | PI | 35.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.13 J | ND(0.50) | 2.7 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/21/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/28/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/28/2006 | PI | 23.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.11 J | ND(0.50) | 1.9 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/28/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/2/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/2/2006 | PI | 26.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.6 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/2/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/9/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/9/2006 | PI | 18.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.4 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/9/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/16/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/16/2006 | PI | 6.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.41 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/16/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/23/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/23/2006 | PI | 31.5 | ND(0.50) | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.3 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/23/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/30/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/30/2006 | PI | 8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.95 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/30/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/6/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/6/2006 | PI | 23.7 | ND(0.50) | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.4 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/6/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/13/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/13/2006 | PI | 16 | ND(0.50) | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.8 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/13/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/20/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/20/2006 | PI | 4.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.55 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/20/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/27/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/27/2006 | PI | 16.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.6 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/27/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/6/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/6/2006 | PI | 20.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.4 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/6/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/10/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/10/2006 | PI | 11.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.3 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/10/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/17/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/17/2006 | PI | 26.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.9 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/17/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/24/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/24/2006 | PI | 49.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/24/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/31/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/31/2006 | PI | 19.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.8 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/31/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 8/14/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 8/14/2006 | PI | 55.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.18 J | ND(0.50) | 6.3 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 8/14/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 8/21/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 8/21/2006 | PI | 46.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.4 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 8/21/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 8/28/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 8/28/2006 | PI | 43.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.5 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 8/28/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/5/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/5/2006 | PI | 54.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.7 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/5/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/12/2006 | PI | 48.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.16 J | ND(0.50) | 4.8 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/12/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/19/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/19/2006 | PI | 31.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.3 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/19/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/26/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/26/2006 | PI | 14.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.3 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/26/2006 | PM | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/3/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/3/2006 | PI | 11.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.31 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/3/2006 | PM | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/10/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/10/2006 | PI | 17.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.3 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/10/2006 | PM | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/17/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/17/2006 | PI | 34.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.3 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/17/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/24/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/24/2006 | PI | 9.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.19 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/24/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/31/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/31/2006 | PI | 13.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.64 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/31/2006 | PM | 0.63 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/7/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/7/2006 | PI | 28 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.2 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/7/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/14/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/14/2006 | PI | 19.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.9 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/14/2006 | PM | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/21/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/21/2006 | PI | 12.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/21/2006 | PM | 0.69 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/28/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/28/2006 | PI | 12.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.81 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/28/2006 | PM | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 12/5/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L2201 | 3507 Hampshire Glen Ct | 12/5/2006 | PI | 39.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 12/5/2006 | PM | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 12/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 12/12/2006 | PI | 69.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.19 J | ND(0.50) | 6.1 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 12/12/2006 | PM | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 12/19/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 12/19/2006 | PI | 34.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.1 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 12/19/2006 | PM | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 1/9/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 1/9/2007 | PI | 44.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.7 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 1/9/2007 | PM | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 1/23/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 1/23/2007 | PI | 42.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 1/23/2007 | PM | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 2/6/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 2/6/2007 | PI | 30.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.9 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 2/6/2007 | PM | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 2/20/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 2/20/2007 | PI | 34 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.2 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 2/20/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/6/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/6/2007 | PI | 27.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.5 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/6/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/20/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/20/2007 | PI | 24.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.1 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/20/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/3/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/3/2007 | PI | 27.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.5 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/3/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/17/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/17/2007 | PI | 28.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.5 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/17/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/1/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/1/2007 | PI | 33 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.6 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/1/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/15/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/15/2007 | PI | 11.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.35 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/15/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/29/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/29/2007 | PI | 16 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.76 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/29/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/12/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/12/2007 | PI | 13.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.61 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/12/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/26/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/26/2007 | PI | 4.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.37 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/26/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/10/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/10/2007 | PI | 7.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.54 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/10/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/24/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/24/2007 | PI | 4.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.31 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/24/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 8/7/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L2201 | 3507 Hampshire Glen Ct | 8/7/2007 | PI | 6.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.54 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 8/7/2007 | PM | 0.071 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/4/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/4/2007 | PI | 3.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.21 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/4/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/18/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/18/2007 | PI | 10.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.87 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/18/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/2/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/2/2007 | PI | 7.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.53 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/2/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/16/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/16/2007 | PI | 5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.27 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/16/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/30/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/30/2007 | PI | 6.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.16 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/30/2007 | PM | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/13/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/13/2007 | PI | 5.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.33 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/13/2007 | PM | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/27/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/27/2007 | PI | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/27/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 12/11/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 12/11/2007 | PI | 3.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.20 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 12/11/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 1/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L2201 | 3507 Hampshire Glen Ct | 1/8/2008 | PI | 3.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.21 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 1/8/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 2/5/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 2/5/2008 | PI | 5.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.49 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 2/5/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/4/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/4/2008 | PI | 6.1 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.42 J | ND(5) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/4/2008 | PM | 1.5 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/8/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/8/2008 | PI | 9.2 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.54 | ND(5) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/8/2008 | PM | 1.9 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/6/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/6/2008 | PI | 7.4 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.43 J | ND(5) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/6/2008 | PM | 3.3 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/3/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/3/2008 | PI | 5.9 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.32 J | ND(5) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/3/2008 | PM | 4.8 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/8/2008 | PI | 10.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.58 | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/8/2008 | PM | 4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 8/5/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 8/5/2008 | PI | 6.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.37 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 8/5/2008 | PM | 7.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/9/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/9/2008 | PI | 4.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.24 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/9/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/7/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/7/2008 | PI | 3.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.20 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/7/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/4/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/4/2008 | PM | 3.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.22 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/18/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/18/2008 | PI | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.13 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/18/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 12/2/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 12/2/2008 | PI | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.13 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 12/2/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 1/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 1/6/2009 | PI | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.11 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 1/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 2/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 2/3/2009 | PI | 2.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.15 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 2/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/3/2009 | PI | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 3/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/7/2009 | PI | 2.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.15 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 4/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/5/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/5/2009 | PI | 2.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.13 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 5/5/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/2/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/2/2009 | PI | 3.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.17 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 6/2/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/7/2009 | PI | 2.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.13 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 7/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 8/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 8/4/2009 | PI | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.080 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 8/4/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/1/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/1/2009 | PI | 3.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.15 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 9/1/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/6/2009 | PI | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 10/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/3/2009 | PI | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.082 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 11/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 12/8/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 12/8/2009 | PI | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.089 J | ND(5.0) |
| M35P356L2201 | 3507 Hampshire Glen Ct | 12/8/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 3/2/2006 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 4/21/2006 | | 30.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.15 J | ND(0.50) | 3.3 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 4/28/2006 | | 23.6 | ND(0.50) | 14 | ND(0.50) | ND(0.50) | ND(0.50) | 0.12 J | ND(0.50) | 2.9 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 5/2/2006 | | 8.8 | ND(0.50) | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.92 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 5/9/2006 | | 6.9 | ND(0.50) | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.73 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 5/16/2006 | | 8.6 | ND(0.50) | 4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.96 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 5/23/2006 | | 29.8 | ND(0.50) | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.2 | ND(5.0) |

Kleinfelder
1340 Charwood Road, Suite I
Hanover, Maryland

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L2202 | 3507 Hampshire Glen Ct | 5/30/2006 | | 8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.93 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 6/6/2006 | | 24.5 | ND(0.50) | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.5 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 6/13/2006 | | 16.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.8 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 6/20/2006 | | 4.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.41 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 6/27/2006 | | 17.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.7 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 7/6/2006 | | 18.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.2 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 7/10/2006 | | 11.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.3 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 7/17/2006 | | 24.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.7 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 7/24/2006 | | 48.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.15 J | ND(0.50) | 5 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 7/31/2006 | | 20.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.1 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 8/14/2006 | | 51.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.18 J | ND(0.50) | 6.3 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 8/21/2006 | | 46.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.097 J | ND(0.50) | 4.5 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 8/28/2006 | | 46 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.1 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 9/5/2006 | | 55.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.5 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 9/12/2006 | | 43.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.14 J | ND(0.50) | 4.9 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 9/19/2006 | | 28.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.8 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 9/26/2006 | | 30.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 10/3/2006 | | 26.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.095 J | ND(0.50) | 2.9 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 10/10/2006 | | 23.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.5 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 10/17/2006 | | 31.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.11 J | ND(0.50) | 3.2 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 10/24/2006 | | 23.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.3 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 10/31/2006 | | 22.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 11/7/2006 | | 49.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 11/14/2006 | | 17.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.9 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 11/21/2006 | | 25.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.078 J | ND(0.50) | 2.6 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 11/28/2006 | | 23.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 12/5/2006 | | 27.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.8 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L2202 | 3507 Hampshire Glen Ct | 12/12/2006 | | 68.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.5 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 12/19/2006 | | 64.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.9 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 1/9/2007 | | 44 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.11 J | ND(0.50) | 3.9 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 1/23/2007 | | 39.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.1 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 2/6/2007 | | 35.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.3 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 2/20/2007 | | 34.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.2 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 3/6/2007 | | 26.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.6 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 3/20/2007 | | 28.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.8 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 4/3/2007 | | 27.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.6 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 4/17/2007 | | 26.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.3 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 5/1/2007 | | 27.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.3 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 5/15/2007 | | 13.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.1 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 5/29/2007 | | 11.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.95 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 6/12/2007 | | ND(0.50) | ND(0.50) | 0.060 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 6/26/2007 | | 5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.33 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 7/10/2007 | | 7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.45 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 7/24/2007 | | 4.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.29 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 8/7/2007 | | 7.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.6 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 9/4/2007 | | 3.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.22 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 9/18/2007 | | 11 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.9 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 10/2/2007 | | 7.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.54 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 10/16/2007 | | 4.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.36 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 10/30/2007 | | 4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.24 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 11/13/2007 | | 5.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | NA | NA | NA | NA |
| M35P356L2202 | 3507 Hampshire Glen Ct | 11/27/2007 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 12/11/2007 | | 3.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.21 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 1/8/2008 | | 3.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.19 J | ND(5.0) |

Kleinfelder
1340 Charwood Road, Suite I
Hanover, Maryland

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L2202 | 3507 Hampshire Glen Ct | 2/5/2008 | | 5.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.45 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 3/4/2008 | | 6.1 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.43 J | ND(5) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 4/8/2008 | | 9.4 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.56 | ND(5) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 5/6/2008 | | 7.4 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.42 J | ND(5) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 6/3/2008 | | 6 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.31 J | ND(5) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 7/8/2008 | | 11.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.58 | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 8/5/2008 | | 7.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.37 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 9/9/2008 | | 3.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.19 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 10/7/2008 | | 3.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.20 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 11/4/2008 | | 3.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.21 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 12/2/2008 | | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.11 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 1/6/2009 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.11 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 2/3/2009 | | 2.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.15 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 3/3/2009 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 4/7/2009 | | 2.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.14 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 5/5/2009 | | 2.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.14 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 6/2/2009 | | 2.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.14 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 7/7/2009 | | 2.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.12 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 8/4/2009 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.081 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 9/1/2009 | | 3.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.15 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 10/6/2009 | | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.080 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 11/3/2009 | | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.082 J | ND(5.0) |
| M35P356L2202 | 3507 Hampshire Glen Ct | 12/8/2009 | | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.088 J | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 3/3/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 3/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 3/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Kleinfelder
1340 Charwood Road, Suite I
Hanover, Maryland

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L05 | 3508 Hampshire Glen Ct | 3/30/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/3/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/1/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/1/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/1/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/8/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/8/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/8/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/15/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/15/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/15/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/22/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/22/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/22/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/31/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/31/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/31/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/5/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/5/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/5/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L05 | 3508 Hampshire Glen Ct | 6/12/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/12/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/19/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/19/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/19/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/26/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/26/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/26/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 7/10/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 7/10/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 7/10/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 7/25/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 7/25/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 7/25/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/1/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/1/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/1/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/8/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/8/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/8/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/15/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/15/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/15/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/22/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/22/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/22/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/29/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L05 | 3508 Hampshire Glen Ct | 8/29/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/29/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/5/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/5/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/5/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/12/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/12/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/19/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/19/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/19/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/26/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/26/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/26/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/3/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/3/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/3/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/10/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/10/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/10/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/17/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/17/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/17/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/24/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/24/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/24/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/31/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L05 | 3508 Hampshire Glen Ct | 10/31/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/31/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/7/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/7/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/7/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/14/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/14/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/14/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/21/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/21/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/21/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/28/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/28/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/28/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 12/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 12/12/2006 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 12/12/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 1/9/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 1/9/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 1/9/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 1/23/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 1/23/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 1/23/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 2/20/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 2/20/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 2/20/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 3/6/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Kleinfelder
1340 Charwood Road, Suite I
Hanover, Maryland

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L05 | 3508 Hampshire Glen Ct | 3/6/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 3/6/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 3/20/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 3/20/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 3/20/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/3/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/3/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/3/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/17/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/17/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/17/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/1/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/1/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/1/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/15/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/15/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/15/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/29/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/29/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/29/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/12/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/12/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/12/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/26/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/26/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/26/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 7/10/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L05 | 3508 Hampshire Glen Ct | 7/10/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 7/10/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 7/24/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 7/24/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 7/24/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/7/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/7/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/7/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/21/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/21/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/21/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/4/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/4/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/4/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/18/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/18/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/18/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/30/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/30/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/30/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/13/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/13/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/13/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/27/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/27/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/27/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 12/12/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L05 | 3508 Hampshire Glen Ct | 12/12/2007 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 12/12/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 1/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 1/8/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 1/8/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 2/5/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L05 | 3508 Hampshire Glen Ct | 2/5/2008 | PI | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L05 | 3508 Hampshire Glen Ct | 2/5/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L05 | 3508 Hampshire Glen Ct | 3/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 3/4/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 3/4/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/8/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/8/2008 | PI | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/8/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/7/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/7/2008 | PI | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/7/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/3/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/3/2008 | PI | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/3/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L05 | 3508 Hampshire Glen Ct | 7/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 7/8/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 7/8/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/5/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/5/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/5/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/9/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L05 | 3508 Hampshire Glen Ct | 9/9/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/9/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/8/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/4/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/4/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 12/2/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 12/2/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 12/2/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 1/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 1/6/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 1/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 2/5/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 2/5/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 2/5/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 3/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 3/3/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 3/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/7/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 4/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/5/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/5/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 5/5/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/3/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 6/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L05 | 3508 Hampshire Glen Ct | 7/10/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 7/10/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 7/10/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/4/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 8/4/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/15/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/15/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 9/15/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/6/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 10/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/3/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 11/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 12/8/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 12/8/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L05 | 3508 Hampshire Glen Ct | 12/8/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 3/4/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 3/29/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 4/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 4/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 4/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 4/26/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 5/2/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 5/9/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 5/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P278L02H | 3510 Hampshire Glen Ct | 5/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 5/30/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 6/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 6/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 6/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 6/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 7/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 7/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 7/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 7/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 8/1/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 8/8/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 8/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 8/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 8/29/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 9/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 9/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 9/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 9/26/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 10/3/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 10/10/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 10/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 10/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 10/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 11/7/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 11/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 11/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethylbenzene (µg/L) | Total Xylenes (µg/L) | Naphthalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|----------------|------------------------|-------------|-------------------|-------------|----------------|----------------|---------------------|----------------------|--------------------|-------------|-------------|-------------|------------|
| M35P278L02H | 3510 Hampshire Glen Ct | 11/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 12/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 12/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 1/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 2/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 2/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 3/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 3/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 4/3/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 4/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 5/1/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 5/15/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 5/29/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 6/12/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 6/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 7/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 7/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 8/7/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 8/21/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 9/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 10/2/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 10/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 10/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 11/13/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 11/27/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 12/11/2007 | | 0.066 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P278L02H | 3510 Hampshire Glen Ct | 1/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 2/5/2008 | | 0.21 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P278L02H | 3510 Hampshire Glen Ct | 3/4/2008 | | 0.077 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 4/8/2008 | | 0.073 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P278L02H | 3510 Hampshire Glen Ct | 5/6/2008 | | 0.071 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P278L02H | 3510 Hampshire Glen Ct | 6/3/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P278L02H | 3510 Hampshire Glen Ct | 7/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 8/5/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 9/9/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 10/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 11/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 12/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 1/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 2/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 3/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 4/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 5/5/2009 | | 0.082 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 6/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 7/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 8/4/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 9/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 10/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 11/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02H | 3510 Hampshire Glen Ct | 12/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 3/4/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 3/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 3/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L06 | 3600 Hampshire Glen Ct | 3/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 4/4/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 4/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 4/18/2006 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 4/25/2006 | | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 5/2/2006 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 5/9/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 5/16/2006 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 5/23/2006 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 5/30/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 6/6/2006 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 6/15/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 6/20/2006 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 6/27/2006 | | 0.47 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 7/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 7/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 7/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 7/25/2006 | | ND(5.0) | ND(5.0) | ND(5.0) | ND(5.0) | ND(5.0) | ND(5.0) | ND(5.0) | ND(5.0) | ND(5.0) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 8/1/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 8/8/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 8/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 8/29/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 9/5/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 9/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 9/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 9/26/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 10/3/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L06 | 3600 Hampshire Glen Ct | 10/10/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 10/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 10/24/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 10/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 11/7/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 11/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 11/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 11/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 12/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 12/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 12/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 1/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 2/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 2/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 3/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 4/3/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 4/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 5/1/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 5/29/2007 | | 0.077 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 6/12/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 6/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 8/7/2007 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 8/21/2007 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 9/4/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 9/18/2007 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 10/2/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L06 | 3600 Hampshire Glen Ct | 10/16/2007 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 10/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 11/13/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 11/27/2007 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 12/12/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 1/10/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 2/5/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L06 | 3600 Hampshire Glen Ct | 3/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 4/8/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L06 | 3600 Hampshire Glen Ct | 5/6/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L06 | 3600 Hampshire Glen Ct | 6/3/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L06 | 3600 Hampshire Glen Ct | 8/5/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 9/9/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 10/7/2008 | | 0.098 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 11/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 12/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 1/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 2/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 3/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 3/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 4/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 5/5/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 6/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 7/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 8/4/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 9/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 10/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L06 | 3600 Hampshire Glen Ct | 11/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L06 | 3600 Hampshire Glen Ct | 12/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 3/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 3/29/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 4/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 4/12/2006 | | 0.52 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 4/19/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 4/26/2006 | | 0.61 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 5/2/2006 | | 0.88 | ND(0.50) | 0.093 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 5/9/2006 | | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 5/16/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 5/23/2006 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 5/30/2006 | | 0.28 J | ND(0.50) | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 6/6/2006 | | 0.20 J | ND(0.50) | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 6/13/2006 | | ND(0.50) | ND(0.50) | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 6/20/2006 | | ND(0.50) | ND(0.50) | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 6/27/2006 | | 0.26 J | ND(0.50) | 0.30 J | ND(0.50) | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 7/6/2006 | | ND(0.50) | ND(0.50) | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 7/11/2006 | | ND(0.50) | ND(0.50) | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 7/18/2006 | | ND(0.50) | ND(0.50) | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 7/25/2006 | | 0.27 J | 0.13 J | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 8/1/2006 | | 0.19 J | 0.094 J | 0.35 J | ND(0.50) | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 8/8/2006 | | ND(0.50) | ND(0.50) | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 8/15/2006 | | 0.17 J | ND(0.50) | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 8/22/2006 | | 0.17 J | ND(0.50) | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 8/29/2006 | | ND(0.50) | ND(0.50) | 0.27 J | 0.090 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 9/5/2006 | | ND(0.50) | ND(0.50) | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 9/12/2006 | | ND(0.50) | ND(0.50) | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L08 | 3602 Hampshire Glen Ct | 9/19/2006 | | 0.16 J | ND(0.50) | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 9/26/2006 | | ND(0.50) | ND(0.50) | 0.098 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 10/3/2006 | | ND(0.50) | ND(0.50) | 0.086 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 10/10/2006 | | 0.17 J | ND(0.50) | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 10/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 10/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 10/31/2006 | | ND(0.50) | ND(0.50) | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 11/7/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 11/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 11/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 11/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 12/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 12/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 12/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 1/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 2/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 2/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 3/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 3/20/2007 | | ND(0.50) | ND(0.50) | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 4/3/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 4/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 5/1/2007 | | ND(0.50) | ND(0.50) | 0.077 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 5/15/2007 | | ND(0.50) | ND(0.50) | 0.059 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 5/29/2007 | | 0.14 J | ND(0.50) | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 6/12/2007 | | ND(0.50) | ND(0.50) | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 6/26/2007 | | ND(0.50) | ND(0.50) | 0.064 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L08 | 3602 Hampshire Glen Ct | 7/10/2007 | | ND(0.50) | 0.086 J | 0.30 J | ND(0.50) | 0.088 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 7/24/2007 | | ND(0.50) | ND(0.50) | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 8/7/2007 | | ND(0.50) | ND(0.50) | 0.096 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 8/21/2007 | | ND(0.50) | ND(0.50) | 0.096 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 9/4/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 9/18/2007 | | ND(0.50) | ND(0.50) | 0.076 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 10/2/2007 | | ND(0.50) | ND(0.50) | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 10/16/2007 | | ND(0.50) | ND(0.50) | 0.087 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 10/30/2007 | | ND(0.50) | ND(0.50) | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 11/13/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 11/27/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 12/11/2007 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L08 | 3602 Hampshire Glen Ct | 1/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 2/5/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L08 | 3602 Hampshire Glen Ct | 3/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 4/8/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L08 | 3602 Hampshire Glen Ct | 5/6/2008 | | ND(0.5) | 0.16 J | 0.19 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L08 | 3602 Hampshire Glen Ct | 6/3/2008 | | ND(0.5) | ND(0.5) | 0.14 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L08 | 3602 Hampshire Glen Ct | 7/17/2008 | | ND(0.50) | ND(0.50) | 0.26 J | ND(0.50) | 0.072 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 8/5/2008 | | ND(0.50) | ND(0.50) | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 9/9/2008 | | ND(0.50) | ND(0.50) | 0.069 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 10/7/2008 | | ND(0.50) | ND(0.50) | 0.076 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 11/4/2008 | | ND(0.50) | ND(0.50) | 0.051 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 12/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 1/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 2/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 3/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L08 | 3602 Hampshire Glen Ct | 4/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 5/5/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 6/2/2009 | | ND(0.50) | ND(0.50) | 0.058 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 7/7/2009 | | ND(0.50) | ND(0.50) | 0.062 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 8/4/2009 | | ND(0.50) | ND(0.50) | 0.096 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 9/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 10/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 11/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L08 | 3602 Hampshire Glen Ct | 12/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L19 | 3603 Hampshire Glen Ct | 3/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L19 | 3603 Hampshire Glen Ct | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L19 | 3603 Hampshire Glen Ct | 5/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L19 | 3603 Hampshire Glen Ct | 8/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L19 | 3603 Hampshire Glen Ct | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L19 | 3603 Hampshire Glen Ct | 4/10/2007 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L19 | 3603 Hampshire Glen Ct | 7/16/2007 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L19 | 3603 Hampshire Glen Ct | 10/23/2007 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L19 | 3603 Hampshire Glen Ct | 1/14/2008 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L19 | 3603 Hampshire Glen Ct | 4/1/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L19 | 3603 Hampshire Glen Ct | 7/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L19 | 3603 Hampshire Glen Ct | 10/13/2008 | | 0.084 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L19 | 3603 Hampshire Glen Ct | 1/14/2009 | | 0.093 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L19 | 3603 Hampshire Glen Ct | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L19 | 3603 Hampshire Glen Ct | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L19 | 3603 Hampshire Glen Ct | 10/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 3/16/2006 | | 6.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.86 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 3/29/2006 | | 10.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.2 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L09 | 3604 Hampshire Glen Ct | 4/6/2006 | | 11.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.7 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 4/11/2006 | | 17.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.2 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 4/18/2006 | | 24.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.1 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 4/25/2006 | | 23.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.8 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/2/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/2/2006 | PI | 26 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.4 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/2/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/9/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/9/2006 | PI | 22.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.8 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/9/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/16/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/16/2006 | PI | 36.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.9 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/16/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/23/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/23/2006 | PI | 38.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.2 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/23/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/31/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/31/2006 | PI | 41.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.8 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/31/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/6/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/6/2006 | PI | 41.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 6.2 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/6/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/13/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/13/2006 | PI | 49.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.19 J | ND(0.50) | ND(0.50) | 7.4 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/13/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/20/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/20/2006 | PI | 58.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 7.7 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L09 | 3604 Hampshire Glen Ct | 6/20/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/27/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/27/2006 | PI | 71.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 10.9 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/27/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/6/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/6/2006 | PI | 30.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.2 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/6/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/11/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/11/2006 | PI | 21 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.7 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/11/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/18/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/18/2006 | PI | 14.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/18/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/25/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/25/2006 | PI | 15.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.8 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/25/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/1/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/1/2006 | PI | 18.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.4 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/1/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/8/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/8/2006 | PI | 32.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/8/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/15/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/15/2006 | PI | 32.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.8 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/15/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/22/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/22/2006 | PI | 31.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.1 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L09 | 3604 Hampshire Glen Ct | 8/22/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/29/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/29/2006 | PI | 40.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/29/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/5/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/5/2006 | PI | 39.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 6.1 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/5/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/12/2006 | PI | 42.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 6.2 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/12/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/19/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/19/2006 | PI | 49.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 6.4 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/19/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/26/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/26/2006 | PI | 54.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 6.2 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/26/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/3/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/3/2006 | PI | 55.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 6.2 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/3/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/10/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/10/2006 | PI | 47.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.3 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/10/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/31/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/31/2006 | PI | 19.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.1 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/31/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/7/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/7/2006 | PI | 38 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.7 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L09 | 3604 Hampshire Glen Ct | 11/7/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/14/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/14/2006 | PI | 27 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.2 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/14/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/21/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/21/2006 | PI | 18.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.7 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/21/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/28/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/28/2006 | PI | 9.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/28/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/6/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/6/2006 | PI | 6.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.86 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/6/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/12/2006 | PI | 7.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/12/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/19/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/19/2006 | PI | 8.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.1 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/19/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 1/9/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 1/9/2007 | PI | 11.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.4 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 1/9/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 1/23/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 1/23/2007 | PI | 9.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.2 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 1/23/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 2/6/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 2/6/2007 | PI | 11.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.5 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L09 | 3604 Hampshire Glen Ct | 2/6/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 2/20/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 2/20/2007 | PI | 15.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 2/20/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 3/6/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 3/6/2007 | PI | 17 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.3 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 3/6/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 3/20/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 3/20/2007 | PI | 18 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.5 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 3/20/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 4/3/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 4/3/2007 | PI | 15 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.9 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 4/3/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 4/17/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 4/17/2007 | PI | 17.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.4 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 4/17/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/1/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/1/2007 | PI | 22.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/1/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/15/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/15/2007 | PI | 35 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.8 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/15/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/29/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/29/2007 | PI | 64.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 9.3 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/29/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/12/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/12/2007 | PI | 80.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 9.5 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L09 | 3604 Hampshire Glen Ct | 6/12/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/26/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/26/2007 | PI | 74.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 10.9 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/26/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/10/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/10/2007 | PI | 80.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 10.5 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/10/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/24/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/24/2007 | PI | 77.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 10 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/24/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/21/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/21/2007 | PI | 46 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 7.5 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/21/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/4/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/4/2007 | PI | 58 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 6.7 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/4/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/18/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/18/2007 | PI | 38 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.4 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/18/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/2/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/2/2007 | PI | 37.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.2 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/2/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/16/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/16/2007 | PI | 30.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.7 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/16/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/30/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/30/2007 | PI | 24.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.6 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L09 | 3604 Hampshire Glen Ct | 10/30/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/13/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/13/2007 | PI | 17.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.5 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/13/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/27/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/27/2007 | PI | 13.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.5 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/27/2007 | PM | 0.098 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/11/2007 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/11/2007 | PI | 7.1 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.75 | ND(5) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/11/2007 | PM | 0.5 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L09 | 3604 Hampshire Glen Ct | 1/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 1/8/2008 | PI | 9.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.94 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 1/8/2008 | PM | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 2/5/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L09 | 3604 Hampshire Glen Ct | 2/5/2008 | PI | 6.2 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.88 | ND(5) |
| M35P356L09 | 3604 Hampshire Glen Ct | 2/5/2008 | PM | 0.5 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L09 | 3604 Hampshire Glen Ct | 3/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 3/4/2008 | PI | 3.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.41 J | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 3/4/2008 | PM | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 4/8/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L09 | 3604 Hampshire Glen Ct | 4/8/2008 | PI | 3.8 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.48 J | ND(5) |
| M35P356L09 | 3604 Hampshire Glen Ct | 4/8/2008 | PM | 0.48 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/6/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/6/2008 | PI | 3.4 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.45 J | ND(5) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/6/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/3/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/3/2008 | PI | 1.9 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.21 J | ND(5) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L09 | 3604 Hampshire Glen Ct | 6/3/2008 | PM | 0.85 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/8/2008 | PI | 2.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.29 J | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/8/2008 | PM | 4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/29/2008 | PE | ND(0.50) | ND(0.50) | 0.070 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/29/2008 | PI | 5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.42 J | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/29/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/5/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/5/2008 | PI | 5.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.66 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/5/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/16/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/16/2008 | PI | 7.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.89 | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/16/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/7/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/7/2008 | PI | 4.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.49 J | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/7/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/4/2008 | PI | 3.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.40 J | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/4/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/2/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/2/2008 | PI | 2.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.30 J | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/2/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 1/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 1/6/2009 | PI | 2.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.26 J | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 1/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 2/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 2/3/2009 | PI | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.17 J | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L09 | 3604 Hampshire Glen Ct | 2/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 3/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 3/3/2009 | PI | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.20 J | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 3/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 4/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 4/7/2009 | PI | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.13 J | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 4/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/5/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/5/2009 | PI | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.14 J | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 5/5/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/2/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/2/2009 | PI | 0.98 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.12 J | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 6/2/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/7/2009 | PI | 0.91 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.087 J | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 7/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/4/2009 | PI | 1.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.21 J | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 8/4/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/1/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/1/2009 | PI | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.20 J | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 9/1/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/6/2009 | PI | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.18 J | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 10/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 11/3/2009 | PI | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.12 J | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L09 | 3604 Hampshire Glen Ct | 11/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/1/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/1/2009 | PI | 0.67 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.085 J | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/1/2009 | PM | 0.094 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/21/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/21/2009 | PI | 0.64 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L09 | 3604 Hampshire Glen Ct | 12/21/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L18 | 3605 Hampshire Glen Ct | 3/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L18 | 3605 Hampshire Glen Ct | 4/17/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L18 | 3605 Hampshire Glen Ct | 5/30/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L18 | 3605 Hampshire Glen Ct | 8/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L18 | 3605 Hampshire Glen Ct | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L18 | 3605 Hampshire Glen Ct | 4/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L18 | 3605 Hampshire Glen Ct | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L18 | 3605 Hampshire Glen Ct | 10/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L18 | 3605 Hampshire Glen Ct | 1/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L18 | 3605 Hampshire Glen Ct | 4/1/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L18 | 3605 Hampshire Glen Ct | 7/17/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L18 | 3605 Hampshire Glen Ct | 10/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L18 | 3605 Hampshire Glen Ct | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L18 | 3605 Hampshire Glen Ct | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L18 | 3605 Hampshire Glen Ct | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L18 | 3605 Hampshire Glen Ct | 10/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 3/16/2006 | | 20.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.9 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 3/20/2006 | | 19.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.9 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 3/27/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 3/27/2006 | PI | 16.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L11 | 3606 Hampshire Glen Ct | 3/27/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/4/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/4/2006 | PI | 15.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.1 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/4/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/12/2006 | PI | 18.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.6 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/12/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/19/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/19/2006 | PI | 19.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.6 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/19/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/26/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/26/2006 | PI | 16.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.2 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/26/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/2/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/2/2006 | PI | 16.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.5 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/2/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/9/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/9/2006 | PI | 15.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.2 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/9/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/16/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/16/2006 | PI | 15 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/16/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/23/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/23/2006 | PI | 13 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.9 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/23/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/30/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/30/2006 | PI | 13 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.6 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L11 | 3606 Hampshire Glen Ct | 5/30/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/6/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/6/2006 | PI | 11.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.8 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/6/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/13/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/13/2006 | PI | 11.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.6 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/13/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/20/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/20/2006 | PI | 12.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.6 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/20/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/27/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/27/2006 | PI | 12 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.5 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/27/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/6/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/6/2006 | PI | 13.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.7 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/6/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/11/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/11/2006 | PI | 11.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.6 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/11/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/18/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/18/2006 | PI | 12 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.5 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/18/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/1/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/1/2006 | PI | 11.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.6 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/1/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/8/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/8/2006 | PI | 10.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.6 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L11 | 3606 Hampshire Glen Ct | 8/8/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/15/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/15/2006 | PI | 10.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.6 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/15/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/22/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/22/2006 | PI | 12.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.6 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/22/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/29/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/29/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/29/2006 | PM2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/5/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/5/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/5/2006 | PM2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/12/2006 | PI | 12.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.8 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/12/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/19/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/19/2006 | PI | 12.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.8 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/19/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/26/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/26/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/26/2006 | PM2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/3/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/3/2006 | PI | 14.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.1 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/3/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/10/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/10/2006 | PI | 15 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.1 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L11 | 3606 Hampshire Glen Ct | 10/10/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/17/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/17/2006 | PI | 16.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.2 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/17/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/24/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/24/2006 | PI | 15.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.1 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/24/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/31/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/31/2006 | PI | 16.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.1 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/31/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/7/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/7/2006 | PI | 17.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.2 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/7/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/14/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/14/2006 | PI | 15.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.3 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/14/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/21/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/21/2006 | PI | 17.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.3 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/21/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/28/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/28/2006 | PI | 13.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.7 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/28/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 12/5/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 12/5/2006 | PI | 14.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.1 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 12/5/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 12/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 12/12/2006 | PI | 15.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.9 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L11 | 3606 Hampshire Glen Ct | 12/12/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 12/19/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 12/19/2006 | PI | 15.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.7 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 12/19/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 1/9/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 1/9/2007 | PI | 16.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 1/9/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 1/23/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 1/23/2007 | PI | 15.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.8 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 1/23/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 2/20/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 2/20/2007 | PI | 15.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.1 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 2/20/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 3/6/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 3/6/2007 | PI | 13.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.8 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 3/6/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 3/20/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 3/20/2007 | PI | 14.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.7 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 3/20/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/3/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/3/2007 | PI | 12.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.8 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/3/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/17/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/17/2007 | PI | 10.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.5 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/17/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/1/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/1/2007 | PI | 11.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.6 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L11 | 3606 Hampshire Glen Ct | 5/1/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/15/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/15/2007 | PI | 11.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.6 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/15/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/29/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/29/2007 | PI | 10.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.5 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/29/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/12/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/12/2007 | PI | 9.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/12/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/26/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/26/2007 | PI | 10.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.2 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/26/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/10/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/10/2007 | PI | 11.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.3 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/10/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/24/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/24/2007 | PI | 10.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.4 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/24/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/7/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/7/2007 | PI | 11.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.4 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/7/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/21/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/21/2007 | PI | 14.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.6 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/21/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/4/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/4/2007 | PI | 12.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.3 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L11 | 3606 Hampshire Glen Ct | 9/4/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/18/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/18/2007 | PI | 13.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.3 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/18/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/2/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/2/2007 | PI | 14.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.1 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/2/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/16/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/16/2007 | PI | 10.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.59 | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/16/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/30/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/30/2007 | PI | 6.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.46 J | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/30/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/13/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/13/2007 | PI | 7.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.34 J | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/13/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/27/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/27/2007 | PI | 7.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.41 J | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/27/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 12/11/2007 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L11 | 3606 Hampshire Glen Ct | 12/11/2007 | PI | 5.3 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.31 J | ND(5) |
| M35P356L11 | 3606 Hampshire Glen Ct | 12/11/2007 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L11 | 3606 Hampshire Glen Ct | 1/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 1/8/2008 | PI | 3.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.20 J | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 1/8/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 2/5/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L11 | 3606 Hampshire Glen Ct | 2/5/2008 | PI | 1.9 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.21 J | ND(5) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L11 | 3606 Hampshire Glen Ct | 2/5/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L11 | 3606 Hampshire Glen Ct | 3/4/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L11 | 3606 Hampshire Glen Ct | 3/4/2008 | PI | 2.5 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.14 J | ND(5) |
| M35P356L11 | 3606 Hampshire Glen Ct | 3/4/2008 | PM | 0.09 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/8/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/8/2008 | PI | 2 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.12 J | ND(5) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/8/2008 | PM | 0.079 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/6/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/6/2008 | PI | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.12 J | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/6/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/3/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/3/2008 | PI | 1.6 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/3/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/8/2008 | PI | 0.83 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/8/2008 | PM | 0.093 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/5/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/5/2008 | PI | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/5/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/9/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/9/2008 | PI | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/9/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/7/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/7/2008 | PI | 0.81 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/7/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/4/2008 | PI | 0.97 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L11 | 3606 Hampshire Glen Ct | 11/4/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 12/2/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 12/2/2008 | PI | 0.62 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 12/2/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 1/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 1/6/2009 | PI | 0.66 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 1/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 2/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 2/3/2009 | PI | 0.55 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 2/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 2/10/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 2/10/2009 | PI | 0.68 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 2/10/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 3/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 3/3/2009 | PI | 0.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 3/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/7/2009 | PI | 0.53 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 4/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/5/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/5/2009 | PI | 0.54 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 5/5/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/2/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/2/2009 | PI | 0.58 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 6/2/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 7/7/2009 | PI | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L11 | 3606 Hampshire Glen Ct | 7/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/4/2009 | PI | 0.53 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 8/4/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/8/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/8/2009 | PI | 0.45 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 9/8/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/6/2009 | PI | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 10/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/3/2009 | PI | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 11/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 12/8/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 12/8/2009 | PI | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L11 | 3606 Hampshire Glen Ct | 12/8/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L17 | 3607 Hampshire Glen Ct | 3/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L17 | 3607 Hampshire Glen Ct | 4/17/2006 | | 0.73 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L17 | 3607 Hampshire Glen Ct | 6/16/2006 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L17 | 3607 Hampshire Glen Ct | 8/15/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L17 | 3607 Hampshire Glen Ct | 12/11/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L17 | 3607 Hampshire Glen Ct | 4/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L17 | 3607 Hampshire Glen Ct | 7/16/2007 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L17 | 3607 Hampshire Glen Ct | 10/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L17 | 3607 Hampshire Glen Ct | 1/14/2008 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L17 | 3607 Hampshire Glen Ct | 4/3/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L17 | 3607 Hampshire Glen Ct | 7/16/2008 | | 0.096 J | ND(0.50) | 0.069 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L17 | 3607 Hampshire Glen Ct | 10/21/2008 | | 0.078 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L17 | 3607 Hampshire Glen Ct | 1/15/2009 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L17 | 3607 Hampshire Glen Ct | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L17 | 3607 Hampshire Glen Ct | 8/6/2009 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L17 | 3607 Hampshire Glen Ct | 10/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 3/15/2006 | | 16.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.3 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 3/20/2006 | | 16.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.6 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 3/24/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 3/24/2006 | PI | 15.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.2 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 3/24/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 3/29/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 3/29/2006 | PI | 16.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.3 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 3/29/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/5/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/5/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/6/2006 | PI | 17.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.5 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/12/2006 | PI | 16.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.3 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/12/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/19/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/19/2006 | PI | 18.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.5 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/19/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/26/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/26/2006 | PI | 15.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.8 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/26/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/2/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/2/2006 | PI | 15.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.6 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L12 | 3608 Hampshire Glen Ct | 5/2/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/9/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/9/2006 | PI | 15.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.9 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/9/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/23/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/23/2006 | PI | 12.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.5 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/23/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/30/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/30/2006 | PI | 10.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.2 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/30/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/6/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/6/2006 | PI | 9.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.2 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/6/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/13/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/13/2006 | PI | 8.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.98 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/13/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/20/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/20/2006 | PI | 9.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.96 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/20/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/27/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/27/2006 | PI | 3.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.29 J | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/27/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/6/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/6/2006 | PI | 10.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.2 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/6/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/18/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/18/2006 | PI | 6.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.75 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L12 | 3608 Hampshire Glen Ct | 7/18/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/25/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/25/2006 | PI | 5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.65 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/25/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/1/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/1/2006 | PI | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.21 J | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/1/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/8/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/8/2006 | PI | 3.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.47 J | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/8/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/15/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/15/2006 | PI | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.25 J | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/15/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/22/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/22/2006 | PI | 6.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.67 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/22/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/29/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/29/2006 | PI | 5.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.68 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/29/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/5/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/5/2006 | PI | 5.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.63 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/5/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/12/2006 | PI | 4.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.46 J | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/12/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/26/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/26/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L12 | 3608 Hampshire Glen Ct | 9/26/2006 | PM2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/3/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/3/2006 | PI | 8.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/3/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/10/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/10/2006 | PI | 6.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.83 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/10/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/17/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/17/2006 | PI | 5.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.63 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/17/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/24/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/24/2006 | PI | 4.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.58 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/24/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/31/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/31/2006 | PI | 4.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.49 J | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/31/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/7/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/7/2006 | PI | 3.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.33 J | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/7/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/14/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/14/2006 | PI | 8.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.2 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/14/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/21/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/21/2006 | PI | 6.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.74 | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/21/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/28/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/28/2006 | PI | 2.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.24 J | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L12 | 3608 Hampshire Glen Ct | 11/28/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 12/5/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 12/5/2006 | PI | 3.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.34 J | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 12/5/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 12/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 12/12/2006 | PI | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.15 J | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 12/12/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 12/19/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 12/19/2006 | PI | 2.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.13 J | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 12/19/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 1/9/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 1/9/2007 | PI | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 1/9/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 1/23/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 1/23/2007 | PI | 0.87 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 1/23/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 2/6/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 2/6/2007 | PI | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 2/6/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 2/20/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 2/20/2007 | PI | 0.91 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 2/20/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 3/6/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 3/6/2007 | PI | 0.51 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 3/6/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 3/20/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 3/20/2007 | PI | 0.94 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L12 | 3608 Hampshire Glen Ct | 3/20/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/3/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/3/2007 | PI | 0.86 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/3/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/17/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/17/2007 | PI | 0.88 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/17/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/1/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/1/2007 | PI | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/1/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/15/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/15/2007 | PI | 0.78 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/15/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/29/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/29/2007 | PI | 0.78 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/29/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/12/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/12/2007 | PI | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/12/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/10/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/10/2007 | PI | 0.74 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/10/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/24/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/24/2007 | PI | 0.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/24/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/7/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/7/2007 | PI | 0.51 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L12 | 3608 Hampshire Glen Ct | 8/7/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/21/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/21/2007 | PI | 0.46 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/21/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/4/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/4/2007 | PI | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/4/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/18/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/18/2007 | PI | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/18/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/2/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/2/2007 | PI | 0.67 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/2/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/16/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/16/2007 | PI | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/16/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/30/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/30/2007 | PI | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/30/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/13/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/13/2007 | PI | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/13/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/27/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/27/2007 | PI | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/27/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 12/11/2007 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L12 | 3608 Hampshire Glen Ct | 12/11/2007 | PI | 0.26 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L12 | 3608 Hampshire Glen Ct | 12/11/2007 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L12 | 3608 Hampshire Glen Ct | 1/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 1/8/2008 | PI | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 1/8/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 2/5/2008 | PE | 0.25 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L12 | 3608 Hampshire Glen Ct | 2/5/2008 | PI | 0.29 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L12 | 3608 Hampshire Glen Ct | 2/5/2008 | PM | 0.16 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/8/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/8/2008 | PI | 0.25 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/8/2008 | PM | 0.13 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/6/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/6/2008 | PI | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/6/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/3/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/3/2008 | PI | 0.31 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/3/2008 | PM | 0.23 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/8/2008 | PI | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/8/2008 | PM | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/5/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/5/2008 | PI | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/5/2008 | PM | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/9/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/9/2008 | PI | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/9/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/7/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/7/2008 | PI | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L12 | 3608 Hampshire Glen Ct | 10/7/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/4/2008 | PI | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/4/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 12/2/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 12/2/2008 | PI | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 12/2/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 1/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 1/6/2009 | PI | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 1/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 2/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 2/3/2009 | PI | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 2/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 2/12/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 2/12/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 2/12/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 3/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 3/3/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 3/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/7/2009 | PI | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 4/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/5/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/5/2009 | PI | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 5/5/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/2/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 6/2/2009 | PI | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L12 | 3608 Hampshire Glen Ct | 6/2/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/21/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/21/2009 | PI | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 7/21/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/5/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/5/2009 | PI | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 8/5/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/1/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/1/2009 | PI | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 9/1/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/6/2009 | PI | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 10/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/3/2009 | PI | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 11/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 12/8/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 12/8/2009 | PI | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L12 | 3608 Hampshire Glen Ct | 12/8/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L16 | 3609 Hampshire Glen Ct | 3/14/2006 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L16 | 3609 Hampshire Glen Ct | 4/17/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L16 | 3609 Hampshire Glen Ct | 6/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L16 | 3609 Hampshire Glen Ct | 8/15/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L16 | 3609 Hampshire Glen Ct | 1/22/2007 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L16 | 3609 Hampshire Glen Ct | 4/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L16 | 3609 Hampshire Glen Ct | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L16 | 3609 Hampshire Glen Ct | 10/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L16 | 3609 Hampshire Glen Ct | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L16 | 3609 Hampshire Glen Ct | 4/4/2008 | | 1.3 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.34 J | ND(5) |
| M35P356L16 | 3609 Hampshire Glen Ct | 7/21/2008 | | 0.62 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L16 | 3609 Hampshire Glen Ct | 10/8/2008 | | 0.75 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.16 J | ND(5.0) |
| M35P356L16 | 3609 Hampshire Glen Ct | 1/12/2009 | | 2.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.71 | ND(5.0) |
| M35P356L16 | 3609 Hampshire Glen Ct | 4/8/2009 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.30 J | ND(5.0) |
| M35P356L16 | 3609 Hampshire Glen Ct | 7/22/2009 | | 0.97 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.32 J | ND(5.0) |
| M35P356L16 | 3609 Hampshire Glen Ct | 10/7/2009 | | 0.92 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.23 J | ND(5.0) |
| M35P356L13 | 3610 Hampshire Glen Ct | 3/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L13 | 3610 Hampshire Glen Ct | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L13 | 3610 Hampshire Glen Ct | 6/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L13 | 3610 Hampshire Glen Ct | 8/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L13 | 3610 Hampshire Glen Ct | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L13 | 3610 Hampshire Glen Ct | 4/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L13 | 3610 Hampshire Glen Ct | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L13 | 3610 Hampshire Glen Ct | 10/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L13 | 3610 Hampshire Glen Ct | 1/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L13 | 3610 Hampshire Glen Ct | 4/1/2008 | | 0.09 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L13 | 3610 Hampshire Glen Ct | 7/17/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L13 | 3610 Hampshire Glen Ct | 10/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L13 | 3610 Hampshire Glen Ct | 1/13/2009 | | ND(0.50) | ND(0.50) | 0.58 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L13 | 3610 Hampshire Glen Ct | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L13 | 3610 Hampshire Glen Ct | 7/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L13 | 3610 Hampshire Glen Ct | 10/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L14 | 3612 Hampshire Glen Ct | 3/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L14 | 3612 Hampshire Glen Ct | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L14 | 3612 Hampshire Glen Ct | 6/14/2006 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L14 | 3612 Hampshire Glen Ct | 8/15/2006 | | 1.2 | ND(0.50) | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L14 | 3612 Hampshire Glen Ct | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L14 | 3612 Hampshire Glen Ct | 4/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L14 | 3612 Hampshire Glen Ct | 7/16/2007 | | ND(0.50) | ND(0.50) | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L14 | 3612 Hampshire Glen Ct | 10/24/2007 | | 0.56 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L14 | 3612 Hampshire Glen Ct | 1/14/2008 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L14 | 3612 Hampshire Glen Ct | 7/16/2008 | | ND(0.50) | ND(0.50) | 0.066 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L14 | 3612 Hampshire Glen Ct | 10/9/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L14 | 3612 Hampshire Glen Ct | 1/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L14 | 3612 Hampshire Glen Ct | 4/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L14 | 3612 Hampshire Glen Ct | 7/14/2009 | | ND(0.50) | ND(0.50) | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L14 | 3612 Hampshire Glen Ct | 10/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L15 | 3614 Hampshire Glen Ct | 3/14/2006 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L15 | 3614 Hampshire Glen Ct | 4/18/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L15 | 3614 Hampshire Glen Ct | 6/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L15 | 3614 Hampshire Glen Ct | 8/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L15 | 3614 Hampshire Glen Ct | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L15 | 3614 Hampshire Glen Ct | 4/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L15 | 3614 Hampshire Glen Ct | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L15 | 3614 Hampshire Glen Ct | 10/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L15 | 3614 Hampshire Glen Ct | 1/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L15 | 3614 Hampshire Glen Ct | 4/1/2008 | | ND(0.5) | 0.096 J | 0.11 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P356L15 | 3614 Hampshire Glen Ct | 7/16/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L15 | 3614 Hampshire Glen Ct | 10/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L15 | 3614 Hampshire Glen Ct | 1/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L15 | 3614 Hampshire Glen Ct | 4/2/2009 | | ND(0.50) | ND(0.50) | 0.081 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L15 | 3614 Hampshire Glen Ct | 7/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L15 | 3614 Hampshire Glen Ct | 10/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L1R | 14351 Hampshire Knob Dr | 3/4/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L1R | 14351 Hampshire Knob Dr | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L1R | 14351 Hampshire Knob Dr | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L1R | 14351 Hampshire Knob Dr | 6/15/2006 | | ND(0.50) | ND(0.50) | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L1R | 14351 Hampshire Knob Dr | 8/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L1R | 14351 Hampshire Knob Dr | 4/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L1R | 14351 Hampshire Knob Dr | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L1R | 14351 Hampshire Knob Dr | 10/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L1R | 14351 Hampshire Knob Dr | 1/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L1R | 14351 Hampshire Knob Dr | 4/1/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L1R | 14351 Hampshire Knob Dr | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L1R | 14351 Hampshire Knob Dr | 10/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L1R | 14351 Hampshire Knob Dr | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L1R | 14351 Hampshire Knob Dr | 4/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L1R | 14351 Hampshire Knob Dr | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L1R | 14351 Hampshire Knob Dr | 10/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L21 | 14352 Hampshire Knob Dr | 3/4/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L21 | 14352 Hampshire Knob Dr | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L21 | 14352 Hampshire Knob Dr | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L21 | 14352 Hampshire Knob Dr | 6/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L21 | 14352 Hampshire Knob Dr | 8/29/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L21 | 14352 Hampshire Knob Dr | 3/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L21 | 14352 Hampshire Knob Dr | 4/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L21 | 14352 Hampshire Knob Dr | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L21 | 14352 Hampshire Knob Dr | 10/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L21 | 14352 Hampshire Knob Dr | 1/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P356L21 | 14352 Hampshire Knob Dr | 4/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 24 |
| M35P356L21 | 14352 Hampshire Knob Dr | 10/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L21 | 14352 Hampshire Knob Dr | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L21 | 14352 Hampshire Knob Dr | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L21 | 14352 Hampshire Knob Dr | 8/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L20 | 14355 Hampshire Knob Dr | 4/4/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L20 | 14355 Hampshire Knob Dr | 2/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L20 | 14355 Hampshire Knob Dr | 4/11/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L20 | 14355 Hampshire Knob Dr | 8/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L20 | 14355 Hampshire Knob Dr | 10/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L20 | 14355 Hampshire Knob Dr | 2/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L20 | 14355 Hampshire Knob Dr | 4/3/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L20 | 14355 Hampshire Knob Dr | 10/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L20 | 14355 Hampshire Knob Dr | 1/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L20 | 14355 Hampshire Knob Dr | 4/16/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L20 | 14355 Hampshire Knob Dr | 7/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P356L20 | 14355 Hampshire Knob Dr | 10/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L30R | 3601 Jackson Cabin Rd | 3/2/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L30R | 3601 Jackson Cabin Rd | 3/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L30R | 3601 Jackson Cabin Rd | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L30R | 3601 Jackson Cabin Rd | 6/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L30R | 3601 Jackson Cabin Rd | 8/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L30R | 3601 Jackson Cabin Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L30R | 3601 Jackson Cabin Rd | 4/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L30R | 3601 Jackson Cabin Rd | 7/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L30R | 3601 Jackson Cabin Rd | 1/15/2008 | | 0.085 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L30R | 3601 Jackson Cabin Rd | 4/1/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethylbenzene (µg/L) | Total Xylenes (µg/L) | Naphthalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|----------------|-----------------------|-------------|-------------------|-------------|----------------|----------------|---------------------|----------------------|--------------------|-------------|-------------|-------------|------------|
| M35P224L30R | 3601 Jackson Cabin Rd | 7/14/2008 | | 0.066 J | 0.096 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L30R | 3601 Jackson Cabin Rd | 10/9/2008 | | 0.076 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L30R | 3601 Jackson Cabin Rd | 10/14/2008 | | 0.092 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L30R | 3601 Jackson Cabin Rd | 1/14/2009 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L30R | 3601 Jackson Cabin Rd | 4/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L30R | 3601 Jackson Cabin Rd | 7/8/2009 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L30R | 3601 Jackson Cabin Rd | 10/12/2009 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L02 | 3602 Jackson Cabin Rd | 3/4/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L02 | 3602 Jackson Cabin Rd | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L02 | 3602 Jackson Cabin Rd | 4/19/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L02 | 3602 Jackson Cabin Rd | 6/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L02 | 3602 Jackson Cabin Rd | 8/16/2006 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L02 | 3602 Jackson Cabin Rd | 4/10/2007 | | 0.47 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L02 | 3602 Jackson Cabin Rd | 9/4/2007 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L02 | 3602 Jackson Cabin Rd | 10/24/2007 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L02 | 3602 Jackson Cabin Rd | 1/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L02 | 3602 Jackson Cabin Rd | 4/4/2008 | | 0.44 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L02 | 3602 Jackson Cabin Rd | 7/17/2008 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L02 | 3602 Jackson Cabin Rd | 10/10/2008 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L02 | 3602 Jackson Cabin Rd | 4/1/2009 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L02 | 3602 Jackson Cabin Rd | 7/15/2009 | | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L29 | 3603 Jackson Cabin Rd | 3/15/2006 | | 0.79 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L29 | 3603 Jackson Cabin Rd | 4/18/2006 | | 1.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.28 J | ND(5.0) |
| M35P224L29 | 3603 Jackson Cabin Rd | 6/13/2006 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.23 J | ND(5.0) |
| M35P224L29 | 3603 Jackson Cabin Rd | 8/14/2006 | | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L29 | 3603 Jackson Cabin Rd | 1/22/2007 | | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.33 J | ND(5.0) |
| M35P224L29 | 3603 Jackson Cabin Rd | 4/11/2007 | | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.36 J | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-----------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P224L29 | 3603 Jackson Cabin Rd | 7/16/2007 | | 1.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.23 J | ND(5.0) |
| M35P224L29 | 3603 Jackson Cabin Rd | 10/23/2007 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.12 J | ND(5.0) |
| M35P224L29 | 3603 Jackson Cabin Rd | 1/14/2008 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.17 J | ND(5.0) |
| M35P224L29 | 3603 Jackson Cabin Rd | 4/1/2008 | | 1.1 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.14 J | ND(5) |
| M35P224L29 | 3603 Jackson Cabin Rd | 7/14/2008 | | 0.89 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L29 | 3603 Jackson Cabin Rd | 10/8/2008 | | 0.72 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.090 J | ND(5.0) |
| M35P224L29 | 3603 Jackson Cabin Rd | 1/12/2009 | | 0.98 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.12 J | ND(5.0) |
| M35P224L29 | 3603 Jackson Cabin Rd | 4/1/2009 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L29 | 3603 Jackson Cabin Rd | 7/14/2009 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.29 J | ND(5.0) |
| M35P224L29 | 3603 Jackson Cabin Rd | 10/7/2009 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.15 J | ND(5.0) |
| M35P224L03 | 3604 Jackson Cabin Rd | 3/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L03 | 3604 Jackson Cabin Rd | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L03 | 3604 Jackson Cabin Rd | 6/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L03 | 3604 Jackson Cabin Rd | 8/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L03 | 3604 Jackson Cabin Rd | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L03 | 3604 Jackson Cabin Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L03 | 3604 Jackson Cabin Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L03 | 3604 Jackson Cabin Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L03 | 3604 Jackson Cabin Rd | 1/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L03 | 3604 Jackson Cabin Rd | 7/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L28 | 3605 Jackson Cabin Rd | 3/18/2006 | | 7.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.1 | ND(5.0) |
| M35P224L28 | 3605 Jackson Cabin Rd | 4/18/2006 | | 7.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.1 | ND(5.0) |
| M35P224L28 | 3605 Jackson Cabin Rd | 6/17/2006 | | 5.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.71 | ND(5.0) |
| M35P224L28 | 3605 Jackson Cabin Rd | 8/15/2006 | | 6.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.96 | ND(5.0) |
| M35P224L28 | 3605 Jackson Cabin Rd | 1/23/2007 | | 5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.85 | ND(5.0) |
| M35P224L28 | 3605 Jackson Cabin Rd | 7/16/2007 | | 5.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.66 | ND(5.0) |
| M35P224L28 | 3605 Jackson Cabin Rd | 1/15/2008 | | 4.3 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.56 | ND(5) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-----------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P224L28 | 3605 Jackson Cabin Rd | 7/18/2008 | | 3.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.48 J | ND(5.0) |
| M35P224L28 | 3605 Jackson Cabin Rd | 1/7/2009 | | 3.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.35 J | ND(5.0) |
| M35P224L28 | 3605 Jackson Cabin Rd | 7/8/2009 | | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.23 J | ND(5.0) |
| M35P224L04 | 3606 Jackson Cabin Rd | 3/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L04 | 3606 Jackson Cabin Rd | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L04 | 3606 Jackson Cabin Rd | 6/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L04 | 3606 Jackson Cabin Rd | 8/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L04 | 3606 Jackson Cabin Rd | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L04 | 3606 Jackson Cabin Rd | 7/16/2007 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L04 | 3606 Jackson Cabin Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L04 | 3606 Jackson Cabin Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L04 | 3606 Jackson Cabin Rd | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L04 | 3606 Jackson Cabin Rd | 7/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L27 | 3607 Jackson Cabin Rd | 3/14/2006 | | 0.76 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L27 | 3607 Jackson Cabin Rd | 4/18/2006 | | 0.75 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L27 | 3607 Jackson Cabin Rd | 6/12/2006 | | 0.81 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L27 | 3607 Jackson Cabin Rd | 8/22/2006 | | 0.56 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L27 | 3607 Jackson Cabin Rd | 1/22/2007 | | 0.85 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L27 | 3607 Jackson Cabin Rd | 7/16/2007 | | 0.75 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L27 | 3607 Jackson Cabin Rd | 1/14/2008 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L27 | 3607 Jackson Cabin Rd | 7/14/2008 | | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L27 | 3607 Jackson Cabin Rd | 1/7/2009 | | 0.71 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L27 | 3607 Jackson Cabin Rd | 7/8/2009 | | 0.46 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L05 | 3608 Jackson Cabin Rd | 3/16/2006 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L05 | 3608 Jackson Cabin Rd | 4/21/2006 | | 0.68 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L05 | 3608 Jackson Cabin Rd | 6/14/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L05 | 3608 Jackson Cabin Rd | 8/15/2006 | | 0.47 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-----------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P224L05 | 3608 Jackson Cabin Rd | 1/22/2007 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L05 | 3608 Jackson Cabin Rd | 7/21/2007 | | 0.73 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L05 | 3608 Jackson Cabin Rd | 1/21/2008 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L05 | 3608 Jackson Cabin Rd | 9/5/2008 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L05 | 3608 Jackson Cabin Rd | 1/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L05 | 3608 Jackson Cabin Rd | 7/9/2009 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L26 | 3609 Jackson Cabin Rd | 3/14/2006 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L26 | 3609 Jackson Cabin Rd | 4/18/2006 | | 0.58 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L26 | 3609 Jackson Cabin Rd | 6/13/2006 | | 0.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L26 | 3609 Jackson Cabin Rd | 8/17/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L26 | 3609 Jackson Cabin Rd | 1/27/2007 | | 0.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L26 | 3609 Jackson Cabin Rd | 7/21/2007 | | 0.75 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L26 | 3609 Jackson Cabin Rd | 1/15/2008 | | 0.73 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L26 | 3609 Jackson Cabin Rd | 7/16/2008 | | 0.58 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L26 | 3609 Jackson Cabin Rd | 1/14/2009 | | 0.77 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L26 | 3609 Jackson Cabin Rd | 7/16/2009 | | 3.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.1 | ND(0.50) | 0.29 J | ND(5.0) |
| M35P224L06 | 3610 Jackson Cabin Rd | 3/18/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L06 | 3610 Jackson Cabin Rd | 4/22/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L06 | 3610 Jackson Cabin Rd | 6/14/2006 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L06 | 3610 Jackson Cabin Rd | 8/18/2006 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L06 | 3610 Jackson Cabin Rd | 1/23/2007 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L06 | 3610 Jackson Cabin Rd | 7/17/2007 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L06 | 3610 Jackson Cabin Rd | 1/14/2008 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L06 | 3610 Jackson Cabin Rd | 7/18/2008 | | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L06 | 3610 Jackson Cabin Rd | 1/13/2009 | | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L06 | 3610 Jackson Cabin Rd | 7/8/2009 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L25 | 3611 Jackson Cabin Rd | 3/14/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-----------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P224L25 | 3611 Jackson Cabin Rd | 4/22/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L25 | 3611 Jackson Cabin Rd | 7/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L25 | 3611 Jackson Cabin Rd | 8/28/2006 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L25 | 3611 Jackson Cabin Rd | 7/20/2007 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L25 | 3611 Jackson Cabin Rd | 1/14/2008 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L25 | 3611 Jackson Cabin Rd | 7/31/2009 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L07 | 3612 Jackson Cabin Rd | 3/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L07 | 3612 Jackson Cabin Rd | 4/18/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L07 | 3612 Jackson Cabin Rd | 6/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L07 | 3612 Jackson Cabin Rd | 8/15/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L07 | 3612 Jackson Cabin Rd | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L07 | 3612 Jackson Cabin Rd | 7/17/2007 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L07 | 3612 Jackson Cabin Rd | 1/14/2008 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L07 | 3612 Jackson Cabin Rd | 7/15/2008 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L07 | 3612 Jackson Cabin Rd | 1/7/2009 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L07 | 3612 Jackson Cabin Rd | 4/9/2009 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L07 | 3612 Jackson Cabin Rd | 7/9/2009 | | 0.094 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L24 | 3615 Jackson Cabin Rd | 3/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L24 | 3615 Jackson Cabin Rd | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L24 | 3615 Jackson Cabin Rd | 6/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L24 | 3615 Jackson Cabin Rd | 8/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L24 | 3615 Jackson Cabin Rd | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L24 | 3615 Jackson Cabin Rd | 7/17/2007 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L24 | 3615 Jackson Cabin Rd | 1/15/2008 | | 0.39 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L24 | 3615 Jackson Cabin Rd | 7/14/2008 | | 0.074 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L24 | 3615 Jackson Cabin Rd | 1/12/2009 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L24 | 3615 Jackson Cabin Rd | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-----------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P224L20 | 3616 Jackson Cabin Rd | 3/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L20 | 3616 Jackson Cabin Rd | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L20 | 3616 Jackson Cabin Rd | 6/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L20 | 3616 Jackson Cabin Rd | 8/29/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L20 | 3616 Jackson Cabin Rd | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L20 | 3616 Jackson Cabin Rd | 7/18/2007 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L20 | 3616 Jackson Cabin Rd | 1/15/2008 | | 0.096 J | ND(0.5) | 0.11 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L20 | 3616 Jackson Cabin Rd | 7/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L20 | 3616 Jackson Cabin Rd | 1/13/2009 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L20 | 3616 Jackson Cabin Rd | 7/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L23 | 3617 Jackson Cabin Rd | 6/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L23 | 3617 Jackson Cabin Rd | 8/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L23 | 3617 Jackson Cabin Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L23 | 3617 Jackson Cabin Rd | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L23 | 3617 Jackson Cabin Rd | 1/18/2008 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L23 | 3617 Jackson Cabin Rd | 7/18/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L23 | 3617 Jackson Cabin Rd | 1/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L23 | 3617 Jackson Cabin Rd | 7/16/2009 | | 0.094 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L21 | 3618 Jackson Cabin Rd | 3/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L21 | 3618 Jackson Cabin Rd | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L21 | 3618 Jackson Cabin Rd | 6/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L21 | 3618 Jackson Cabin Rd | 8/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L21 | 3618 Jackson Cabin Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L21 | 3618 Jackson Cabin Rd | 8/6/2007 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L21 | 3618 Jackson Cabin Rd | 1/14/2008 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L21 | 3618 Jackson Cabin Rd | 7/14/2008 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L21 | 3618 Jackson Cabin Rd | 1/7/2009 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
 14258 Jarrttsville Pike
 Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-----------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P224L21 | 3618 Jackson Cabin Rd | 7/8/2009 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L22 | 3620 Jackson Cabin Rd | 6/14/2006 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L22 | 3620 Jackson Cabin Rd | 8/15/2006 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L22 | 3620 Jackson Cabin Rd | 1/27/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L22 | 3620 Jackson Cabin Rd | 7/21/2007 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L22 | 3620 Jackson Cabin Rd | 1/14/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L22 | 3620 Jackson Cabin Rd | 7/15/2008 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L22 | 3620 Jackson Cabin Rd | 1/8/2009 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L22 | 3620 Jackson Cabin Rd | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L26 | 3103 Jackson Ridge Ct | 3/16/2006 | | ND(0.50) | ND(0.50) | 6.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L26 | 3103 Jackson Ridge Ct | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L26 | 3103 Jackson Ridge Ct | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L26 | 3103 Jackson Ridge Ct | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P024L26 | 3103 Jackson Ridge Ct | 7/17/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L26 | 3103 Jackson Ridge Ct | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L26 | 3103 Jackson Ridge Ct | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L05 | 3104 Jackson Ridge Ct | 3/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L05 | 3104 Jackson Ridge Ct | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L05 | 3104 Jackson Ridge Ct | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L05 | 3104 Jackson Ridge Ct | 1/22/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P024L05 | 3104 Jackson Ridge Ct | 7/17/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L05 | 3104 Jackson Ridge Ct | 1/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L05 | 3104 Jackson Ridge Ct | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L27 | 3105 Jackson Ridge Ct | 3/16/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L27 | 3105 Jackson Ridge Ct | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L27 | 3105 Jackson Ridge Ct | 7/19/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L27 | 3105 Jackson Ridge Ct | 1/15/2008 | | 0.17 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P024L27 | 3105 Jackson Ridge Ct | 7/22/2008 | | 0.12 J | ND(0.50) | 0.095 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L27 | 3105 Jackson Ridge Ct | 1/13/2009 | | 0.13 J | ND(0.50) | 0.058 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L27 | 3105 Jackson Ridge Ct | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L04 | 3106 Jackson Ridge Ct | 3/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L04 | 3106 Jackson Ridge Ct | 3/5/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L04 | 3106 Jackson Ridge Ct | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L04 | 3106 Jackson Ridge Ct | 7/23/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L04 | 3106 Jackson Ridge Ct | 1/16/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L04 | 3106 Jackson Ridge Ct | 7/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L03 | 3107 Jackson Ridge Ct | 3/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L03 | 3107 Jackson Ridge Ct | 2/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L03 | 3107 Jackson Ridge Ct | 8/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L03 | 3107 Jackson Ridge Ct | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P024L03 | 3107 Jackson Ridge Ct | 7/22/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L03 | 3107 Jackson Ridge Ct | 1/20/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L03 | 3107 Jackson Ridge Ct | 7/10/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P136LNA | 14021 Jarrettsville Pike | 3/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P025LNA | 14023 Jarrettsville Pike | 3/16/2006 | | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P138LNA | 14101 Jarrettsville Pike | 3/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P139LNA | 14103 Jarrettsville Pike | 3/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P144LNA | 14104 Jarrettsville Pike | 2/27/2006 | | 2.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.17 J | ND(5.0) |
| M43P144LNA | 14104 Jarrettsville Pike | 3/28/2006 | | 1.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P144LNA | 14104 Jarrettsville Pike | 4/25/2006 | | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.17 J | ND(5.0) |
| M43P144LNA | 14104 Jarrettsville Pike | 8/18/2006 | | 4.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.21 J | ND(5.0) |
| M43P144LNA | 14104 Jarrettsville Pike | 1/24/2007 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P144LNA | 14104 Jarrettsville Pike | 7/17/2007 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P144LNA | 14104 Jarrettsville Pike | 1/16/2008 | | 0.82 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M43P144LNA | 14104 Jarrettsville Pike | 7/17/2008 | | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P144LNA | 14104 Jarrettsville Pike | 1/14/2009 | | 0.96 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P144LNA | 14104 Jarrettsville Pike | 7/9/2009 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P142L02 | 14106 Jarrettsville Pike | 2/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P142L02 | 14106 Jarrettsville Pike | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P142L02 | 14106 Jarrettsville Pike | 4/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P142L02 | 14106 Jarrettsville Pike | 8/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P142L02 | 14106 Jarrettsville Pike | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P142L02 | 14106 Jarrettsville Pike | 7/16/2007 | | 0.11 J | ND(0.50) | 11.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P142L02 | 14106 Jarrettsville Pike | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M43P142L02 | 14106 Jarrettsville Pike | 7/18/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P142L02 | 14106 Jarrettsville Pike | 1/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P142L02 | 14106 Jarrettsville Pike | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P143L01 | 14108 Jarrettsville Pike | 2/25/2006 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P143L01 | 14108 Jarrettsville Pike | 3/27/2006 | | 0.92 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P143L01 | 14108 Jarrettsville Pike | 4/24/2006 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.11 J | ND(5.0) |
| M43P143L01 | 14108 Jarrettsville Pike | 8/18/2006 | | 0.73 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P143L01 | 14108 Jarrettsville Pike | 1/24/2007 | | 0.64 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P143L01 | 14108 Jarrettsville Pike | 7/20/2007 | | 0.56 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P143L01 | 14108 Jarrettsville Pike | 1/22/2008 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P143L01 | 14108 Jarrettsville Pike | 1/15/2009 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P143L01 | 14108 Jarrettsville Pike | 7/14/2009 | | 0.54 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P026LNA | 14110 Jarrettsville Pike | 2/24/2006 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P026LNA | 14110 Jarrettsville Pike | 3/27/2006 | | 2.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P026LNA | 14110 Jarrettsville Pike | 4/24/2006 | | 2.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P026LNA | 14110 Jarrettsville Pike | 8/22/2006 | | 3.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P026LNA | 14110 Jarrettsville Pike | 1/29/2007 | | 4.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M43P026LNA | 14110 Jarrettsville Pike | 7/16/2007 | | 12.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.26 J | ND(5.0) |
| M43P026LNA | 14110 Jarrettsville Pike | 1/21/2008 | | 10.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.20 J | ND(5.0) |
| M43P026LNA | 14110 Jarrettsville Pike | 7/17/2008 | | 8.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.13 J | ND(5.0) |
| M43P026LNA | 14110 Jarrettsville Pike | 1/8/2009 | | 6.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.12 J | ND(5.0) |
| M43P026LNA | 14110 Jarrettsville Pike | 7/9/2009 | | 7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.17 J | ND(5.0) |
| M43P005LNA | 14112 Jarrettsville Pike | 2/24/2006 | | 2.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P005LNA | 14112 Jarrettsville Pike | 3/25/2006 | | 3.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P005LNA | 14112 Jarrettsville Pike | 4/27/2006 | | 3.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P005LNA | 14112 Jarrettsville Pike | 8/17/2006 | | 3.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P005LNA | 14112 Jarrettsville Pike | 1/23/2007 | | 3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P005LNA | 14112 Jarrettsville Pike | 7/16/2007 | | 3.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P005LNA | 14112 Jarrettsville Pike | 1/15/2008 | | 1.4 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M43P005LNA | 14112 Jarrettsville Pike | 7/17/2008 | | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P005LNA | 14112 Jarrettsville Pike | 1/14/2009 | | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P005LNA | 14112 Jarrettsville Pike | 7/14/2009 | | 3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P275LNA | 14114 Jarrettsville Pike | 2/24/2006 | | 5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.19 J | ND(5.0) |
| M35P275LNA | 14114 Jarrettsville Pike | 3/25/2006 | | 3.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P275LNA | 14114 Jarrettsville Pike | 4/24/2006 | | 2.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P275LNA | 14114 Jarrettsville Pike | 8/21/2006 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P275LNA | 14114 Jarrettsville Pike | 1/24/2007 | | 2.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P275LNA | 14114 Jarrettsville Pike | 7/20/2007 | | 2.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P275LNA | 14114 Jarrettsville Pike | 1/18/2008 | | 4.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P275LNA | 14114 Jarrettsville Pike | 7/14/2008 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P275LNA | 14114 Jarrettsville Pike | 7/9/2009 | | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P160LNA | 14116 Jarrettsville Pike | 2/23/2006 | | 6.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.39 J | ND(5.0) |
| M35P160LNA | 14116 Jarrettsville Pike | 3/28/2006 | | 3.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P160LNA | 14116 Jarrettsville Pike | 4/24/2006 | | 4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.20 J | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P160LNA | 14116 Jarrettsville Pike | 8/28/2006 | | 2.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P160LNA | 14116 Jarrettsville Pike | 1/25/2007 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P160LNA | 14116 Jarrettsville Pike | 7/16/2007 | | 0.97 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P160LNA | 14116 Jarrettsville Pike | 1/21/2008 | | 3.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P160LNA | 14116 Jarrettsville Pike | 7/18/2008 | | 3.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P160LNA | 14116 Jarrettsville Pike | 1/14/2009 | | 2.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.13 J | ND(5.0) |
| M35P160LNA | 14116 Jarrettsville Pike | 7/14/2009 | | 3.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P159LNA | 14118 Jarrettsville Pike | 2/23/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P159LNA | 14118 Jarrettsville Pike | 3/27/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P159LNA | 14118 Jarrettsville Pike | 4/24/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P159LNA | 14118 Jarrettsville Pike | 8/15/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P159LNA | 14118 Jarrettsville Pike | 1/24/2007 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P159LNA | 14118 Jarrettsville Pike | 7/16/2007 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P159LNA | 14118 Jarrettsville Pike | 1/14/2008 | | 0.31 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P159LNA | 14118 Jarrettsville Pike | 7/15/2008 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P159LNA | 14118 Jarrettsville Pike | 1/14/2009 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P159LNA | 14118 Jarrettsville Pike | 7/9/2009 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P226LNA | 14202 Jarrettsville Pike | 2/24/2006 | | 0.65 | ND(0.50) | 0.84 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P226LNA | 14202 Jarrettsville Pike | 3/27/2006 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P226LNA | 14202 Jarrettsville Pike | 4/24/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P226LNA | 14202 Jarrettsville Pike | 6/12/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P226LNA | 14202 Jarrettsville Pike | 8/16/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P226LNA | 14202 Jarrettsville Pike | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P226LNA | 14202 Jarrettsville Pike | 4/10/2007 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P226LNA | 14202 Jarrettsville Pike | 7/18/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P226LNA | 14202 Jarrettsville Pike | 10/22/2007 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P226LNA | 14202 Jarrettsville Pike | 1/18/2008 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P226LNA | 14202 Jarrettsville Pike | 4/2/2008 | | 0.44 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P226LNA | 14202 Jarrettsville Pike | 7/15/2008 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P226LNA | 14202 Jarrettsville Pike | 10/8/2008 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P226LNA | 14202 Jarrettsville Pike | 1/14/2009 | | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P226LNA | 14202 Jarrettsville Pike | 4/2/2009 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P226LNA | 14202 Jarrettsville Pike | 7/15/2009 | | 0.45 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P226LNA | 14202 Jarrettsville Pike | 10/9/2009 | | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P286LNA01 | 14209 Jarrettsville Pike | 3/20/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P286LNA01 | 14209 Jarrettsville Pike | 3/22/2006 | | ND(0.50) | ND(0.50) | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P282LNA | 14212 Jarrettsville Pike | 3/3/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P282LNA | 14212 Jarrettsville Pike | 3/27/2006 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P282LNA | 14212 Jarrettsville Pike | 4/24/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P282LNA | 14212 Jarrettsville Pike | 6/12/2006 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P282LNA | 14212 Jarrettsville Pike | 8/16/2006 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P282LNA | 14212 Jarrettsville Pike | 1/25/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P282LNA | 14212 Jarrettsville Pike | 4/10/2007 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P282LNA | 14212 Jarrettsville Pike | 7/17/2007 | | 0.17 J | ND(0.50) | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P282LNA | 14212 Jarrettsville Pike | 10/22/2007 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P282LNA | 14212 Jarrettsville Pike | 1/17/2008 | | 0.37 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P282LNA | 14212 Jarrettsville Pike | 4/2/2008 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P282LNA | 14212 Jarrettsville Pike | 7/15/2008 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P282LNA | 14212 Jarrettsville Pike | 10/8/2008 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P282LNA | 14212 Jarrettsville Pike | 1/14/2009 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P282LNA | 14212 Jarrettsville Pike | 4/1/2009 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P201LNA | 14214 Jarrettsville Pike | 2/25/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P201LNA | 14214 Jarrettsville Pike | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P201LNA | 14214 Jarrettsville Pike | 4/24/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrettsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P201LNA | 14214 Jarrettsville Pike | 6/12/2006 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P201LNA | 14214 Jarrettsville Pike | 8/16/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P201LNA | 14214 Jarrettsville Pike | 1/25/2007 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P201LNA | 14214 Jarrettsville Pike | 4/10/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P201LNA | 14214 Jarrettsville Pike | 7/17/2007 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P201LNA | 14214 Jarrettsville Pike | 10/22/2007 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P201LNA | 14214 Jarrettsville Pike | 1/17/2008 | | 0.068 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P201LNA | 14214 Jarrettsville Pike | 4/2/2008 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P201LNA | 14214 Jarrettsville Pike | 7/15/2008 | | 0.079 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P201LNA | 14214 Jarrettsville Pike | 10/8/2008 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P201LNA | 14214 Jarrettsville Pike | 1/14/2009 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P201LNA | 14214 Jarrettsville Pike | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P201LNA | 14214 Jarrettsville Pike | 7/9/2009 | | 0.095 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P201LNA | 14214 Jarrettsville Pike | 10/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P218LNA | 14227 Jarrettsville Pike | 3/18/2006 | | 3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P218LNA | 14227 Jarrettsville Pike | 6/27/2006 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P285LNA | 14228 Jarrettsville Pike | 2/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P285LNA | 14228 Jarrettsville Pike | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P285LNA | 14228 Jarrettsville Pike | 4/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P285LNA | 14228 Jarrettsville Pike | 6/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P285LNA | 14228 Jarrettsville Pike | 8/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P285LNA | 14228 Jarrettsville Pike | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P285LNA | 14228 Jarrettsville Pike | 4/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P285LNA | 14228 Jarrettsville Pike | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P285LNA | 14228 Jarrettsville Pike | 10/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P285LNA | 14228 Jarrettsville Pike | 1/17/2008 | | 0.096 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P285LNA | 14228 Jarrettsville Pike | 4/2/2008 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P285LNA | 14228 Jarrettsville Pike | 7/15/2008 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P285LNA | 14228 Jarrettsville Pike | 10/9/2008 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P285LNA | 14228 Jarrettsville Pike | 1/14/2009 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P285LNA | 14228 Jarrettsville Pike | 4/1/2009 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P285LNA | 14228 Jarrettsville Pike | 7/9/2009 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P285LNA | 14228 Jarrettsville Pike | 10/7/2009 | | 0.47 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P208LNA | 14231 Jarrettsville Pike | 3/15/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P210LNA | 14232 Jarrettsville Pike | 2/23/2006 | | 0.93 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P210LNA | 14232 Jarrettsville Pike | 3/27/2006 | | 0.71 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P210LNA | 14232 Jarrettsville Pike | 4/24/2006 | | 0.67 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P210LNA | 14232 Jarrettsville Pike | 6/12/2006 | | 0.69 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P210LNA | 14232 Jarrettsville Pike | 8/17/2006 | | 0.66 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P210LNA | 14232 Jarrettsville Pike | 1/25/2007 | | 0.55 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P210LNA | 14232 Jarrettsville Pike | 4/9/2007 | | 0.61 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P210LNA | 14232 Jarrettsville Pike | 7/17/2007 | | 0.52 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P210LNA | 14232 Jarrettsville Pike | 10/22/2007 | | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P210LNA | 14232 Jarrettsville Pike | 1/17/2008 | | 0.3 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P210LNA | 14232 Jarrettsville Pike | 4/2/2008 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P210LNA | 14232 Jarrettsville Pike | 7/15/2008 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P210LNA | 14232 Jarrettsville Pike | 10/8/2008 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P210LNA | 14232 Jarrettsville Pike | 1/14/2009 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P210LNA | 14232 Jarrettsville Pike | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P210LNA | 14232 Jarrettsville Pike | 7/8/2009 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P210LNA | 14232 Jarrettsville Pike | 10/7/2009 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P203LNA01 | 14237 Jarrettsville Pike | 3/15/2006 | | 0.44 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P203LNA02 | 14237 Jarrettsville Pike | 3/15/2006 | | 0.68 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 2/23/2006 | PIO | 504 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.34 J | 74.6 | 1.4 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P182LNA | 14240 Jarrettsville Pike | 3/3/2006 | PEO | 35.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.17 J | ND(0.50) | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 3/3/2006 | PIO | 443 | ND(5.0) | ND(5.0) | ND(5.0) | ND(5.0) | ND(5.0) | ND(5.0) | 68.5 | ND(5.0) | ND(50) |
| M35P182LNA | 14240 Jarrettsville Pike | 3/3/2006 | PMO | 337 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 20.5 | 0.26 J | 3.1 J |
| M35P182LNA | 14240 Jarrettsville Pike | 3/10/2006 | PEO | 82.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.51 | ND(0.50) | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 3/10/2006 | PIO | 499 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.40 J | 83.2 | 1.5 | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 3/10/2006 | PMO | 413 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 32 | 0.38 J | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 3/17/2006 | PIO | 463 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 85.3 | 1.7 | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 4/24/2006 | PIO | 508 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.42 J | 90.9 | 2 | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 6/13/2006 | PIO | 319 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.37 J | 44.1 | 1.4 | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 8/17/2006 | PIO | 370 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.32 J | 51.6 | 1.6 | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 1/25/2007 | PIO | 383 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.43 J | 43.8 | 2.2 | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 4/10/2007 | PIO | 656 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.73 | 67.8 | 3.8 | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 7/17/2007 | PIO | 259 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.31 J | 28.1 | 1.5 | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 10/22/2007 | PIO | 266 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 23.5 | 1.4 | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 1/17/2008 | PIO | 273 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 26.6 | 1.5 | 5.5 |
| M35P182LNA | 14240 Jarrettsville Pike | 4/4/2008 | PIO | 429 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 39.4 | 2.6 | ND(5) |
| M35P182LNA | 14240 Jarrettsville Pike | 7/17/2008 | PIO | 344 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 25.1 | 1.4 | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 10/9/2008 | PIO | 155 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 11.9 | 0.8 | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 1/5/2009 | PIO | 90.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 8.5 | 0.43 J | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 1/14/2009 | PIO | 156 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 13.6 | 0.73 | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 4/1/2009 | PIO | 41.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.6 | 0.12 J | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 7/8/2009 | PIO | 56.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.9 | 0.13 J | ND(5.0) |
| M35P182LNA | 14240 Jarrettsville Pike | 10/7/2009 | PIO | 58 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.9 | 0.23 J | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 2/20/2006 | PIO | 43 | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 13.2 | 0.30 J | 6.5 |
| M35P183LNA | 14242 Jarrettsville Pike | 2/27/2006 | PIO | 1160 | 4.5 | 3.9 | 0.12 J | 0.48 J | 0.26 J | 2.5 | 29.9 | 18.5 | 18.7 |
| M35P183LNA | 14242 Jarrettsville Pike | 3/1/2006 | PEO | 117 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.99 | ND(0.50) | 8 |
| M35P183LNA | 14242 Jarrettsville Pike | 3/1/2006 | PIO | 1470 | 0.32 J | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | 3.6 | 31.7 | 19.4 | 2.9 J |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P183LNA | 14242 Jarrettsville Pike | 3/8/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/8/2006 | PI | 4610 | 16.2 | 18 | 0.46 J | 1.5 | ND(0.50) | 14.9 | 56.4 J | 99.6 J | 12.5 |
| M35P183LNA | 14242 Jarrettsville Pike | 3/8/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/16/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/16/2006 | PI | 3050 | 12.3 | 14.8 | ND(5.0) | 1.0 J | ND(5.0) | 7.8 | 50.9 | 66.1 | 18.5 J |
| M35P183LNA | 14242 Jarrettsville Pike | 3/16/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/22/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/22/2006 | PI | 793 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2 | 36.1 | 4.7 | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/22/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/29/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/29/2006 | PI | 476 | 0.61 | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | 1.3 | 33.1 | 6.3 | 9.8 |
| M35P183LNA | 14242 Jarrettsville Pike | 3/29/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/5/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/5/2006 | PI | 257 | ND(1.0) | ND(1.0) | ND(1.0) | ND(1.0) | ND(1.0) | 0.50 J | 25.3 | 1.8 | ND(10) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/5/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/12/2006 | PI | 124 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 15.6 | 0.23 J | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/12/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/19/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/19/2006 | PI | 98 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 16.4 | 0.23 J | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/19/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/26/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/26/2006 | PI | 90.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 18.4 | 0.19 J | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/26/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/2/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/2/2006 | PI | 178 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.38 J | 23.1 | 1.9 | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/2/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P183LNA | 14242 Jarrettsville Pike | 5/8/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/8/2006 | PI | 90.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.15 J | 20.9 | 0.52 | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/8/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/15/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/15/2006 | PI | 51.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 22.5 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/15/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/22/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/22/2006 | PI | 50.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 21.5 | 0.13 J | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/22/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/31/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/31/2006 | PI | 35.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 20.1 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/31/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/5/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/5/2006 | PI | 22.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 17 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/5/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/12/2006 | PI | 16.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 18.6 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/12/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/19/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/19/2006 | PI | 15.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 15.2 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/19/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/26/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/26/2006 | PI | 12.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 15.6 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/26/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/5/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/5/2006 | PI | 22.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 19.2 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/5/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P183LNA | 14242 Jarrettsville Pike | 7/10/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/10/2006 | PI | 15.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 15.7 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/10/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/17/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/17/2006 | PI | 13.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 15 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/17/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/31/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/31/2006 | PI | 9.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 11.5 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/31/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/7/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/7/2006 | PI | 7.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 9.5 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/7/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/14/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/14/2006 | PI | 8.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 13.9 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/14/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/21/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/21/2006 | PI | 6.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 10.6 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/21/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/28/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/28/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/28/2006 | PM2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 9/6/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 9/6/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 9/6/2006 | PM2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 9/11/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 9/11/2006 | PI | 3.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 10.8 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 9/11/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P183LNA | 14242 Jarrettsville Pike | 9/18/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 9/18/2006 | PI | 3.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 10 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 9/18/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 9/25/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 9/25/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 9/25/2006 | PM2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/2/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/2/2006 | PI | 3.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 7.1 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/2/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.1 J |
| M35P183LNA | 14242 Jarrettsville Pike | 10/9/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/9/2006 | PI | 3.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 7.3 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/9/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/16/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/16/2006 | PI | 3.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 6.9 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/16/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.1 J |
| M35P183LNA | 14242 Jarrettsville Pike | 10/24/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/24/2006 | PI | 2.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.1 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/24/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/30/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/30/2006 | PI | 3.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 7.9 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/30/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.0 J |
| M35P183LNA | 14242 Jarrettsville Pike | 11/6/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/6/2006 | PI | 2.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.9 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/6/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/13/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/13/2006 | PI | 2.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.9 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/13/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.9 J |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P183LNA | 14242 Jarrettsville Pike | 11/20/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/20/2006 | PI | 2.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.1 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/20/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/27/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/27/2006 | PI | 0.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.3 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/27/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 12/4/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 12/4/2006 | PI | 3.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.9 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 12/4/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 12/11/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 12/11/2006 | PI | 3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.9 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 12/11/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 12/18/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 12/18/2006 | PI | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.2 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 12/18/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 1/8/2007 | PE | ND(2.5) | ND(2.5) | ND(2.5) | ND(2.5) | ND(2.5) | ND(2.5) | ND(2.5) | ND(2.5) | ND(2.5) | ND(25) |
| M35P183LNA | 14242 Jarrettsville Pike | 1/8/2007 | PI | 27.9 | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.12 J | 6.6 | 0.29 J | 12.9 |
| M35P183LNA | 14242 Jarrettsville Pike | 1/8/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 1/22/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 1/22/2007 | PI | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.6 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 1/22/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 2/5/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 2/5/2007 | PI | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.96 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 2/5/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/5/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/5/2007 | PI | 16.2 | ND(0.50) | 2 | ND(0.50) | ND(0.50) | ND(0.50) | 0.15 J | 8.8 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/5/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrettsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P183LNA | 14242 Jarrettsville Pike | 3/19/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/19/2007 | PI | 19.7 | ND(0.50) | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 8.1 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/19/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/2/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/2/2007 | PI | 24.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.17 J | 7.5 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/2/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/16/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/16/2007 | PI | 21.5 | ND(0.50) | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | 0.18 J | 6.7 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/16/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/30/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/30/2007 | PI | 35.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 7 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/30/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/14/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/14/2007 | PI | 16.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.8 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/14/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/30/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/30/2007 | PI | 6.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.5 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/30/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/11/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/11/2007 | PI | 3.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.64 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/11/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/25/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/25/2007 | PI | 3.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.6 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/25/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/9/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/9/2007 | PI | 3.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.65 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/9/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P183LNA | 14242 Jarrettsville Pike | 7/23/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/23/2007 | PI | 2.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.46 J | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/23/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/6/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/6/2007 | PI | 2.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.5 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/6/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/20/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/20/2007 | PI | 3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.54 | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/20/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 9/4/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 9/4/2007 | PI | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 9/4/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/1/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/1/2007 | PI | 1.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/1/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/15/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/15/2007 | PI | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/15/2007 | PM | 0.099 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/30/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/30/2007 | PI | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/30/2007 | PM | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/12/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/12/2007 | PI | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/12/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/26/2007 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/26/2007 | PI | 1.2 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/26/2007 | PM | 0.091 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P183LNA | 14242 Jarrettsville Pike | 12/10/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 12/10/2007 | PI | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 12/10/2007 | PM | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 1/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 1/8/2008 | PI | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 1/8/2008 | PM | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 2/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 2/4/2008 | PI | 0.73 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 2/4/2008 | PM | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/3/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/3/2008 | PI | 0.74 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/3/2008 | PM | 0.37 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/7/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/7/2008 | PI | 0.53 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/7/2008 | PM | 0.52 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/5/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/5/2008 | PI | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/5/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/2/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/2/2008 | PI | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/2/2008 | PM | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/10/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/10/2008 | PI | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 7/10/2008 | PM | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/4/2008 | PI | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/4/2008 | PM | 0.99 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P183LNA | 14242 Jarrettsville Pike | 9/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 9/8/2008 | PI | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 9/8/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/16/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/16/2008 | PI | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/16/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/3/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/3/2008 | PI | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/3/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 12/1/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 12/1/2008 | PI | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 12/1/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 1/5/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 1/5/2009 | PI | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 1/5/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 2/2/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 2/2/2009 | PI | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 2/2/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/9/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/9/2009 | PI | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 3/9/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/6/2009 | PI | 0.84 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 4/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/4/2009 | PI | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 5/4/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P183LNA | 14242 Jarrettsville Pike | 6/1/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/1/2009 | PI | 0.095 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/1/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/30/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/30/2009 | PI | 0.099 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 6/30/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/17/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/17/2009 | PI | 0.16 J | ND(0.50) | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/17/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/31/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/31/2009 | PI | 0.11 J | ND(0.50) | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 8/31/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/12/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/12/2009 | PI | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 10/12/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/2/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/2/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 11/2/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 12/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 12/7/2009 | PI | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P183LNA | 14242 Jarrettsville Pike | 12/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 3/17/2006 | PIO | 25.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 3/24/2006 | PIO | 29.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 3/31/2006 | PIO | 123 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.15 J | ND(0.50) | 0.77 | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 4/6/2006 | PIO | 39.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 4/14/2006 | PIO | 24.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 4/21/2006 | PIO | 36.7 | 0.28 J | 1.1 | ND(0.50) | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P217LNA | 14243 Jarrettsville Pike | 4/28/2006 | PIO | 16.4 | 0.10 J | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 5/1/2006 | PIO | 27 | ND(0.50) | 0.30 J | ND(0.50) | 0.069 J | ND(0.50) | ND(0.50) | ND(0.50) | 0.18 J | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 5/8/2006 | PIO | 14.6 | ND(0.50) | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 5/15/2006 | PIO | 8.3 | ND(0.50) | 0.35 J | ND(0.50) | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 5/22/2006 | PIO | 16.5 | ND(0.50) | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 5/31/2006 | PIO | 6.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 6/5/2006 | PIO | 24.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.16 J | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 6/12/2006 | PIO | 6.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 6/19/2006 | PIO | 4.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 6/26/2006 | PIO | 3.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 7/5/2006 | PIO | 4.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 7/10/2006 | PIO | 8.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 7/17/2006 | PIO | 5.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 7/24/2006 | PIO | 3.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 7/31/2006 | PIO | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 8/7/2006 | PIO | 20.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 8/14/2006 | PIO | 14 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 8/21/2006 | PIO | 8.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 8/28/2006 | PIO | 5.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 9/5/2006 | PIO | 5.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 9/11/2006 | PIO | 4.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 9/18/2006 | PIO | 4.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 9/25/2006 | PIO | 3.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 10/2/2006 | PIO | 2.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 10/9/2006 | PIO | 3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 10/16/2006 | PIO | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 10/23/2006 | PIO | 2.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P217LNA | 14243 Jarrettsville Pike | 10/30/2006 | PIO | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 11/6/2006 | PIO | 2.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 11/14/2006 | PIO | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 11/20/2006 | PIO | 2.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 11/27/2006 | PIO | 2.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 12/4/2006 | PIO | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 12/11/2006 | PIO | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 12/18/2006 | PIO | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 1/8/2007 | PIO | 1.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 1/22/2007 | PIO | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 2/5/2007 | PIO | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 2/21/2007 | PIO | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 3/5/2007 | PIO | 0.83 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 3/19/2007 | PIO | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 4/2/2007 | PIO | 0.81 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 4/16/2007 | PIO | 0.66 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 4/30/2007 | PIO | 0.95 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 5/14/2007 | PIO | 0.76 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 5/30/2007 | PIO | 2.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 6/11/2007 | PIO | 0.89 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 6/25/2007 | PIO | 0.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 7/9/2007 | PIO | 0.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 7/23/2007 | PIO | 10.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 8/6/2007 | PIO | 2.8 | ND(0.50) | 0.051 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 8/20/2007 | PIO | 2.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 9/5/2007 | PIO | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 9/17/2007 | PIO | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P217LNA | 14243 Jarrettsville Pike | 10/1/2007 | PIO | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 10/15/2007 | PIO | 0.86 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 10/29/2007 | PIO | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 11/12/2007 | PIO | 0.77 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 1/7/2008 | PIO | 1.5 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P217LNA | 14243 Jarrettsville Pike | 2/4/2008 | PIO | 1.4 | ND(0.50) | 0.068 J | ND(0.50) | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 3/3/2008 | PIO | 1.2 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P217LNA | 14243 Jarrettsville Pike | 4/7/2008 | PIO | 1.1 | ND(0.50) | 0.068 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 5/5/2008 | PIO | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 6/2/2008 | PIO | 0.47 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P217LNA | 14243 Jarrettsville Pike | 7/7/2008 | PIO | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 8/4/2008 | PIO | 0.62 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 9/8/2008 | PIO | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 10/6/2008 | PIO | 0.61 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 11/3/2008 | PIO | 0.53 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 12/1/2008 | PIO | 0.48 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 1/6/2009 | PIO | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 2/3/2009 | PIO | 0.51 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 3/4/2009 | PIO | 0.46 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 4/6/2009 | PIO | 0.84 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 5/4/2009 | PIO | 0.48 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 6/1/2009 | PIO | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 7/6/2009 | PIO | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 8/3/2009 | PIO | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 8/31/2009 | PIO | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 10/5/2009 | PIO | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P217LNA | 14243 Jarrettsville Pike | 11/2/2009 | PIO | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrettsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P217LNA | 14243 Jarrettsville Pike | 12/7/2009 | PIO | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 4/3/2006 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 4/10/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 4/17/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 4/24/2006 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 5/1/2006 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 5/8/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 5/15/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 5/22/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 6/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 6/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 6/29/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 8/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 11/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 12/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 1/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.1 |
| M35P185LNA | 14258 Jarrettsville Pike | 2/28/2007 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 3/16/2007 | | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 4/12/2007 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 7/25/2007 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 8/23/2007 | | 0.75 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 9/17/2007 | | 0.69 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 10/15/2007 | | 0.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 12/5/2007 | | 1.1 | ND(1.0) | ND(1.0) | ND(1.0) | ND(1.0) | NA | ND(5.0) | ND(5.0) | ND(5.0) | ND(25) |
| M35P185LNA | 14258 Jarrettsville Pike | 1/11/2008 | | 0.51 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 2/20/2008 | | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrettsville Pike
Phoenix, MD

| Map/Parcel/Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethylbenzene (µg/L) | Total Xylenes (µg/L) | Naphthalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|----------------|--------------------------|-------------|-------------------|-------------|----------------|----------------|---------------------|----------------------|--------------------|-------------|-------------|-------------|------------|
| M35P185LNA | 14258 Jarrettsville Pike | 5/20/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 8/14/2008 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 12/10/2008 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 3/9/2009 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 6/18/2009 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P185LNA | 14258 Jarrettsville Pike | 9/22/2009 | | ND(1.0) | NA | NA | NA | NA | NA | ND(5.0) | ND(5.0) | ND(5.0) | ND(25) |
| M35P185LNA | 14258 Jarrettsville Pike | 12/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 3/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 10/1/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 10/15/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 10/29/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 11/13/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 12/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 1/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 2/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 3/3/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 4/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 5/5/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 6/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 7/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 8/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 9/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 10/6/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 11/3/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 12/1/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 1/5/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 2/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethylbenzene (µg/L) | Total Xylenes (µg/L) | Naphthalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|----------------|--------------------------|-------------|-------------------|-------------|----------------|----------------|---------------------|----------------------|--------------------|-------------|-------------|-------------|------------|
| M35P123LNAJ | 14300 Jarrettsville Pike | 3/4/2009 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 4/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 5/4/2009 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 6/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 7/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 8/3/2009 | | 0.082 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 8/31/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 10/5/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 11/2/2009 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAJ | 14300 Jarrettsville Pike | 12/7/2009 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 3/3/2006 | PEO | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 34 |
| M35P031LNA | 14301 Jarrettsville Pike | 3/3/2006 | PIO | 773000 | 5380 | 10500 | 814 | 1950 | ND(250) | 1330 | 5220 | 19600 | ND(2500) |
| M35P031LNA | 14301 Jarrettsville Pike | 3/3/2006 | PMO | 566000 | ND(500) | ND(500) | ND(500) | ND(500) | ND(500) | ND(500) | ND(500) | ND(500) | ND(5000) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/6/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/6/2006 | PI | 114 | ND(0.50) | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 10.3 | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/6/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/12/2006 | PI | 183 | ND(0.50) | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 14.7 | 0.24 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/12/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/18/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/18/2006 | PI | 178 | ND(0.50) | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 16.7 | 0.26 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/18/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/26/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/26/2006 | PI | 167 | ND(0.50) | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 16.7 | 0.24 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/26/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/3/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/3/2006 | PI | 197 | ND(0.50) | 0.094 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 18.3 | 0.24 J | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P031LNA | 14301 Jarrettsville Pike | 10/3/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/10/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/10/2006 | PI | 162 | ND(0.50) | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 13 | 0.26 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/10/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/16/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/16/2006 | PI | 152 | ND(0.50) | 0.097 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 12.6 | 0.22 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/16/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/23/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/23/2006 | PI | 155 | ND(0.50) | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 13.3 | 0.26 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/23/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/31/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/31/2006 | PI | 128 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 10.5 | 0.22 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/31/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/7/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/7/2006 | PI | 174 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 14.4 | 0.26 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/7/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/13/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/13/2006 | PI | 181 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 12.8 | 0.23 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/13/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/21/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/21/2006 | PI | 111 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 8.3 | 0.17 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/21/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/28/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/28/2006 | PI | 102 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 8 | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/28/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 12/4/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 12/4/2006 | PI | 122 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 11.1 | 0.20 J | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P031LNA | 14301 Jarrettsville Pike | 12/4/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 12/12/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 12/12/2006 | PI | 78 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 6.5 | 0.17 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 12/12/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 12/18/2006 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 12/18/2006 | PI | 78.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.8 | 0.16 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 12/18/2006 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 1/8/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 1/8/2007 | PI | 95.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.5 | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 1/8/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 1/22/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 1/22/2007 | PI | 77.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.4 | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 1/22/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 2/5/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 2/5/2007 | PI | 108 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 8.8 | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 2/5/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 2/21/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 2/21/2007 | PI | 112 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 6.8 | 0.18 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 2/21/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 3/5/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 3/5/2007 | PI | 99.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 6.8 | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 3/5/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 3/19/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 3/19/2007 | PI | 112 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 8.5 | 0.16 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 3/19/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 4/2/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 4/2/2007 | PI | 99.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 6 | 0.19 J | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P031LNA | 14301 Jarrettsville Pike | 4/2/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 4/16/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 4/16/2007 | PI | 86.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 6.5 | 0.16 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 4/16/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 4/30/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 4/30/2007 | PI | 97.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 7.2 | 0.15 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 4/30/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 5/14/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 5/14/2007 | PI | 96.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.9 | 0.12 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 5/14/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 5/30/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 5/30/2007 | PI | 63.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.8 | 0.11 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 5/30/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 6/11/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 6/11/2007 | PI | 0.23 J | ND(0.50) | 0.26 J | ND(0.50) | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 6/11/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 6/25/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 6/25/2007 | PI | 70.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.3 | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 6/25/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 7/9/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 7/9/2007 | PI | 71.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.7 | 0.068 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 7/9/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 7/23/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 7/23/2007 | PI | 61.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.5 | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 7/23/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 8/6/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 8/6/2007 | PI | 75.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.6 | 0.12 J | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P031LNA | 14301 Jarrettsville Pike | 8/6/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 8/20/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 8/20/2007 | PI | 99.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 6.6 | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 8/20/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/5/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/5/2007 | PI | 71.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.2 | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/5/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/17/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/17/2007 | PI | 90 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 6.7 | 0.14 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/17/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/2/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/2/2007 | PI | 99.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 7.4 | 0.20 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/2/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/15/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/15/2007 | PI | 93.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 6.8 | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/15/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/29/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/29/2007 | PI | 78.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.7 | 0.15 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/29/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/13/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/13/2007 | PI | 102 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 7.5 | 0.19 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/13/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/26/2007 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/26/2007 | PI | 73.9 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 5.9 | 0.16 J | ND(5) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/26/2007 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P031LNA | 14301 Jarrettsville Pike | 12/10/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 12/10/2007 | PI | 92.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.8 | 0.18 J | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrettsville Pike
Phoenix, MD

| Map/Parcel/Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethylbenzene (µg/L) | Total Xylenes (µg/L) | Naphthalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|----------------|--------------------------|-------------|-------------------|-------------|----------------|----------------|---------------------|----------------------|--------------------|-------------|-------------|-------------|------------|
| M35P031LNA | 14301 Jarrettsville Pike | 12/10/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 1/7/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P031LNA | 14301 Jarrettsville Pike | 1/7/2008 | PI | 102 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 4.9 | 0.17 J | ND(5) |
| M35P031LNA | 14301 Jarrettsville Pike | 1/7/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P031LNA | 14301 Jarrettsville Pike | 2/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 2/4/2008 | PI | 165 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 29.4 | 0.87 | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 2/4/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 3/3/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P031LNA | 14301 Jarrettsville Pike | 3/3/2008 | PI | 218 a | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 37.8 | 1.1 | ND(5) |
| M35P031LNA | 14301 Jarrettsville Pike | 3/3/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P031LNA | 14301 Jarrettsville Pike | 4/7/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 4/7/2008 | PI | 212 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 38.8 | 1.2 | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 4/7/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 5/5/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 5/5/2008 | PI | 133 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 14.9 | 0.49 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 5/5/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 6/2/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 6/2/2008 | PI | 91.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.3 | 0.18 J | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 6/2/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 7/7/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 7/7/2008 | PI | 67.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.4 | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 7/7/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 8/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 8/4/2008 | PI | 86.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.7 | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 8/4/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 9/8/2008 | PI | 52.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.58 | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P031LNA | 14301 Jarrettsville Pike | 9/8/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/6/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/6/2008 | PI | 54.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.89 | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/6/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/3/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/3/2008 | PI | 48.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.57 | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/3/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 12/1/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 12/1/2008 | PI | 21.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 12/1/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 1/5/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 1/5/2009 | PI | 21.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 1/5/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 2/2/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 2/2/2009 | PI | 40.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.54 | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 2/2/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 2/10/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 2/10/2009 | PI | 36.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.78 | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 2/10/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 3/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 3/4/2009 | PI | 37.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.82 | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 3/4/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 4/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 4/6/2009 | PI | 39.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.9 | ND(0.50) | 6.2 |
| M35P031LNA | 14301 Jarrettsville Pike | 4/6/2009 | PM | ND(0.50) | ND(0.50) | 0.079 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 5/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 5/4/2009 | PI | 38.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.2 | 0.14 J | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P031LNA | 14301 Jarrettsville Pike | 5/4/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 6/1/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 6/1/2009 | PI | 32.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.2 | 0.22 J | 5.8 |
| M35P031LNA | 14301 Jarrettsville Pike | 6/1/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 7/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 7/6/2009 | PI | 8.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.16 J | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 7/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 8/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 8/3/2009 | PI | 8.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 8/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 8/31/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 8/31/2009 | PI | 24 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 8/31/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/5/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/5/2009 | PI | 31.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.13 J | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 10/5/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/2/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/2/2009 | PI | 18.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 11/2/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 12/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 12/7/2009 | PI | 13.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P031LNA | 14301 Jarrettsville Pike | 12/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 2/24/2006 | PEO | 0.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 3/3/2006 | | 0.55 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 3/13/2006 | PE | 0.85 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 3/20/2006 | | ND(5.0) | ND(5.0) | ND(5.0) | ND(5.0) | ND(5.0) | ND(5.0) | ND(5.0) | ND(5.0) | ND(5.0) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 3/27/2006 | | 0.72 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P151LNA | 14307 Jarrettsville Pike | 4/3/2006 | | 0.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 4/10/2006 | | 0.86 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 4/17/2006 | | 0.85 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 4/24/2006 | | 0.64 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 5/1/2006 | | 0.83 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 5/8/2006 | | 0.78 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 5/15/2006 | | 0.61 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 5/22/2006 | | 0.79 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 5/31/2006 | | 0.55 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 6/5/2006 | | 0.77 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 6/12/2006 | | 0.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 6/19/2006 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.13 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 6/26/2006 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.14 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 7/5/2006 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 7/10/2006 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 7/17/2006 | | 0.83 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 7/24/2006 | | 0.98 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 7/31/2006 | | 0.94 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 8/14/2006 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 8/21/2006 | | 0.99 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 8/28/2006 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.18 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 9/5/2006 | | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.18 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 9/11/2006 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.21 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 9/18/2006 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.16 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 9/25/2006 | | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/2/2006 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.22 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/9/2006 | | 29.2 | 0.69 | 0.24 J | ND(0.50) | 0.34 J | ND(0.50) | ND(0.50) | 0.28 J | 1.6 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P151LNA | 14307 Jarrettsville Pike | 10/16/2006 | | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.21 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/23/2006 | | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.23 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/30/2006 | | 2.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.29 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/6/2006 | | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.18 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/13/2006 | | 3.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.32 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/20/2006 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.36 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/27/2006 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.21 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 12/4/2006 | | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.33 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 12/11/2006 | | 2.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.40 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 12/18/2006 | | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.34 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 1/8/2007 | | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.20 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 1/22/2007 | | 2.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.23 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 2/6/2007 | | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.14 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 2/21/2007 | | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.22 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 3/5/2007 | | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.17 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 3/19/2007 | | 4.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.29 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 4/2/2007 | | 4.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.28 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 4/16/2007 | | 4.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.27 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 4/30/2007 | | 5.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.20 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 5/14/2007 | | 6.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.23 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 5/30/2007 | | 3.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.17 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 6/11/2007 | | 10 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.28 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 6/25/2007 | | 16.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.40 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 7/9/2007 | | 17.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.33 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 7/16/2007 | | 21.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.34 J | 0.65 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 7/16/2007 | PE | 21.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.36 J | 0.65 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 7/23/2007 | | 23.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.34 J | 0.57 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P151LNA | 14307 Jarrettsville Pike | 8/6/2007 | | 24.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.37 J | 0.62 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 8/20/2007 | PE | ND(0.50) | ND(0.50) | 0.057 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 8/20/2007 | PI | 33.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.48 J | 0.71 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 8/20/2007 | PM | ND(0.50) | ND(0.50) | 0.046 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 9/5/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 9/5/2007 | PI | 34.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.47 J | 0.56 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 9/5/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 9/17/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 9/17/2007 | PI | 33.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.5 | 0.55 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 9/17/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/2/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/2/2007 | PI | 36.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.46 J | 0.61 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/2/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/16/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/16/2007 | PI | 82.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.36 J | 1.2 | 2.4 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/16/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/29/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/29/2007 | PI | 65.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.82 | 1 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/29/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/12/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/12/2007 | PI | 77.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.39 J | 1.1 | 1.9 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/12/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/26/2007 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/26/2007 | PI | 72.5 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.37 J | 0.99 | 1.6 | ND(5) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/26/2007 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P151LNA | 14307 Jarrettsville Pike | 12/10/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 12/10/2007 | PI | 94 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.51 | 1.3 | 2.7 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P151LNA | 14307 Jarrettsville Pike | 12/10/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 1/7/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P151LNA | 14307 Jarrettsville Pike | 1/7/2008 | PI | 100 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.6 | 1.6 | 2.4 | ND(5) |
| M35P151LNA | 14307 Jarrettsville Pike | 1/7/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P151LNA | 14307 Jarrettsville Pike | 2/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 2/4/2008 | PI | 128 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.98 | 2.4 | 3.4 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 2/4/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 3/3/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P151LNA | 14307 Jarrettsville Pike | 3/3/2008 | PI | 116 a | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.85 | 2.2 | 2.4 | ND(5) |
| M35P151LNA | 14307 Jarrettsville Pike | 3/3/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P151LNA | 14307 Jarrettsville Pike | 4/7/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 4/7/2008 | PI | 126 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1 | 2.8 | 2.2 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 4/7/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 5/5/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 5/5/2008 | PI | 257 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.9 | 4.4 | 8.1 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 5/5/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 6/2/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 6/2/2008 | PI | 199 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.1 | 2.9 | 5.8 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 6/2/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 7/7/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 7/7/2008 | PI | 185 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.4 | 3.6 | 5.5 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 7/7/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 8/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 8/4/2008 | PI | 216 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.3 | 4.3 | 7.2 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 8/4/2008 | PM | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 9/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 9/8/2008 | PI | 228 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.2 | 3.6 | 6.1 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P151LNA | 14307 Jarrettsville Pike | 9/8/2008 | PM | 4.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/6/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/6/2008 | PI | 275 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.9 | 5.1 | 8.2 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/6/2008 | PM | 20.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/3/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/3/2008 | PI | 308 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.4 | 6.4 | 7 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/3/2008 | PM | 55.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/25/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/25/2008 | PI | 183 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.6 | 4.8 | 3.9 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/25/2008 | PM | 7.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 12/1/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 12/1/2008 | PI | 141 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.3 | 5.5 | 3.4 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 12/1/2008 | PM | 5.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 12/15/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 12/15/2008 | PI | 266 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.4 | 6.8 | 3.5 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 12/15/2008 | PM | 4.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 1/5/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 1/5/2009 | PI | 128 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.7 | 6.5 | 3.1 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 1/5/2009 | PM | 3.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 1/19/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 1/19/2009 | PI | 144 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.2 | 8.5 | 3.2 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 1/19/2009 | PM | 4.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 2/2/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 2/2/2009 | PI | 91.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.6 | 6.2 | 2.1 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 2/2/2009 | PM | 4.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 2/16/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 2/16/2009 | PI | 159 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.9 | 8.5 | 2.7 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P151LNA | 14307 Jarrettsville Pike | 2/16/2009 | PM | 3.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 3/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 3/4/2009 | PI | 36.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.9 | 4.4 | 0.39 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 3/4/2009 | PM | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 3/16/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 3/16/2009 | PI | 189 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4 | 12.3 | 3.2 | 10.2 |
| M35P151LNA | 14307 Jarrettsville Pike | 3/16/2009 | PM | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 4/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 4/6/2009 | PI | 47.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.8 | 5.9 | 0.36 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 4/6/2009 | PM | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 4/20/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 4/20/2009 | PI | 301 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.3 | 17.5 | 3.3 | 48.8 |
| M35P151LNA | 14307 Jarrettsville Pike | 4/20/2009 | PM | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 5/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 5/4/2009 | PI | 86.5 | 0.55 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2 | 6 | 2.9 | 2.4 J |
| M35P151LNA | 14307 Jarrettsville Pike | 5/4/2009 | PM | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 5/18/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 5/18/2009 | PI | 355 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.9 | 17.3 | 6 | 2.8 J |
| M35P151LNA | 14307 Jarrettsville Pike | 5/18/2009 | PM | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 6/1/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 6/1/2009 | PI | 25.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.2 | 8.3 | 0.18 J | 1.5 J |
| M35P151LNA | 14307 Jarrettsville Pike | 6/1/2009 | PM | 0.47 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 6/15/2009 | PE | ND(0.50) | ND(0.50) | 0.098 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 6/15/2009 | PI | 16.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.6 | 1.5 | 0.19 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 6/15/2009 | PM | 0.58 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 6/25/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 6/25/2009 | PI | 19.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.8 | 7.8 | 0.11 J | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P151LNA | 14307 Jarrettsville Pike | 6/25/2009 | PM | 0.61 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 7/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 7/6/2009 | PI | 12.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.9 | 6.5 | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 7/6/2009 | PM | 0.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 7/21/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 7/21/2009 | PI | 12.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.1 | 5.1 | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 7/21/2009 | PM | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 8/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 8/3/2009 | PI | 38.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.9 | 13 | 0.11 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 8/3/2009 | PM | 0.59 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 8/18/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 8/18/2009 | PI | 257 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.6 | 13.4 | 2.3 | 2.5 J |
| M35P151LNA | 14307 Jarrettsville Pike | 8/18/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 8/31/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 8/31/2009 | PI | 170 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.8 | 17.4 | 0.53 | 2.3 J |
| M35P151LNA | 14307 Jarrettsville Pike | 9/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 9/3/2009 | PI | 145 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.4 | 14.9 | 0.78 | 2.4 J |
| M35P151LNA | 14307 Jarrettsville Pike | 9/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 9/15/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 9/15/2009 | PI | 153 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.2 | 12.2 | 0.57 | 2.2 J |
| M35P151LNA | 14307 Jarrettsville Pike | 9/15/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/5/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/5/2009 | PI | 109 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.8 | 15.8 | 0.40 J | 2.5 J |
| M35P151LNA | 14307 Jarrettsville Pike | 10/5/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/19/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 10/19/2009 | PI | 259 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.1 | 16.4 | 1.8 | 3.6 J |
| M35P151LNA | 14307 Jarrettsville Pike | 10/19/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P151LNA | 14307 Jarrettsville Pike | 11/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/3/2009 | PI | 253 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.9 | 15 | 2.3 | 5.4 |
| M35P151LNA | 14307 Jarrettsville Pike | 11/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/23/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/23/2009 | PI | 20.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.1 | 3.7 | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 11/23/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 12/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 12/7/2009 | PI | 67.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3 | 6.6 | 0.49 J | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 12/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 12/21/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 12/21/2009 | PI | 98.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.7 | 7 | 0.82 | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 12/21/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 1/4/2010 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P151LNA | 14307 Jarrettsville Pike | 1/4/2010 | PI | 47.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.7 | 7.3 | 0.28 J | 2.6 J |
| M35P151LNA | 14307 Jarrettsville Pike | 1/4/2010 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P192LNA | 14311 Jarrettsville Pike | 3/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P192LNA | 14311 Jarrettsville Pike | 6/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P192LNA | 14311 Jarrettsville Pike | 8/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P192LNA | 14311 Jarrettsville Pike | 11/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P192LNA | 14311 Jarrettsville Pike | 12/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P192LNA | 14311 Jarrettsville Pike | 1/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P192LNA | 14311 Jarrettsville Pike | 2/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P192LNA | 14311 Jarrettsville Pike | 3/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P192LNA | 14311 Jarrettsville Pike | 4/12/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P192LNA | 14311 Jarrettsville Pike | 5/15/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P192LNA | 14311 Jarrettsville Pike | 6/7/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P192LNA | 14311 Jarrettsville Pike | 7/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P192LNA | 14311 Jarrettsville Pike | 8/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P192LNA | 14311 Jarrettsville Pike | 9/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P192LNA | 14311 Jarrettsville Pike | 10/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L01 | 14315 Jarrettsville Pike | 3/3/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L01 | 14315 Jarrettsville Pike | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L01 | 14315 Jarrettsville Pike | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L01 | 14315 Jarrettsville Pike | 6/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L01 | 14315 Jarrettsville Pike | 8/15/2006 | | ND(0.50) | ND(0.50) | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L01 | 14315 Jarrettsville Pike | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L01 | 14315 Jarrettsville Pike | 4/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L01 | 14315 Jarrettsville Pike | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L01 | 14315 Jarrettsville Pike | 10/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L01 | 14315 Jarrettsville Pike | 1/18/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L01 | 14315 Jarrettsville Pike | 4/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L01 | 14315 Jarrettsville Pike | 7/15/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L01 | 14315 Jarrettsville Pike | 10/9/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L01 | 14315 Jarrettsville Pike | 1/13/2009 | | ND(0.50) | ND(0.50) | 0.63 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L01 | 14315 Jarrettsville Pike | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L01 | 14315 Jarrettsville Pike | 7/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L01 | 14315 Jarrettsville Pike | 10/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 3/14/2006 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 1/9/2007 | | 0.20 J | ND(0.50) | 0.093 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 1/23/2007 | | 0.18 J | 0.15 J | 0.094 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 2/6/2007 | | 0.18 J | ND(0.50) | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 2/20/2007 | | ND(0.50) | ND(0.50) | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 3/6/2007 | | ND(0.50) | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 3/20/2007 | | ND(0.50) | 0.13 J | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P243LNA | 14320 Jarrettsville Pike | 4/3/2007 | | 0.18 J | ND(0.50) | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 4/17/2007 | | ND(0.50) | ND(0.50) | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 5/1/2007 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 5/15/2007 | | 0.14 J | ND(0.50) | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 5/29/2007 | | 0.15 J | 0.11 J | 0.092 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 6/12/2007 | | 0.097 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 6/26/2007 | | ND(0.50) | ND(0.50) | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 7/10/2007 | | 0.12 J | 0.14 J | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 7/24/2007 | | 0.10 J | ND(0.50) | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 8/7/2007 | | 0.14 J | 0.13 J | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 8/21/2007 | | 0.10 J | 0.17 J | 0.63 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 9/4/2007 | | 0.11 J | ND(0.50) | 0.81 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 9/18/2007 | | 0.13 J | ND(0.50) | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 10/2/2007 | | 0.14 J | 0.13 J | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 10/16/2007 | | 0.12 J | ND(0.50) | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 10/30/2007 | | 0.11 J | 0.12 J | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 11/13/2007 | | ND(0.50) | 0.14 J | 0.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 11/27/2007 | | 0.095 J | 0.19 J | 0.54 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P243LNA | 14320 Jarrettsville Pike | 12/11/2007 | | ND(0.5) | ND(0.5) | 0.29 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P243LNA | 14320 Jarrettsville Pike | 1/8/2008 | | 0.086 J | ND(0.50) | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 2/5/2008 | | 0.23 J | 0.35 J | 0.2 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P243LNA | 14320 Jarrettsville Pike | 3/4/2008 | | 0.13 J | ND(0.5) | 0.13 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P243LNA | 14320 Jarrettsville Pike | 4/8/2008 | | 0.085 J | ND(0.5) | 0.12 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P243LNA | 14320 Jarrettsville Pike | 5/6/2008 | | 0.083 J | ND(0.5) | 0.081 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P243LNA | 14320 Jarrettsville Pike | 6/3/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P243LNA | 14320 Jarrettsville Pike | 7/8/2008 | | 0.084 J | ND(0.50) | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 8/5/2008 | | 0.094 J | 0.25 J | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P243LNA | 14320 Jarrettsville Pike | 9/9/2008 | | 0.092 J | 0.19 J | 0.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 10/7/2008 | | 0.086 J | 0.13 J | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 11/4/2008 | | 0.089 J | 0.45 J | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 12/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 1/6/2009 | | 0.11 J | 0.29 J | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 2/3/2009 | | ND(0.50) | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 3/3/2009 | | ND(0.50) | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 4/7/2009 | | 0.083 J | 0.17 J | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 5/4/2009 | | ND(0.50) | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 6/2/2009 | | ND(0.50) | 0.12 J | 0.090 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 7/6/2009 | | ND(0.50) | 0.12 J | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 8/4/2009 | | ND(0.50) | ND(0.50) | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 9/1/2009 | | 0.099 J | ND(0.50) | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 10/6/2009 | | ND(0.50) | 0.12 J | 0.071 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 11/3/2009 | | 0.092 J | ND(0.50) | 0.75 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P243LNA | 14320 Jarrettsville Pike | 12/22/2009 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 2/25/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 3/14/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 4/11/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 4/25/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 5/2/2006 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 5/9/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 5/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 5/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 5/30/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 6/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P174LNA | 14330 Jarrettsville Pike | 6/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 6/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 6/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 7/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 7/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 7/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 7/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 8/1/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 8/8/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 8/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 8/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 8/29/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 9/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 9/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 9/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 9/26/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 10/3/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 10/10/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 10/17/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 10/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 10/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 11/7/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 11/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 11/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 11/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 12/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 12/12/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P174LNA | 14330 Jarrettsville Pike | 12/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 1/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 2/6/2007 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 2/20/2007 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 3/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 3/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 4/3/2007 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 4/17/2007 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 5/1/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 5/15/2007 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 5/29/2007 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 6/12/2007 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 6/26/2007 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 7/10/2007 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 7/24/2007 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 8/6/2007 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 8/20/2007 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 9/4/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 9/18/2007 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 10/2/2007 | | 0.091 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 10/16/2007 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 10/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 11/13/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 1/8/2008 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 2/5/2008 | | 0.28 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P174LNA | 14330 Jarrettsville Pike | 3/4/2008 | | 0.17 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P174LNA | 14330 Jarrettsville Pike | 4/8/2008 | | 0.22 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P174LNA | 14330 Jarrettsville Pike | 5/6/2008 | | 0.16 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P174LNA | 14330 Jarrettsville Pike | 6/3/2008 | | 0.096 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P174LNA | 14330 Jarrettsville Pike | 7/8/2008 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 8/5/2008 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 9/9/2008 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 10/7/2008 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 11/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 12/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 1/6/2009 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 2/3/2009 | | ND(0.50) | 0.61 | ND(0.50) | ND(0.50) | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 3/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 4/7/2009 | | ND(0.50) | 0.86 | 0.054 J | ND(0.50) | 0.47 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 5/4/2009 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 6/1/2009 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 7/6/2009 | | 0.083 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 8/4/2009 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 9/1/2009 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 10/6/2009 | | 0.099 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 11/3/2009 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P174LNA | 14330 Jarrettsville Pike | 12/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L02 | 14333 Jarrettsville Pike | 5/28/2009 | PI | ND(0.50) | ND(0.50) | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L02 | 14333 Jarrettsville Pike | 7/8/2009 | PI | ND(0.50) | ND(0.50) | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L02 | 14333 Jarrettsville Pike | 10/8/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P152L02 | 14333 Jarrettsville Pike | 10/23/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P280LNA | 14335 Jarrettsville Pike | 3/3/2006 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P280LNA | 14335 Jarrettsville Pike | 3/29/2006 | | 0.75 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P280LNA | 14335 Jarrettsville Pike | 4/17/2006 | | 0.69 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P280LNA | 14335 Jarrettsville Pike | 6/14/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P280LNA | 14335 Jarrettsville Pike | 8/17/2006 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P280LNA | 14335 Jarrettsville Pike | 1/22/2007 | | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P280LNA | 14335 Jarrettsville Pike | 4/11/2007 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P280LNA | 14335 Jarrettsville Pike | 7/16/2007 | | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P280LNA | 14335 Jarrettsville Pike | 10/22/2007 | | 0.47 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P280LNA | 14335 Jarrettsville Pike | 1/15/2008 | | 0.3 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P280LNA | 14335 Jarrettsville Pike | 4/1/2008 | | 0.25 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P280LNA | 14335 Jarrettsville Pike | 7/15/2008 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P280LNA | 14335 Jarrettsville Pike | 10/10/2008 | | 0.099 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P280LNA | 14335 Jarrettsville Pike | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P280LNA | 14335 Jarrettsville Pike | 4/1/2009 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P280LNA | 14335 Jarrettsville Pike | 7/8/2009 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P280LNA | 14335 Jarrettsville Pike | 10/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P167LNA | 14342 Jarrettsville Pike | 3/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P167LNA | 14342 Jarrettsville Pike | 4/11/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P167LNA | 14342 Jarrettsville Pike | 8/21/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P167LNA | 14342 Jarrettsville Pike | 11/12/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P167LNA | 14342 Jarrettsville Pike | 4/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P167LNA | 14342 Jarrettsville Pike | 1/23/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P167LNA | 14342 Jarrettsville Pike | 4/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P167LNA | 14342 Jarrettsville Pike | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P167LNA | 14342 Jarrettsville Pike | 10/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P281LNA | 14345 Jarrettsville Pike | 3/15/2006 | | 0.57 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P281LNA | 14345 Jarrettsville Pike | 4/19/2006 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P281LNA | 14345 Jarrettsville Pike | 4/10/2007 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P130LNA | 14346 Jarrettsville Pike | 3/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P130LNA | 14346 Jarrettsville Pike | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P130LNA | 14346 Jarrettsville Pike | 4/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P130LNA | 14346 Jarrettsville Pike | 7/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P130LNA | 14346 Jarrettsville Pike | 10/23/2007 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P130LNA | 14346 Jarrettsville Pike | 1/18/2008 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P130LNA | 14346 Jarrettsville Pike | 4/2/2008 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P130LNA | 14346 Jarrettsville Pike | 7/15/2008 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P130LNA | 14346 Jarrettsville Pike | 10/9/2008 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P130LNA | 14346 Jarrettsville Pike | 1/14/2009 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P130LNA | 14346 Jarrettsville Pike | 4/1/2009 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P130LNA | 14346 Jarrettsville Pike | 6/2/2009 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P130LNA | 14346 Jarrettsville Pike | 7/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P130LNA | 14346 Jarrettsville Pike | 10/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/17/2006 | | 0.86 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 4/17/2006 | | 2.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 8/9/2006 | PIO | 19.6 | ND(0.5) | ND(0.5) | ND(0.5) | ND(1.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) |
| M35P314LNA | 14405 Jarrettsville Pike | 8/17/2006 | PIO | 47.7 | ND(0.5) | ND(0.5) | ND(0.5) | ND(1.5) | ND(0.5) | ND(0.5) | ND(0.5) | 1.45 | ND(0.5) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/22/2006 | PEO | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<10) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/22/2006 | PIO | 13.5 | ND(<1) | ND(<1) | ND(<1) | ND(<1) | ND(<1) | ND(<1) | ND(<1) | ND(<1) | ND(<10) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/22/2006 | PMO | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<10) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/17/2006 | PEO | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<10) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/17/2006 | PIO | 3.1 | ND(<1) | ND(<1) | ND(<1) | ND(<1) | ND(<1) | ND(<1) | ND(<1) | ND(<1) | ND(<10) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/17/2006 | PMO | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<10) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/20/2006 | PEO | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<10) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/20/2006 | PIO | 1.4 | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<10) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/20/2006 | PMO | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<10) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P314LNA | 14405 Jarrettsville Pike | 1/30/2007 | | 4.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.23 J | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/27/2007 | PEO | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<10) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/27/2007 | PIO | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<10) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/27/2007 | PMO | 3.8 | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<10) |
| M35P314LNA | 14405 Jarrettsville Pike | 4/9/2007 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 6/21/2007 | PEO | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<10) |
| M35P314LNA | 14405 Jarrettsville Pike | 6/21/2007 | PIO | 1.8 | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | 1 | ND(<0.5) | ND(<0.5) | ND(<10) |
| M35P314LNA | 14405 Jarrettsville Pike | 6/21/2007 | PMO | 0.6 | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<10) |
| M35P314LNA | 14405 Jarrettsville Pike | 7/19/2007 | | 3.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.6 | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/23/2007 | | 1.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/23/2007 | PEO | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/23/2007 | PIO | 1.4 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/23/2007 | PMO | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/18/2008 | | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.30 J | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 4/4/2008 | | 0.61 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P314LNA | 14405 Jarrettsville Pike | 4/23/2008 | PEO | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) |
| M35P314LNA | 14405 Jarrettsville Pike | 4/23/2008 | PIO | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) |
| M35P314LNA | 14405 Jarrettsville Pike | 4/23/2008 | PMO | 0.8 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) |
| M35P314LNA | 14405 Jarrettsville Pike | 7/18/2008 | | 29.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.71 | ND(0.50) | 0.26 J | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 8/20/2008 | PEO | 0.57 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 8/20/2008 | PIO | 11.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.5 | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 8/20/2008 | PMO | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/12/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/12/2008 | PI | 7.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.46 J | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/12/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/13/2008 | | 6.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.41 J | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/14/2008 | | 6.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.35 J | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P314LNA | 14405 Jarrettsville Pike | 9/15/2008 | | 6.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.43 J | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/16/2008 | | 6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.45 J | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/17/2008 | | 4.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/18/2008 | | 3.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/19/2008 | | 3.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/20/2008 | | 3.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/21/2008 | | 3.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/22/2008 | | 3.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/23/2008 | | 3.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/24/2008 | | 4.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/25/2008 | | 3.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/26/2008 | | 3.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/27/2008 | | 2.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/28/2008 | | 5.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/29/2008 | | 3.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 9/30/2008 | | 2.8 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/1/2008 | | 2.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/2/2008 | | 3.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/3/2008 | | 2.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/5/2008 | | 3.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/6/2008 | | 0.46 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/7/2008 | | 0.93 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/8/2008 | | 0.69 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/9/2008 | | 0.62 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/10/2008 | | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/11/2008 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/12/2008 | | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrettsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P314LNA | 14405 Jarrettsville Pike | 10/13/2008 | | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/14/2008 | | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/15/2008 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/16/2008 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/17/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/17/2008 | PI | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/17/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/18/2008 | | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/19/2008 | | 2.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/20/2008 | | 2.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/21/2008 | | 0.91 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/22/2008 | | 2.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/23/2008 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/25/2008 | | 0.078 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/26/2008 | | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/27/2008 | | 0.45 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/28/2008 | | 0.52 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/29/2008 | | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/30/2008 | | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/31/2008 | | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/1/2008 | | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/2/2008 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/3/2008 | | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/4/2008 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/5/2008 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/6/2008 | | 3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/7/2008 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P314LNA | 14405 Jarrettsville Pike | 11/8/2008 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/9/2008 | | 2.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/10/2008 | | 2.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/11/2008 | | 0.64 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/12/2008 | | 2.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/13/2008 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/14/2008 | | 0.92 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/15/2008 | | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/16/2008 | | 2.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/17/2008 | | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/18/2008 | | 2.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/19/2008 | | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/20/2008 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/20/2008 | PEO | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<10) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/20/2008 | PIO | 1.3 | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<10) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/20/2008 | PMO | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<0.5) | ND(<10) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/21/2008 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/22/2008 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/23/2008 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/24/2008 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/25/2008 | | 0.79 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/26/2008 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/27/2008 | | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/28/2008 | | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/29/2008 | | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/30/2008 | | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/1/2008 | | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P314LNA | 14405 Jarrettsville Pike | 12/2/2008 | | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/3/2008 | | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/4/2008 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/5/2008 | | 0.34 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/6/2008 | | 0.77 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/7/2008 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/8/2008 | | 0.73 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/9/2008 | | 0.77 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/10/2008 | | 0.88 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/11/2008 | | 0.82 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/12/2008 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/13/2008 | | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/14/2008 | | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/15/2008 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/16/2008 | | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/17/2008 | | 2.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/18/2008 | | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/19/2008 | | 1.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/20/2008 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/21/2008 | | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/22/2008 | | 2.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/23/2008 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/24/2008 | | 2.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/27/2008 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/28/2008 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | NA | NA | NA | NA |
| M35P314LNA | 14405 Jarrettsville Pike | 12/29/2008 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/30/2008 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P314LNA | 14405 Jarrettsville Pike | 12/31/2008 | | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/2/2009 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/3/2009 | | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/4/2009 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/5/2009 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/6/2009 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/7/2009 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/8/2009 | | 0.59 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/9/2009 | | 0.94 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/10/2009 | | 0.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/11/2009 | | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/12/2009 | | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/13/2009 | | 0.76 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/14/2009 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/15/2009 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/17/2009 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/19/2009 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/20/2009 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/21/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/21/2009 | PI | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/21/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/22/2009 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/23/2009 | | 0.97 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/24/2009 | | 0.92 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/25/2009 | | 0.47 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/26/2009 | | 0.73 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/27/2009 | | 0.74 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P314LNA | 14405 Jarrettsville Pike | 1/28/2009 | | 0.78 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/29/2009 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/30/2009 | | 0.74 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 1/31/2009 | | 0.84 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/1/2009 | | 0.64 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/2/2009 | | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/3/2009 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/4/2009 | | 1.1 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/5/2009 | | 0.99 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/6/2009 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/7/2009 | | 0.88 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/8/2009 | | 0.91 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/9/2009 | | 0.88 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/10/2009 | | 0.65 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/11/2009 | | 0.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/12/2009 | | 0.75 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/13/2009 | | 0.58 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/14/2009 | | 0.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/15/2009 | | 0.66 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/16/2009 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/17/2009 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/18/2009 | | 0.85 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/19/2009 | | 0.58 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/20/2009 | | 0.99 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/21/2009 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/22/2009 | | 0.87 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/23/2009 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P314LNA | 14405 Jarrettsville Pike | 2/24/2009 | | 0.45 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/25/2009 | | 0.94 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/26/2009 | | 0.75 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/27/2009 | | 0.46 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 2/28/2009 | | 0.91 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/1/2009 | | 0.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/2/2009 | | 0.48 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/3/2009 | | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/4/2009 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/5/2009 | | 0.95 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/6/2009 | | 0.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/7/2009 | | 0.77 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/8/2009 | | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/9/2009 | | 0.61 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/10/2009 | | 0.47 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/11/2009 | | 0.98 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/12/2009 | | 0.84 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/13/2009 | | 0.79 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/14/2009 | | 0.85 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/15/2009 | | 0.81 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/16/2009 | | 0.79 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/17/2009 | | 0.66 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/18/2009 | | 0.77 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/19/2009 | | 0.76 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 3/20/2009 | | 0.75 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 4/1/2009 | PE | 0.67 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 4/1/2009 | PI | 0.78 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P314LNA | 14405 Jarrettsville Pike | 4/1/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 5/4/2009 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 5/12/2009 | PE | 0.51 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 5/12/2009 | PI | 0.55 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 5/12/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 6/1/2009 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 7/7/2009 | PE | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 7/7/2009 | PI | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 7/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 7/31/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 7/31/2009 | PI | 3.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.19 J | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 7/31/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 8/31/2009 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 10/5/2009 | PI | 0.45 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 11/3/2009 | PI | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P314LNA | 14405 Jarrettsville Pike | 12/7/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P153LNA | 14407 Jarrettsville Pike | 3/17/2006 | | 0.95 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P153LNA | 14407 Jarrettsville Pike | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P153LNA | 14407 Jarrettsville Pike | 1/29/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P153LNA | 14407 Jarrettsville Pike | 7/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P153LNA | 14407 Jarrettsville Pike | 1/18/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P153LNA | 14407 Jarrettsville Pike | 7/15/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P153LNA | 14407 Jarrettsville Pike | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P153LNA | 14407 Jarrettsville Pike | 7/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P046LNA | 14409 Jarrettsville Pike | 3/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P046LNA | 14409 Jarrettsville Pike | 4/20/2006 | | 0.53 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P046LNA | 14409 Jarrettsville Pike | 1/29/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P046LNA | 14409 Jarrettsville Pike | 8/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P046LNA | 14409 Jarrettsville Pike | 1/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P046LNA | 14409 Jarrettsville Pike | 1/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P046LNA | 14409 Jarrettsville Pike | 7/16/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P279LNA | 14417 Jarrettsville Pike | 3/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P279LNA | 14417 Jarrettsville Pike | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P279LNA | 14417 Jarrettsville Pike | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P279LNA | 14417 Jarrettsville Pike | 7/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P279LNA | 14417 Jarrettsville Pike | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P279LNA | 14417 Jarrettsville Pike | 7/15/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P279LNA | 14417 Jarrettsville Pike | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P279LNA | 14417 Jarrettsville Pike | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L01 | 14418 Jarrettsville Pike | 3/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L01 | 14418 Jarrettsville Pike | 8/21/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P106LNA01 | 14423 Jarrettsville Pike | 3/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P106LNA01 | 14423 Jarrettsville Pike | 4/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P106LNA01 | 14423 Jarrettsville Pike | 1/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P106LNA01 | 14423 Jarrettsville Pike | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P106LNA01 | 14423 Jarrettsville Pike | 1/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P106LNA01 | 14423 Jarrettsville Pike | 7/22/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P106LNA01 | 14423 Jarrettsville Pike | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P106LNA01 | 14423 Jarrettsville Pike | 7/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P106LNA02 | 14423 Jarrettsville Pike | 4/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P106LNA02 | 14423 Jarrettsville Pike | 1/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P106LNA02 | 14423 Jarrettsville Pike | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P106LNA02 | 14423 Jarrettsville Pike | 1/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P106LNA02 | 14423 Jarrettsville Pike | 7/22/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrrtsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P106LNA02 | 14423 Jarrettsville Pike | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P106LNA02 | 14423 Jarrettsville Pike | 7/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L02 | 14429 Jarrettsville Pike | 3/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L02 | 14429 Jarrettsville Pike | 3/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L02 | 14429 Jarrettsville Pike | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L02 | 14429 Jarrettsville Pike | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L02 | 14429 Jarrettsville Pike | 7/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L02 | 14429 Jarrettsville Pike | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P033L02 | 14429 Jarrettsville Pike | 7/15/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L02 | 14429 Jarrettsville Pike | 1/13/2009 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L02 | 14429 Jarrettsville Pike | 7/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P195LNA0 | 14430 Jarrettsville Pike | 3/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P195LNA0 | 14430 Jarrettsville Pike | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P195LNA0 | 14430 Jarrettsville Pike | 7/18/2007 | | 0.15 J | ND(0.50) | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P195LNA0 | 14430 Jarrettsville Pike | 1/18/2008 | | 0.092 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P195LNA0 | 14430 Jarrettsville Pike | 7/21/2008 | | ND(0.50) | ND(0.50) | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P195LNA0 | 14430 Jarrettsville Pike | 1/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P195LNA0 | 14430 Jarrettsville Pike | 7/8/2009 | | ND(0.50) | ND(0.50) | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P195LNA2 | 14432 Jarrettsville Pike | 3/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P195LNA2 | 14432 Jarrettsville Pike | 7/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P195LNA2 | 14432 Jarrettsville Pike | 7/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P195LNA2 | 14432 Jarrettsville Pike | 1/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P195LNA2 | 14432 Jarrettsville Pike | 7/8/2009 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L03J | 14433 Jarrettsville Pike | 3/16/2006 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L03J | 14433 Jarrettsville Pike | 4/17/2006 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L03J | 14433 Jarrettsville Pike | 1/25/2007 | | 2.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L03J | 14433 Jarrettsville Pike | 8/20/2007 | | 4.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrettsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P033L03J | 14433 Jarrettsville Pike | 7/18/2008 | | 3.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L03J | 14433 Jarrettsville Pike | 1/13/2009 | | 0.88 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L03J | 14433 Jarrettsville Pike | 7/8/2009 | | 0.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L19 | 14403 Katie Rd | 3/18/2006 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L19 | 14403 Katie Rd | 4/22/2006 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L19 | 14403 Katie Rd | 6/17/2006 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L19 | 14403 Katie Rd | 8/19/2006 | | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L19 | 14403 Katie Rd | 1/27/2007 | | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L19 | 14403 Katie Rd | 7/17/2007 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L19 | 14403 Katie Rd | 8/15/2008 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L19 | 14403 Katie Rd | 1/14/2009 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L19 | 14403 Katie Rd | 7/8/2009 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L18 | 14405 Katie Rd | 3/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L18 | 14405 Katie Rd | 4/18/2006 | | 0.75 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L18 | 14405 Katie Rd | 6/14/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L18 | 14405 Katie Rd | 8/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L18 | 14405 Katie Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L18 | 14405 Katie Rd | 7/17/2007 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L18 | 14405 Katie Rd | 1/14/2008 | | 0.095 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L18 | 14405 Katie Rd | 7/14/2008 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L18 | 14405 Katie Rd | 1/13/2009 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L18 | 14405 Katie Rd | 7/13/2009 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 3/18/2006 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 4/18/2006 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 6/12/2006 | | 0.59 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 8/15/2006 | | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.14 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 1/22/2007 | | 9.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.58 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|----------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P224L08 | 14406 Katie Rd | 2/20/2007 | | 11.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.62 | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 4/3/2007 | | 13.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.096 J | ND(0.50) | 0.75 | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 5/1/2007 | | 14 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.79 | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 5/15/2007 | | 13.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.7 | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 5/29/2007 | | 14.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.8 | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 6/12/2007 | | 19.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.73 | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 6/25/2007 | | 18.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.69 | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 7/9/2007 | | 16.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.67 | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 7/24/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 7/24/2007 | PI | 17.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.63 | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 7/24/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 8/7/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 8/7/2007 | PI | 17.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.85 | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 8/7/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 8/21/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 8/21/2007 | PI | 21.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1 | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 8/21/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 9/4/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 9/4/2007 | PI | 17.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.78 | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 9/4/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 9/18/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 9/18/2007 | PI | 18.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.84 | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 9/18/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 10/16/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 10/16/2007 | PI | 19.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.61 | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 10/16/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 10/30/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|----------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P224L08 | 14406 Katie Rd | 10/30/2007 | PI | 23.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.72 | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 10/30/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 11/13/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 11/13/2007 | PI | 20.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.83 | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 11/13/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 11/27/2007 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L08 | 14406 Katie Rd | 11/27/2007 | PI | 17.8 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.77 | ND(5) |
| M35P224L08 | 14406 Katie Rd | 11/27/2007 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L08 | 14406 Katie Rd | 12/11/2007 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L08 | 14406 Katie Rd | 12/11/2007 | PI | 18.7 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.86 | ND(5) |
| M35P224L08 | 14406 Katie Rd | 12/11/2007 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L08 | 14406 Katie Rd | 1/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 1/8/2008 | PI | 18 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.77 | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 1/8/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 2/5/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L08 | 14406 Katie Rd | 2/5/2008 | PI | 16.2 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.88 | ND(5) |
| M35P224L08 | 14406 Katie Rd | 2/5/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L08 | 14406 Katie Rd | 3/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 3/4/2008 | PI | 15.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.74 | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 3/4/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 4/8/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L08 | 14406 Katie Rd | 4/8/2008 | PI | 14.4 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.73 | ND(5) |
| M35P224L08 | 14406 Katie Rd | 4/8/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L08 | 14406 Katie Rd | 5/6/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L08 | 14406 Katie Rd | 5/6/2008 | PI | 12.5 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.68 | ND(5) |
| M35P224L08 | 14406 Katie Rd | 5/6/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L08 | 14406 Katie Rd | 6/3/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|----------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P224L08 | 14406 Katie Rd | 6/3/2008 | PI | 11.3 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.53 | ND(5) |
| M35P224L08 | 14406 Katie Rd | 6/3/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P224L08 | 14406 Katie Rd | 7/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 7/8/2008 | PI | 10 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.41 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 7/8/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 8/5/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 8/5/2008 | PI | 9.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.47 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 8/5/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 9/9/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 9/9/2008 | PI | 8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.33 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 9/9/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 10/7/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 10/7/2008 | PI | 7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.30 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 10/7/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 11/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 11/4/2008 | PI | 7.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.33 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 11/4/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 12/2/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 12/2/2008 | PI | 6.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.21 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 12/2/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 1/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 1/6/2009 | PI | 6.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.30 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 1/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 2/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 2/3/2009 | PI | 6.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.27 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 2/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 2/10/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|----------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P224L08 | 14406 Katie Rd | 2/10/2009 | PI | 6.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.26 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 2/10/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 3/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 3/3/2009 | PI | 5.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.30 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 3/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 4/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 4/7/2009 | PI | 5.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.23 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 4/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 5/5/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 5/5/2009 | PI | 5.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.25 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 5/5/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 6/2/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 6/2/2009 | PI | 4.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.20 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 6/2/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 7/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 7/7/2009 | PI | 4.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.15 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 7/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 8/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 8/4/2009 | PI | 5.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.26 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 8/4/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 9/1/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 9/1/2009 | PI | 4.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.16 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 9/1/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 10/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 10/6/2009 | PI | 4.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.16 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 10/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 11/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|----------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P224L08 | 14406 Katie Rd | 11/3/2009 | PI | 3.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.11 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 11/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 12/8/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 12/8/2009 | PI | 2.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.092 J | ND(5.0) |
| M35P224L08 | 14406 Katie Rd | 12/8/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L17 | 14407 Katie Rd | 3/15/2006 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L17 | 14407 Katie Rd | 4/18/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L17 | 14407 Katie Rd | 6/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L17 | 14407 Katie Rd | 8/14/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L17 | 14407 Katie Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L17 | 14407 Katie Rd | 7/17/2007 | | 0.081 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L17 | 14407 Katie Rd | 1/22/2008 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L17 | 14407 Katie Rd | 7/14/2008 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L17 | 14407 Katie Rd | 1/15/2009 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L17 | 14407 Katie Rd | 10/9/2009 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 3/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 4/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 6/14/2006 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 8/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 1/23/2007 | | 0.94 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 7/17/2007 | | 0.52 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 1/21/2008 | | 11 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.58 | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 2/27/2008 | | 10.9 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.55 | ND(5) |
| M35P224L09 | 14408 Katie Rd | 3/27/2008 | | 12.9 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.54 | ND(5) |
| M35P224L09 | 14408 Katie Rd | 4/10/2008 | | 11.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.59 | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 4/24/2008 | | 8.7 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.39 J | ND(5) |
| M35P224L09 | 14408 Katie Rd | 5/9/2008 | | 8.4 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.42 J | ND(5) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|----------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P224L09 | 14408 Katie Rd | 6/2/2008 | | 5.5 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.23 J | ND(5) |
| M35P224L09 | 14408 Katie Rd | 6/16/2008 | | 6.3 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.3 J | ND(5) |
| M35P224L09 | 14408 Katie Rd | 6/30/2008 | | 4.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.24 J | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 7/16/2008 | | 3.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.17 J | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 8/20/2008 | | 5.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.25 J | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 9/8/2008 | | 5.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.22 J | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 10/8/2008 | | 4.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.19 J | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 11/3/2008 | | 6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.30 J | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 12/1/2008 | | 6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.24 J | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 1/5/2009 | | 7.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.32 J | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 2/2/2009 | | 6.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.28 J | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 3/4/2009 | | 6.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.36 J | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 4/6/2009 | | 7.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.31 J | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 5/4/2009 | | 5.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.30 J | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 6/1/2009 | | 2.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.10 J | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 7/9/2009 | | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 8/4/2009 | | 1.8 | ND(0.50) | 0.091 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.088 J | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 9/1/2009 | | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.074 J | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 10/6/2009 | | 1.5 | ND(0.50) | 0.057 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 11/3/2009 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.079 J | ND(5.0) |
| M35P224L09 | 14408 Katie Rd | 12/8/2009 | | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L16 | 14409 Katie Rd | 3/29/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L16 | 14409 Katie Rd | 6/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L16 | 14409 Katie Rd | 8/15/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L16 | 14409 Katie Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L16 | 14409 Katie Rd | 1/18/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L16 | 14409 Katie Rd | 8/25/2008 | | 0.072 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|----------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P224L16 | 14409 Katie Rd | 1/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L10 | 14410 Katie Rd | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L10 | 14410 Katie Rd | 6/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L10 | 14410 Katie Rd | 8/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L10 | 14410 Katie Rd | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L10 | 14410 Katie Rd | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L10 | 14410 Katie Rd | 1/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L10 | 14410 Katie Rd | 7/14/2008 | | 0.98 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L10 | 14410 Katie Rd | 1/8/2009 | | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.087 J | ND(5.0) |
| M35P224L10 | 14410 Katie Rd | 7/13/2009 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L15 | 14411 Katie Rd | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L15 | 14411 Katie Rd | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L15 | 14411 Katie Rd | 6/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L15 | 14411 Katie Rd | 8/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L15 | 14411 Katie Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L15 | 14411 Katie Rd | 8/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L15 | 14411 Katie Rd | 1/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L15 | 14411 Katie Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L15 | 14411 Katie Rd | 1/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L15 | 14411 Katie Rd | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L11 | 14412 Katie Rd | 3/14/2006 | | 0.75 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L11 | 14412 Katie Rd | 4/18/2006 | | 0.69 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L11 | 14412 Katie Rd | 6/12/2006 | | 0.56 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L11 | 14412 Katie Rd | 8/14/2006 | | 0.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L11 | 14412 Katie Rd | 1/22/2007 | | 0.47 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L11 | 14412 Katie Rd | 7/17/2007 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L11 | 14412 Katie Rd | 1/14/2008 | | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|----------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P224L11 | 14412 Katie Rd | 7/14/2008 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L11 | 14412 Katie Rd | 1/8/2009 | | 0.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L11 | 14412 Katie Rd | 7/15/2009 | | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L14 | 14413 Katie Rd | 4/1/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L14 | 14413 Katie Rd | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L14 | 14413 Katie Rd | 6/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L14 | 14413 Katie Rd | 8/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L14 | 14413 Katie Rd | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L14 | 14413 Katie Rd | 7/19/2007 | | 0.076 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L14 | 14413 Katie Rd | 1/18/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L14 | 14413 Katie Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L14 | 14413 Katie Rd | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L14 | 14413 Katie Rd | 7/16/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L12 | 14414 Katie Rd | 3/14/2006 | | 0.69 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L12 | 14414 Katie Rd | 4/18/2006 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L12 | 14414 Katie Rd | 6/12/2006 | | 0.57 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L12 | 14414 Katie Rd | 8/14/2006 | | 0.51 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L12 | 14414 Katie Rd | 1/22/2007 | | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L12 | 14414 Katie Rd | 7/19/2007 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L12 | 14414 Katie Rd | 1/14/2008 | | 0.64 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L12 | 14414 Katie Rd | 7/14/2008 | | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L12 | 14414 Katie Rd | 1/13/2009 | | 0.47 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L12 | 14414 Katie Rd | 7/8/2009 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P240L01 | 14415 Katie Rd | 3/29/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P240L01 | 14415 Katie Rd | 4/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P240L01 | 14415 Katie Rd | 6/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P240L01 | 14415 Katie Rd | 8/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|----------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M36P240L01 | 14415 Katie Rd | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P240L01 | 14415 Katie Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P240L01 | 14415 Katie Rd | 1/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P240L01 | 14415 Katie Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P240L01 | 14415 Katie Rd | 1/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P240L01 | 14415 Katie Rd | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L13 | 14416 Katie Rd | 3/14/2006 | | 3.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L13 | 14416 Katie Rd | 4/18/2006 | | 4.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L13 | 14416 Katie Rd | 6/12/2006 | | 3.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L13 | 14416 Katie Rd | 8/21/2006 | | 4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L13 | 14416 Katie Rd | 1/23/2007 | | 3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L13 | 14416 Katie Rd | 7/17/2007 | | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L13 | 14416 Katie Rd | 1/14/2008 | | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L13 | 14416 Katie Rd | 7/14/2008 | | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L13 | 14416 Katie Rd | 1/13/2009 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P224L13 | 14416 Katie Rd | 7/8/2009 | | 0.67 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P239L02 | 14417 Katie Rd | 3/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P239L02 | 14417 Katie Rd | 4/17/2006 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P239L02 | 14417 Katie Rd | 6/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P239L02 | 14417 Katie Rd | 8/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P239L02 | 14417 Katie Rd | 1/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P239L02 | 14417 Katie Rd | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P239L02 | 14417 Katie Rd | 1/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P239L02 | 14417 Katie Rd | 10/9/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P239L02 | 14417 Katie Rd | 1/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P239L02 | 14417 Katie Rd | 7/22/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L05 | 14418 Katie Rd | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|----------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M36P133L05 | 14418 Katie Rd | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L05 | 14418 Katie Rd | 6/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L05 | 14418 Katie Rd | 8/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L05 | 14418 Katie Rd | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L05 | 14418 Katie Rd | 4/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L05 | 14418 Katie Rd | 7/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L05 | 14418 Katie Rd | 10/22/2007 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L05 | 14418 Katie Rd | 1/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L05 | 14418 Katie Rd | 4/1/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M36P133L05 | 14418 Katie Rd | 7/18/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L05 | 14418 Katie Rd | 10/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L05 | 14418 Katie Rd | 1/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L05 | 14418 Katie Rd | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L05 | 14418 Katie Rd | 7/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L05 | 14418 Katie Rd | 10/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L03 | 14419 Katie Rd | 3/25/2006 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L03 | 14419 Katie Rd | 4/18/2006 | | 0.45 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L03 | 14419 Katie Rd | 6/17/2006 | | 0.45 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L03 | 14419 Katie Rd | 8/22/2006 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L03 | 14419 Katie Rd | 1/26/2007 | | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L03 | 14419 Katie Rd | 7/19/2007 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L03 | 14419 Katie Rd | 1/14/2008 | | 0.093 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L03 | 14419 Katie Rd | 7/18/2008 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L03 | 14419 Katie Rd | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L03 | 14419 Katie Rd | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L04 | 14420 Katie Rd | 3/29/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L04 | 14420 Katie Rd | 4/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|----------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M36P133L04 | 14420 Katie Rd | 6/14/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L04 | 14420 Katie Rd | 8/14/2006 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L04 | 14420 Katie Rd | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L04 | 14420 Katie Rd | 4/9/2007 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L04 | 14420 Katie Rd | 7/20/2007 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L04 | 14420 Katie Rd | 11/12/2007 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L04 | 14420 Katie Rd | 1/21/2008 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L04 | 14420 Katie Rd | 4/1/2008 | | 0.11 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M36P133L04 | 14420 Katie Rd | 7/14/2008 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L04 | 14420 Katie Rd | 10/9/2008 | | 0.097 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L04 | 14420 Katie Rd | 1/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L04 | 14420 Katie Rd | 4/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L04 | 14420 Katie Rd | 7/21/2009 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P133L04 | 14420 Katie Rd | 10/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P108LNA | 14530 Manor Rd | 1/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P108LNA | 14530 Manor Rd | 7/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P108LNA | 14530 Manor Rd | 1/16/2008 | | 0.09 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M36P108LNA | 14530 Manor Rd | 7/17/2008 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P108LNA | 14530 Manor Rd | 1/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P108LNA | 14530 Manor Rd | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P191LNA | 14532 Manor Rd | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P191LNA | 14532 Manor Rd | 7/20/2007 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P191LNA | 14532 Manor Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M36P191LNA | 14532 Manor Rd | 7/17/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P191LNA | 14532 Manor Rd | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P191LNA | 14532 Manor Rd | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P108L02 | 14604 Manor Rd | 1/22/2007 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M36P108L02 | 14604 Manor Rd | 1/14/2009 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P108L02 | 14604 Manor Rd | 7/13/2009 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L13 | 3400 Meredith Ridge Rd | 3/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L13 | 3400 Meredith Ridge Rd | 1/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L13 | 3400 Meredith Ridge Rd | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L13 | 3400 Meredith Ridge Rd | 7/29/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L13 | 3400 Meredith Ridge Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L13 | 3400 Meredith Ridge Rd | 7/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L12 | 3401 Meredith Ridge Rd | 3/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L12 | 3401 Meredith Ridge Rd | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L12 | 3401 Meredith Ridge Rd | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L12 | 3401 Meredith Ridge Rd | 1/23/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P168L12 | 3401 Meredith Ridge Rd | 7/15/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L12 | 3401 Meredith Ridge Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L12 | 3401 Meredith Ridge Rd | 7/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L11 | 3403 Meredith Ridge Rd | 3/29/2006 | | ND(0.50) | ND(0.50) | 3.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L11 | 3403 Meredith Ridge Rd | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L11 | 3403 Meredith Ridge Rd | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L11 | 3403 Meredith Ridge Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 8.1 |
| M35P168L11 | 3403 Meredith Ridge Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L11 | 3403 Meredith Ridge Rd | 1/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L11 | 3403 Meredith Ridge Rd | 7/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L14 | 3404 Meredith Ridge Rd | 3/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L10 | 3405 Meredith Ridge Rd | 3/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L10 | 3405 Meredith Ridge Rd | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L10 | 3405 Meredith Ridge Rd | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L10 | 3405 Meredith Ridge Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P168L10 | 3405 Meredith Ridge Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L10 | 3405 Meredith Ridge Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L10 | 3405 Meredith Ridge Rd | 7/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L15 | 3406 Meredith Ridge Rd | 3/31/2006 | | 0.22 J | ND(0.50) | 7.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L15 | 3406 Meredith Ridge Rd | 1/22/2007 | | ND(0.50) | ND(0.50) | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L15 | 3406 Meredith Ridge Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L15 | 3406 Meredith Ridge Rd | 1/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L15 | 3406 Meredith Ridge Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L15 | 3406 Meredith Ridge Rd | 1/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L15 | 3406 Meredith Ridge Rd | 7/8/2009 | | ND(0.50) | ND(0.50) | 0.097 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L15 | 3406 Meredith Ridge Rd | 7/31/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L09 | 3407 Meredith Ridge Rd | 1/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L09 | 3407 Meredith Ridge Rd | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L09 | 3407 Meredith Ridge Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.16 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P168L09 | 3407 Meredith Ridge Rd | 7/15/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L09 | 3407 Meredith Ridge Rd | 1/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L09 | 3407 Meredith Ridge Rd | 7/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L08 | 3409 Meredith Ridge Rd | 8/8/2006 | | 0.34 J | ND(0.50) | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L08 | 3409 Meredith Ridge Rd | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L08 | 3409 Meredith Ridge Rd | 4/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L08 | 3409 Meredith Ridge Rd | 7/19/2007 | | ND(0.50) | ND(0.50) | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L08 | 3409 Meredith Ridge Rd | 10/22/2007 | | 0.17 J | ND(0.50) | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L08 | 3409 Meredith Ridge Rd | 1/18/2008 | | 0.096 J | ND(0.50) | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L08 | 3409 Meredith Ridge Rd | 4/1/2008 | | 0.25 J | 0.11 J | 0.35 J | ND(0.5) | 0.14 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P168L08 | 3409 Meredith Ridge Rd | 7/14/2008 | | 0.23 J | 0.15 J | 0.40 J | ND(0.50) | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L08 | 3409 Meredith Ridge Rd | 10/8/2008 | | ND(0.50) | 0.12 J | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L08 | 3409 Meredith Ridge Rd | 1/12/2009 | | 0.089 J | 0.18 J | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P168L08 | 3409 Meredith Ridge Rd | 4/2/2009 | | ND(0.50) | 1.4 | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L08 | 3409 Meredith Ridge Rd | 6/15/2009 | | ND(0.50) | 0.31 J | 1.3 | ND(0.50) | 0.57 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L08 | 3409 Meredith Ridge Rd | 7/8/2009 | | 0.087 J | ND(0.50) | 0.068 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L08 | 3409 Meredith Ridge Rd | 10/7/2009 | | 0.14 J | 3.4 | 0.071 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L08 | 3409 Meredith Ridge Rd | 10/23/2009 | | ND(0.50) | 1.4 | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L07 | 3411 Meredith Ridge Rd | 3/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L07 | 3411 Meredith Ridge Rd | 1/27/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L07 | 3411 Meredith Ridge Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L07 | 3411 Meredith Ridge Rd | 10/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L07 | 3411 Meredith Ridge Rd | 1/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L07 | 3411 Meredith Ridge Rd | 4/1/2008 | | 0.12 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P168L07 | 3411 Meredith Ridge Rd | 7/15/2008 | | 0.090 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L07 | 3411 Meredith Ridge Rd | 10/9/2008 | | 0.085 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L07 | 3411 Meredith Ridge Rd | 1/12/2009 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L07 | 3411 Meredith Ridge Rd | 4/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L07 | 3411 Meredith Ridge Rd | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L07 | 3411 Meredith Ridge Rd | 10/13/2009 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L16 | 3412 Meredith Ridge Rd | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L16 | 3412 Meredith Ridge Rd | 7/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L16 | 3412 Meredith Ridge Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P168L16 | 3412 Meredith Ridge Rd | 7/15/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L16 | 3412 Meredith Ridge Rd | 1/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L16 | 3412 Meredith Ridge Rd | 7/16/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L17 | 3414 Meredith Ridge Rd | 3/30/2006 | | ND(10) | ND(10) | ND(10) | ND(10) | ND(10) | ND(10) | ND(10) | ND(10) | ND(10) | ND(100) |
| M35P168L17 | 3414 Meredith Ridge Rd | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L17 | 3414 Meredith Ridge Rd | 8/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L17 | 3414 Meredith Ridge Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P168L17 | 3414 Meredith Ridge Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L17 | 3414 Meredith Ridge Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L17 | 3414 Meredith Ridge Rd | 7/17/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L04 | 3415 Meredith Ridge Rd | 3/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L04 | 3415 Meredith Ridge Rd | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L04 | 3415 Meredith Ridge Rd | 7/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L04 | 3415 Meredith Ridge Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | 0.053 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P168L04 | 3415 Meredith Ridge Rd | 7/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L04 | 3415 Meredith Ridge Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L04 | 3415 Meredith Ridge Rd | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L03 | 3416 Meredith Ridge Rd | 3/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L05 | 3417 Meredith Ridge Rd | 3/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L05 | 3417 Meredith Ridge Rd | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L05 | 3417 Meredith Ridge Rd | 7/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L05 | 3417 Meredith Ridge Rd | 11/13/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L05 | 3417 Meredith Ridge Rd | 1/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L05 | 3417 Meredith Ridge Rd | 4/1/2008 | | 0.097 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P168L05 | 3417 Meredith Ridge Rd | 7/24/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L05 | 3417 Meredith Ridge Rd | 10/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L05 | 3417 Meredith Ridge Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L05 | 3417 Meredith Ridge Rd | 4/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L05 | 3417 Meredith Ridge Rd | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L05 | 3417 Meredith Ridge Rd | 10/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L02 | 3418 Meredith Ridge Rd | 3/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L02 | 3418 Meredith Ridge Rd | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L02 | 3418 Meredith Ridge Rd | 7/21/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L02 | 3418 Meredith Ridge Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P168L02 | 3418 Meredith Ridge Rd | 7/22/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P168L02 | 3418 Meredith Ridge Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P160L05 | 14416 Misty Valley Rd | 3/14/2006 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P160L05 | 14416 Misty Valley Rd | 4/18/2006 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P160L05 | 14416 Misty Valley Rd | 1/25/2007 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P160L05 | 14416 Misty Valley Rd | 7/17/2007 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P160L05 | 14416 Misty Valley Rd | 1/16/2008 | | 0.12 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M36P160L05 | 14416 Misty Valley Rd | 7/17/2008 | | 0.099 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P160L05 | 14416 Misty Valley Rd | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P160L05 | 14416 Misty Valley Rd | 7/9/2009 | | 0.099 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P160L06 | 14418 Misty Valley Rd | 3/16/2006 | | 0.57 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.1 | ND(0.50) | 36.2 |
| M36P160L06 | 14418 Misty Valley Rd | 4/22/2006 | | 0.53 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P160L06 | 14418 Misty Valley Rd | 8/20/2007 | | 0.61 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P160L06 | 14418 Misty Valley Rd | 1/22/2008 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P160L06 | 14418 Misty Valley Rd | 7/22/2008 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P160L06 | 14418 Misty Valley Rd | 7/13/2009 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P297L27 | 1 Overshot Ct | 3/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P297L01 | 2 Overshot Ct | 3/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P297L01 | 2 Overshot Ct | 3/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P316LNA01 | 3101 Paper Mill Rd | 3/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P316LNA01 | 3101 Paper Mill Rd | 4/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P316LNA01 | 3101 Paper Mill Rd | 8/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P316LNA01 | 3101 Paper Mill Rd | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P316LNA01 | 3101 Paper Mill Rd | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P316LNA01 | 3101 Paper Mill Rd | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P316LNA01 | 3101 Paper Mill Rd | 7/16/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P316LNA01 | 3101 Paper Mill Rd | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P316LNA02 | 3101 Paper Mill Rd | 3/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P316LNA02 | 3101 Paper Mill Rd | 4/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P316LNA02 | 3101 Paper Mill Rd | 8/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P316LNA02 | 3101 Paper Mill Rd | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.18 J | ND(5.0) |
| M35P316LNA02 | 3101 Paper Mill Rd | 7/17/2007 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.42 J | ND(5.0) |
| M35P316LNA02 | 3101 Paper Mill Rd | 1/16/2008 | | 0.21 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.29 J | ND(5) |
| M35P316LNA02 | 3101 Paper Mill Rd | 7/16/2008 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.35 J | ND(5.0) |
| M35P316LNA02 | 3101 Paper Mill Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P316LNA02 | 3101 Paper Mill Rd | 1/15/2009 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.12 J | ND(5.0) |
| M35P316LNA02 | 3101 Paper Mill Rd | 7/13/2009 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.14 J | ND(5.0) |
| M35P241LNA01 | 3112 Paper Mill Rd | 3/21/2006 | | 2.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.35 J | ND(5.0) |
| M35P241LNA01 | 3112 Paper Mill Rd | 1/23/2007 | | 5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.64 | ND(5.0) |
| M35P241LNA01 | 3112 Paper Mill Rd | 7/17/2007 | | 3.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.44 J | ND(5.0) |
| M35P241LNA01 | 3112 Paper Mill Rd | 1/15/2008 | | 2.2 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.22 J | ND(5) |
| M35P241LNA01 | 3112 Paper Mill Rd | 7/15/2008 | | 3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.33 J | ND(5.0) |
| M35P241LNA01 | 3112 Paper Mill Rd | 1/8/2009 | | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.25 J | ND(5.0) |
| M35P241LNA01 | 3112 Paper Mill Rd | 7/14/2009 | | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.31 J | ND(5.0) |
| M35P241LNA02 | 3112 Paper Mill Rd | 3/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P241LNA02 | 3112 Paper Mill Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P241LNA02 | 3112 Paper Mill Rd | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P241LNA02 | 3112 Paper Mill Rd | 1/15/2008 | | ND(0.5) | 0.15 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P241LNA02 | 3112 Paper Mill Rd | 7/15/2008 | | ND(0.50) | 0.098 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P241LNA02 | 3112 Paper Mill Rd | 1/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P241LNA02 | 3112 Paper Mill Rd | 7/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P118LNA | 3115 Paper Mill Rd | 2/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P118LNA | 3115 Paper Mill Rd | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P118LNA | 3115 Paper Mill Rd | 4/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P118LNA | 3115 Paper Mill Rd | 8/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P118LNA | 3115 Paper Mill Rd | 1/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P118LNA | 3115 Paper Mill Rd | 7/16/2007 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P118LNA | 3115 Paper Mill Rd | 7/25/2008 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P118LNA | 3115 Paper Mill Rd | 1/15/2009 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L29 | 3116 Paper Mill Rd | 3/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L29 | 3116 Paper Mill Rd | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L29 | 3116 Paper Mill Rd | 7/17/2007 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L29 | 3116 Paper Mill Rd | 1/18/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L29 | 3116 Paper Mill Rd | 7/16/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L29 | 3116 Paper Mill Rd | 1/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L29 | 3116 Paper Mill Rd | 7/10/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P138LNA | 3117 Paper Mill Rd | 3/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P138LNA | 3117 Paper Mill Rd | 4/24/2006 | | 0.62 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P138LNA | 3117 Paper Mill Rd | 8/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P138LNA | 3117 Paper Mill Rd | 1/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P138LNA | 3117 Paper Mill Rd | 7/17/2007 | | 0.096 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P138LNA | 3117 Paper Mill Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P138LNA | 3117 Paper Mill Rd | 7/16/2008 | | 0.070 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P138LNA | 3117 Paper Mill Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P138LNA | 3117 Paper Mill Rd | 7/10/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L28 | 3120 Paper Mill Rd | 3/15/2006 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1 | ND(5.0) |
| M35P024L28 | 3120 Paper Mill Rd | 1/30/2007 | | 5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.3 | ND(5.0) |
| M35P024L28 | 3120 Paper Mill Rd | 7/17/2007 | | 12.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.7 | ND(5.0) |
| M35P024L28 | 3120 Paper Mill Rd | 1/15/2008 | | 9.1 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 2.7 | ND(5) |
| M35P024L28 | 3120 Paper Mill Rd | 3/3/2008 | | 8.6 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 3.1 | ND(5) |
| M35P024L28 | 3120 Paper Mill Rd | 4/7/2008 | | 8.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.3 | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P024L28 | 3120 Paper Mill Rd | 5/5/2008 | | 7.7 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 3.1 | ND(5) |
| M35P024L28 | 3120 Paper Mill Rd | 7/16/2008 | | 7.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.8 | ND(5.0) |
| M35P024L28 | 3120 Paper Mill Rd | 8/5/2008 | | 8.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.2 | ND(5.0) |
| M35P024L28 | 3120 Paper Mill Rd | 9/8/2008 | | 8.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.8 | ND(5.0) |
| M35P024L28 | 3120 Paper Mill Rd | 10/6/2008 | | 8.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.2 | ND(5.0) |
| M35P024L28 | 3120 Paper Mill Rd | 1/5/2009 | | 9.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.5 | ND(5.0) |
| M35P024L28 | 3120 Paper Mill Rd | 3/4/2009 | | 8.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3.5 | ND(5.0) |
| M35P024L28 | 3120 Paper Mill Rd | 5/4/2009 | | 6.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.7 | ND(5.0) |
| M35P024L28 | 3120 Paper Mill Rd | 7/6/2009 | | 5.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.5 | ND(5.0) |
| M35P024L28 | 3120 Paper Mill Rd | 8/3/2009 | | 6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.1 | ND(5.0) |
| M35P024L28 | 3120 Paper Mill Rd | 8/31/2009 | | 6.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.1 | ND(5.0) |
| M35P024L28 | 3120 Paper Mill Rd | 10/5/2009 | | 5.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.9 | ND(5.0) |
| M35P024L28 | 3120 Paper Mill Rd | 11/2/2009 | | 6.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2 | ND(5.0) |
| M35P024L28 | 3120 Paper Mill Rd | 12/10/2009 | | 4.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.5 | ND(5.0) |
| M35P242LNA | 3121 Paper Mill Rd | 2/25/2006 | | ND(0.50) | 0.56 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P242LNA | 3121 Paper Mill Rd | 4/1/2006 | | ND(0.50) | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P242LNA | 3121 Paper Mill Rd | 4/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P242LNA | 3121 Paper Mill Rd | 8/17/2006 | | 0.21 J | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P242LNA | 3121 Paper Mill Rd | 1/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P242LNA | 3121 Paper Mill Rd | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P242LNA | 3121 Paper Mill Rd | 1/21/2008 | | ND(0.50) | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P242LNA | 3121 Paper Mill Rd | 7/16/2008 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P242LNA | 3121 Paper Mill Rd | 1/7/2009 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P242LNA | 3121 Paper Mill Rd | 7/15/2009 | | 0.14 J | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L02 | 3204 Paper Mill Rd | 3/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L02 | 3204 Paper Mill Rd | 1/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L02 | 3204 Paper Mill Rd | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P024L02 | 3204 Paper Mill Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P024L02 | 3204 Paper Mill Rd | 7/15/2008 | | ND(0.50) | ND(0.50) | 0.074 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L02 | 3204 Paper Mill Rd | 1/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P024L02 | 3204 Paper Mill Rd | 7/13/2009 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P245LNA | 3206 Paper Mill Rd | 3/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P245LNA | 3206 Paper Mill Rd | 1/27/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P245LNA | 3206 Paper Mill Rd | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P245LNA | 3206 Paper Mill Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P245LNA | 3206 Paper Mill Rd | 7/17/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P245LNA | 3206 Paper Mill Rd | 1/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P245LNA | 3206 Paper Mill Rd | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L07 | 3210 Paper Mill Rd | 3/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L07 | 3210 Paper Mill Rd | 1/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L07 | 3210 Paper Mill Rd | 7/21/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L07 | 3210 Paper Mill Rd | 1/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L07 | 3210 Paper Mill Rd | 1/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L07 | 3210 Paper Mill Rd | 8/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L06 | 3212 Paper Mill Rd | 3/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L06 | 3212 Paper Mill Rd | 1/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L06 | 3212 Paper Mill Rd | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L06 | 3212 Paper Mill Rd | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P310L06 | 3212 Paper Mill Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L06 | 3212 Paper Mill Rd | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L01 | 3214 Paper Mill Rd | 3/17/2006 | | 0.64 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L01 | 3214 Paper Mill Rd | 7/17/2007 | | 5.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.15 J | ND(5.0) |
| M35P028L01 | 3214 Paper Mill Rd | 1/18/2008 | | 4.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L01 | 3214 Paper Mill Rd | 7/16/2008 | | 3.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P028L01 | 3214 Paper Mill Rd | 1/12/2009 | | 2.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.090 J | ND(5.0) |
| M35P028L01 | 3214 Paper Mill Rd | 7/14/2009 | | 2.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L05 | 3216 Paper Mill Rd | 3/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L05 | 3216 Paper Mill Rd | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L05 | 3216 Paper Mill Rd | 7/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L05 | 3216 Paper Mill Rd | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P310L05 | 3216 Paper Mill Rd | 7/17/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L05 | 3216 Paper Mill Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L05 | 3216 Paper Mill Rd | 7/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P120LNA | 3219 Paper Mill Rd | 2/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P120LNA | 3219 Paper Mill Rd | 3/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P120LNA | 3219 Paper Mill Rd | 4/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P120LNA | 3219 Paper Mill Rd | 8/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P120LNA | 3219 Paper Mill Rd | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P120LNA | 3219 Paper Mill Rd | 7/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P120LNA | 3219 Paper Mill Rd | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P120LNA | 3219 Paper Mill Rd | 7/18/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P120LNA | 3219 Paper Mill Rd | 1/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P120LNA | 3219 Paper Mill Rd | 7/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L02 | 3224 Paper Mill Rd | 3/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L02 | 3224 Paper Mill Rd | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L02 | 3224 Paper Mill Rd | 4/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L02 | 3224 Paper Mill Rd | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L02 | 3224 Paper Mill Rd | 10/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L02 | 3224 Paper Mill Rd | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P028L02 | 3224 Paper Mill Rd | 4/1/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P028L02 | 3224 Paper Mill Rd | 7/16/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P028L02 | 3224 Paper Mill Rd | 10/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L02 | 3224 Paper Mill Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L02 | 3224 Paper Mill Rd | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L02 | 3224 Paper Mill Rd | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L02 | 3224 Paper Mill Rd | 10/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L04 | 3226 Paper Mill Rd | 3/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L04 | 3226 Paper Mill Rd | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L04 | 3226 Paper Mill Rd | 7/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L04 | 3226 Paper Mill Rd | 1/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L04 | 3226 Paper Mill Rd | 7/22/2008 | | ND(0.50) | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L04 | 3226 Paper Mill Rd | 1/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L04 | 3226 Paper Mill Rd | 7/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L08 | 3235 Paper Mill Rd | 2/23/2006 | | 0.53 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L08 | 3235 Paper Mill Rd | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L08 | 3235 Paper Mill Rd | 4/24/2006 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L08 | 3235 Paper Mill Rd | 6/12/2006 | | 0.56 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L08 | 3235 Paper Mill Rd | 8/14/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L08 | 3235 Paper Mill Rd | 1/24/2007 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L08 | 3235 Paper Mill Rd | 4/10/2007 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L08 | 3235 Paper Mill Rd | 7/18/2007 | | 0.53 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L08 | 3235 Paper Mill Rd | 10/22/2007 | | 0.44 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L08 | 3235 Paper Mill Rd | 1/17/2008 | | 0.87 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P310L08 | 3235 Paper Mill Rd | 4/2/2008 | | 0.46 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L08 | 3235 Paper Mill Rd | 7/16/2008 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L08 | 3235 Paper Mill Rd | 10/8/2008 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L08 | 3235 Paper Mill Rd | 1/12/2009 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L08 | 3235 Paper Mill Rd | 4/7/2009 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P310L08 | 3235 Paper Mill Rd | 7/8/2009 | | 0.084 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L08 | 3235 Paper Mill Rd | 10/7/2009 | | 0.094 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 3/20/2006 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 3/5/2007 | | 4.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.37 J | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 4/10/2007 | | 4.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.38 J | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 7/19/2007 | | 4.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.39 J | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 10/22/2007 | | 13.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.72 | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 1/18/2008 | | 12.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.92 | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 3/3/2008 | | 12 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.83 | ND(5) |
| M35P310L02 | 3300 Paper Mill Rd | 4/1/2008 | | 9.3 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.67 | ND(5) |
| M35P310L02 | 3300 Paper Mill Rd | 4/7/2008 | | 9.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.76 | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 5/5/2008 | | 5.8 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.46 J | ND(5) |
| M35P310L02 | 3300 Paper Mill Rd | 6/2/2008 | | 4.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.35 J | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 7/7/2008 | | 4.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.33 J | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 8/4/2008 | | 5.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.43 J | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 9/8/2008 | | 6.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.46 J | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 10/6/2008 | | 5.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.37 J | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 11/3/2008 | | 6.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.52 | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 12/9/2008 | | 6.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.49 J | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 1/5/2009 | | 6.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.45 J | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 2/2/2009 | | 5.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.42 J | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 3/4/2009 | | 5.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.40 J | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 4/6/2009 | | 5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.35 J | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 5/4/2009 | | 4.5 | ND(0.50) | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.40 J | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 6/2/2009 | | 3.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.25 J | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 7/7/2009 | | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.14 J | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 8/31/2009 | | 3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.24 J | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P310L02 | 3300 Paper Mill Rd | 10/5/2009 | | 2.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.17 J | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 11/2/2009 | | 3.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.23 J | ND(5.0) |
| M35P310L02 | 3300 Paper Mill Rd | 12/8/2009 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.15 J | ND(5.0) |
| M35P310L09 | 3301 Paper Mill Rd | 2/24/2006 | | 0.56 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L09 | 3301 Paper Mill Rd | 4/1/2006 | | 0.59 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L09 | 3301 Paper Mill Rd | 4/24/2006 | | 0.57 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L09 | 3301 Paper Mill Rd | 6/12/2006 | | 0.69 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L09 | 3301 Paper Mill Rd | 8/28/2006 | | 0.69 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L09 | 3301 Paper Mill Rd | 1/25/2007 | | 0.82 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L09 | 3301 Paper Mill Rd | 5/15/2007 | | 0.64 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L09 | 3301 Paper Mill Rd | 7/20/2007 | | 0.54 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L09 | 3301 Paper Mill Rd | 10/22/2007 | | 0.56 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L09 | 3301 Paper Mill Rd | 1/18/2008 | | 0.51 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L09 | 3301 Paper Mill Rd | 4/4/2008 | | 0.33 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P310L09 | 3301 Paper Mill Rd | 7/16/2008 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L09 | 3301 Paper Mill Rd | 10/8/2008 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L09 | 3301 Paper Mill Rd | 1/12/2009 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L09 | 3301 Paper Mill Rd | 4/2/2009 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L09 | 3301 Paper Mill Rd | 7/14/2009 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L09 | 3301 Paper Mill Rd | 10/12/2009 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 2/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 3/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 4/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 6/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 8/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 8/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 9/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P310L10 | 3305 Paper Mill Rd | 9/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 9/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 10/2/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 10/9/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 10/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 10/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 10/30/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 11/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 11/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 11/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 12/4/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 12/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 12/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 1/8/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 2/5/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 2/21/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 3/5/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 4/2/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 4/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 4/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 5/14/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 5/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 6/11/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 6/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 7/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 7/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P310L10 | 3305 Paper Mill Rd | 8/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 9/4/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 9/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 10/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 10/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 11/13/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 11/27/2007 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P310L10 | 3305 Paper Mill Rd | 12/11/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 1/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 3/4/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P310L10 | 3305 Paper Mill Rd | 5/6/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P310L10 | 3305 Paper Mill Rd | 6/3/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P310L10 | 3305 Paper Mill Rd | 7/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 10/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 4/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 5/5/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 6/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 7/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 9/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 10/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L10 | 3305 Paper Mill Rd | 11/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L01 | 3306 Paper Mill Rd | 3/18/2006 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L01 | 3306 Paper Mill Rd | 1/24/2007 | | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L01 | 3306 Paper Mill Rd | 4/9/2007 | | 0.46 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L01 | 3306 Paper Mill Rd | 7/17/2007 | | 0.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L01 | 3306 Paper Mill Rd | 10/24/2007 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P310L01 | 3306 Paper Mill Rd | 1/16/2008 | | 0.4 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P310L01 | 3306 Paper Mill Rd | 4/2/2008 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L01 | 3306 Paper Mill Rd | 7/16/2008 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L01 | 3306 Paper Mill Rd | 10/8/2008 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L01 | 3306 Paper Mill Rd | 7/13/2009 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 2/20/2006 | | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 3/6/2006 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 3/13/2006 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 3/20/2006 | | 4.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 3/27/2006 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 4/3/2006 | | 10.3 | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 33.6 |
| M35P054LNA | 3313 Paper Mill Rd | 4/6/2006 | | 5.1 | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 10.4 |
| M35P054LNA | 3313 Paper Mill Rd | 4/10/2006 | | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 4/17/2006 | | 2.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 4/24/2006 | | 8.1 | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.13 J | ND(0.50) | ND(0.50) | 22.7 |
| M35P054LNA | 3313 Paper Mill Rd | 5/1/2006 | | 2.5 | 0.099 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.6 |
| M35P054LNA | 3313 Paper Mill Rd | 5/9/2006 | | 14.7 | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.14 J | ND(0.50) | ND(0.50) | 40 |
| M35P054LNA | 3313 Paper Mill Rd | 5/16/2006 | | 4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 5.7 |
| M35P054LNA | 3313 Paper Mill Rd | 5/31/2006 | | 2.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.9 J |
| M35P054LNA | 3313 Paper Mill Rd | 6/5/2006 | | 1.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 6/12/2006 | | 3.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 6/19/2006 | | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 6/26/2006 | | 6.8 | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.076 J | ND(0.50) | ND(0.50) | 14.7 |
| M35P054LNA | 3313 Paper Mill Rd | 7/10/2006 | | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 7/17/2006 | | 33.6 | 0.96 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.44 J | ND(0.50) | ND(0.50) | 106 |
| M35P054LNA | 3313 Paper Mill Rd | 7/24/2006 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 8/1/2006 | | 20.2 | 0.53 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 47.6 |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P054LNA | 3313 Paper Mill Rd | 8/7/2006 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 8/22/2006 | | 7.8 | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 15.6 |
| M35P054LNA | 3313 Paper Mill Rd | 8/28/2006 | | 0.97 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 9/5/2006 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 9/11/2006 | | 0.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 9/19/2006 | | 5.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.7 J |
| M35P054LNA | 3313 Paper Mill Rd | 9/25/2006 | | 0.63 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 10/2/2006 | | 0.61 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 10/9/2006 | | 0.66 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 10/16/2006 | | 9.7 | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 10/23/2006 | | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 10/30/2006 | | 0.93 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 11/6/2006 | | 0.68 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 11/13/2006 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 11/20/2006 | | 0.47 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 12/4/2006 | | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 12/11/2006 | | 2.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 12/18/2006 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 1/8/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 1/22/2007 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 2/5/2007 | | 0.84 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 2/20/2007 | | 4.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 3/5/2007 | | 5.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 3/19/2007 | | 0.53 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 4/2/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 4/16/2007 | | 0.83 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 4/30/2007 | | 0.51 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P054LNA | 3313 Paper Mill Rd | 5/14/2007 | | 0.88 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 5/29/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 6/11/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 6/11/2007 | PI | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 6/11/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 6/25/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 6/25/2007 | PI | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 6/25/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 7/9/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 7/9/2007 | PI | 0.66 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 7/9/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 7/23/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 7/23/2007 | PI | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 7/23/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 8/20/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 8/20/2007 | PI | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 8/20/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 9/5/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 9/5/2007 | PI | 0.74 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 9/5/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 9/18/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 9/18/2007 | PI | 0.81 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 9/18/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 10/2/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 10/2/2007 | PI | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 10/2/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 10/15/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P054LNA | 3313 Paper Mill Rd | 10/15/2007 | PI | 4.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.2 J |
| M35P054LNA | 3313 Paper Mill Rd | 10/15/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 10/29/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 10/29/2007 | PI | 8.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 12.2 |
| M35P054LNA | 3313 Paper Mill Rd | 10/29/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 11/12/2007 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 11/12/2007 | PI | 6.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.4 J |
| M35P054LNA | 3313 Paper Mill Rd | 11/12/2007 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 11/26/2007 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P054LNA | 3313 Paper Mill Rd | 11/26/2007 | PI | 3.2 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P054LNA | 3313 Paper Mill Rd | 11/26/2007 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P054LNA | 3313 Paper Mill Rd | 1/7/2008 | PE | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P054LNA | 3313 Paper Mill Rd | 1/7/2008 | PI | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P054LNA | 3313 Paper Mill Rd | 1/7/2008 | PM | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P054LNA | 3313 Paper Mill Rd | 2/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 2/4/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 2/4/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 3/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 3/4/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 3/4/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 4/7/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 4/7/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 4/7/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 5/5/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 5/5/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 5/5/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 6/2/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P054LNA | 3313 Paper Mill Rd | 6/2/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 6/2/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 7/7/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 7/7/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 7/7/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 8/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 8/4/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 8/4/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 9/8/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 9/8/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 9/8/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 10/6/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 10/6/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 10/6/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 11/3/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 11/3/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 11/3/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 12/1/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 12/1/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 12/1/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 1/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 1/6/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 1/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 2/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 2/3/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 2/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 3/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P054LNA | 3313 Paper Mill Rd | 3/4/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 3/4/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 4/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 4/6/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 4/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 5/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 5/4/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 5/4/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 6/1/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 6/1/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 6/1/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 7/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 7/6/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 7/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 8/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 8/4/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 8/4/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 8/31/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 8/31/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 8/31/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 10/5/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 10/5/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 10/5/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 11/2/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 11/2/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 11/2/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 12/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P054LNA | 3313 Paper Mill Rd | 12/7/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P054LNA | 3313 Paper Mill Rd | 12/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA01 | 3314 Paper Mill Rd | 3/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA01 | 3314 Paper Mill Rd | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA01 | 3314 Paper Mill Rd | 4/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA01 | 3314 Paper Mill Rd | 7/18/2007 | | ND(0.50) | ND(0.50) | 0.81 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA01 | 3314 Paper Mill Rd | 10/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA01 | 3314 Paper Mill Rd | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P116LNA01 | 3314 Paper Mill Rd | 4/1/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P116LNA01 | 3314 Paper Mill Rd | 7/16/2008 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA01 | 3314 Paper Mill Rd | 10/9/2008 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA01 | 3314 Paper Mill Rd | 1/12/2009 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA01 | 3314 Paper Mill Rd | 4/1/2009 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA01 | 3314 Paper Mill Rd | 10/8/2009 | | 0.085 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA02 | 3314 Paper Mill Rd | 3/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA02 | 3314 Paper Mill Rd | 1/24/2007 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA02 | 3314 Paper Mill Rd | 4/10/2007 | | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA02 | 3314 Paper Mill Rd | 7/18/2007 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA02 | 3314 Paper Mill Rd | 10/22/2007 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA02 | 3314 Paper Mill Rd | 1/16/2008 | | 0.3 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P116LNA02 | 3314 Paper Mill Rd | 4/1/2008 | | 0.29 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P116LNA02 | 3314 Paper Mill Rd | 7/16/2008 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA02 | 3314 Paper Mill Rd | 10/8/2008 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA02 | 3314 Paper Mill Rd | 4/1/2009 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA02 | 3314 Paper Mill Rd | 7/13/2009 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P116LNA02 | 3314 Paper Mill Rd | 10/8/2009 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 2/28/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P123LNAP | 3320 Paper Mill Rd | 3/7/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 3/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 3/21/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 3/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 4/4/2006 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 4/11/2006 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 4/18/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 4/25/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 5/2/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 5/9/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 5/16/2006 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 5/23/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 5/30/2006 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 6/6/2006 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 6/13/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 6/20/2006 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 6/27/2006 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 7/6/2006 | | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 7/11/2006 | | 0.45 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 7/18/2006 | | 0.48 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 7/25/2006 | | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 8/1/2006 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 8/8/2006 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 8/15/2006 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 8/22/2006 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 8/29/2006 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 9/5/2006 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P123LNAP | 3320 Paper Mill Rd | 9/12/2006 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 9/26/2006 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 10/3/2006 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 10/10/2006 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 10/17/2006 | | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 10/24/2006 | | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 10/31/2006 | | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 11/7/2006 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 11/14/2006 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 11/21/2006 | | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 11/28/2006 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 12/5/2006 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 12/12/2006 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 12/19/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 1/9/2007 | | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 1/23/2007 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 2/6/2007 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 2/20/2007 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 3/6/2007 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 3/20/2007 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 4/3/2007 | | 0.46 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 4/17/2007 | | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 5/1/2007 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 5/15/2007 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 5/30/2007 | | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 6/12/2007 | | ND(0.50) | ND(0.50) | 0.22 J | ND(0.50) | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 6/26/2007 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P123LNAP | 3320 Paper Mill Rd | 7/10/2007 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 7/24/2007 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 8/7/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 8/21/2007 | | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 9/4/2007 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 9/18/2007 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 10/2/2007 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 10/16/2007 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 10/30/2007 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 11/13/2007 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 11/27/2007 | | 0.44 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P123LNAP | 3320 Paper Mill Rd | 12/11/2007 | | 0.34 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P123LNAP | 3320 Paper Mill Rd | 1/8/2008 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 2/5/2008 | | 0.36 J | ND(0.5) | 0.12 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P123LNAP | 3320 Paper Mill Rd | 3/4/2008 | | 0.3 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P123LNAP | 3320 Paper Mill Rd | 4/8/2008 | | 0.31 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P123LNAP | 3320 Paper Mill Rd | 5/6/2008 | | 0.33 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P123LNAP | 3320 Paper Mill Rd | 6/3/2008 | | 0.29 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P123LNAP | 3320 Paper Mill Rd | 7/8/2008 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 8/5/2008 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 9/9/2008 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 10/7/2008 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 11/4/2008 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 12/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 1/6/2009 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 2/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 3/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P123LNAP | 3320 Paper Mill Rd | 4/7/2009 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 5/5/2009 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 6/2/2009 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 7/6/2009 | | 0.090 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 8/4/2009 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 9/1/2009 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 10/6/2009 | | 0.085 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 11/3/2009 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P123LNAP | 3320 Paper Mill Rd | 12/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L09 | 14100 Robcaste Rd | 3/8/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L09 | 14100 Robcaste Rd | 3/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L09 | 14100 Robcaste Rd | 4/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L09 | 14100 Robcaste Rd | 8/29/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L09 | 14100 Robcaste Rd | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L09 | 14100 Robcaste Rd | 8/7/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L09 | 14100 Robcaste Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P265L09 | 14100 Robcaste Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L09 | 14100 Robcaste Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L09 | 14100 Robcaste Rd | 7/17/2009 | | ND(0.50) | ND(0.50) | 0.067 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L08 | 14101 Robcaste Rd | 2/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L08 | 14101 Robcaste Rd | 3/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L08 | 14101 Robcaste Rd | 5/2/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L08 | 14101 Robcaste Rd | 8/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L08 | 14101 Robcaste Rd | 1/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L08 | 14101 Robcaste Rd | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L08 | 14101 Robcaste Rd | 1/14/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P265L08 | 14101 Robcaste Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P265L08 | 14101 Robcaste Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L08 | 14101 Robcaste Rd | 7/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P386LNA | 14102 Robcaste Rd | 3/29/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P386LNA | 14102 Robcaste Rd | 4/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P386LNA | 14102 Robcaste Rd | 8/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P386LNA | 14102 Robcaste Rd | 1/27/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P386LNA | 14102 Robcaste Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P386LNA | 14102 Robcaste Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P386LNA | 14102 Robcaste Rd | 12/10/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P386LNA | 14102 Robcaste Rd | 7/22/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P386LNA | 14102 Robcaste Rd | 12/16/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L06 | 14103 Robcaste Rd | 2/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L06 | 14103 Robcaste Rd | 3/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L06 | 14103 Robcaste Rd | 4/25/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L06 | 14103 Robcaste Rd | 8/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L06 | 14103 Robcaste Rd | 1/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L06 | 14103 Robcaste Rd | 8/6/2007 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L06 | 14103 Robcaste Rd | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P265L06 | 14103 Robcaste Rd | 7/18/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L06 | 14103 Robcaste Rd | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L06 | 14103 Robcaste Rd | 7/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L10 | 14104 Robcaste Rd | 2/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L10 | 14104 Robcaste Rd | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L10 | 14104 Robcaste Rd | 4/25/2006 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L10 | 14104 Robcaste Rd | 8/16/2006 | | 0.20 J | ND(0.50) | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L10 | 14104 Robcaste Rd | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L10 | 14104 Robcaste Rd | 7/16/2007 | | 0.12 J | ND(0.50) | 0.077 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P265L10 | 14104 Robcaste Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P265L10 | 14104 Robcaste Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L10 | 14104 Robcaste Rd | 1/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L10 | 14104 Robcaste Rd | 7/8/2009 | | ND(0.50) | ND(0.50) | 0.083 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L04 | 14105 Robcaste Rd | 2/24/2006 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L04 | 14105 Robcaste Rd | 3/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L04 | 14105 Robcaste Rd | 4/25/2006 | | 0.65 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L04 | 14105 Robcaste Rd | 8/8/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L04 | 14105 Robcaste Rd | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L04 | 14105 Robcaste Rd | 7/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L04 | 14105 Robcaste Rd | 1/17/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P265L04 | 14105 Robcaste Rd | 7/15/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L04 | 14105 Robcaste Rd | 1/7/2009 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L04 | 14105 Robcaste Rd | 7/8/2009 | | 0.085 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L07 | 14106 Robcaste Rd | 2/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L07 | 14106 Robcaste Rd | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L07 | 14106 Robcaste Rd | 4/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L07 | 14106 Robcaste Rd | 8/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L07 | 14106 Robcaste Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L07 | 14106 Robcaste Rd | 7/16/2007 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L07 | 14106 Robcaste Rd | 1/14/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P265L07 | 14106 Robcaste Rd | 7/17/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L07 | 14106 Robcaste Rd | 1/7/2009 | | 0.088 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L07 | 14106 Robcaste Rd | 7/9/2009 | | ND(0.50) | ND(0.50) | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L03 | 14107 Robcaste Rd | 2/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L03 | 14107 Robcaste Rd | 3/29/2006 | | 0.64 | ND(0.50) | 0.099 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.23 J | ND(5.0) |
| M35P265L03 | 14107 Robcaste Rd | 4/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P265L03 | 14107 Robcaste Rd | 8/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L03 | 14107 Robcaste Rd | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L03 | 14107 Robcaste Rd | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L03 | 14107 Robcaste Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P265L03 | 14107 Robcaste Rd | 1/16/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L03 | 14107 Robcaste Rd | 7/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L02 | 14109 Robcaste Rd | 2/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L02 | 14109 Robcaste Rd | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L02 | 14109 Robcaste Rd | 4/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L02 | 14109 Robcaste Rd | 8/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L02 | 14109 Robcaste Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L02 | 14109 Robcaste Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L02 | 14109 Robcaste Rd | 1/14/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P265L02 | 14109 Robcaste Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L02 | 14109 Robcaste Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L02 | 14109 Robcaste Rd | 7/10/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L05 | 14110 Robcaste Rd | 2/24/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L05 | 14110 Robcaste Rd | 3/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L05 | 14110 Robcaste Rd | 5/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L05 | 14110 Robcaste Rd | 8/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L05 | 14110 Robcaste Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L05 | 14110 Robcaste Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L05 | 14110 Robcaste Rd | 1/14/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P265L05 | 14110 Robcaste Rd | 7/17/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L05 | 14110 Robcaste Rd | 1/16/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L05 | 14110 Robcaste Rd | 7/10/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L01 | 14111 Robcaste Rd | 2/24/2006 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P265L01 | 14111 Robcaste Rd | 3/27/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L01 | 14111 Robcaste Rd | 4/24/2006 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L01 | 14111 Robcaste Rd | 8/18/2006 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L01 | 14111 Robcaste Rd | 1/29/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L01 | 14111 Robcaste Rd | 7/20/2007 | | 0.24 J | ND(0.50) | 0.050 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L01 | 14111 Robcaste Rd | 1/18/2008 | | 0.59 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L01 | 14111 Robcaste Rd | 1/14/2009 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P265L01 | 14111 Robcaste Rd | 7/8/2009 | | 0.37 J | ND(0.50) | 0.092 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L13 | 14200 Robcaste Rd | 2/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L13 | 14200 Robcaste Rd | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L13 | 14200 Robcaste Rd | 4/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L13 | 14200 Robcaste Rd | 8/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L13 | 14200 Robcaste Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L13 | 14200 Robcaste Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L13 | 14200 Robcaste Rd | 1/14/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L13 | 14200 Robcaste Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L13 | 14200 Robcaste Rd | 1/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L13 | 14200 Robcaste Rd | 7/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L12 | 14201 Robcaste Rd | 2/27/2006 | | 0.47 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L12 | 14201 Robcaste Rd | 3/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L12 | 14201 Robcaste Rd | 4/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L12 | 14201 Robcaste Rd | 8/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L12 | 14201 Robcaste Rd | 1/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L12 | 14201 Robcaste Rd | 7/21/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L12 | 14201 Robcaste Rd | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L12 | 14201 Robcaste Rd | 7/16/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L12 | 14201 Robcaste Rd | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L12 | 14201 Robcaste Rd | 7/10/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L14 | 14202 Robcaste Rd | 4/24/2006 | | ND(0.50) | ND(0.50) | 0.96 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L14 | 14202 Robcaste Rd | 8/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L14 | 14202 Robcaste Rd | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L14 | 14202 Robcaste Rd | 7/20/2007 | | 0.083 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L14 | 14202 Robcaste Rd | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L14 | 14202 Robcaste Rd | 7/17/2008 | | 0.076 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L14 | 14202 Robcaste Rd | 1/8/2009 | | 0.087 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L14 | 14202 Robcaste Rd | 7/13/2009 | | 0.092 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.1 J |
| M35P322L11 | 14203 Robcaste Rd | 2/27/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L11 | 14203 Robcaste Rd | 3/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L11 | 14203 Robcaste Rd | 4/25/2006 | | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L11 | 14203 Robcaste Rd | 6/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L11 | 14203 Robcaste Rd | 8/17/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L11 | 14203 Robcaste Rd | 1/29/2007 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L11 | 14203 Robcaste Rd | 4/17/2007 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L11 | 14203 Robcaste Rd | 7/19/2007 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L11 | 14203 Robcaste Rd | 10/22/2007 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L11 | 14203 Robcaste Rd | 1/14/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L11 | 14203 Robcaste Rd | 4/2/2008 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L11 | 14203 Robcaste Rd | 7/16/2008 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L11 | 14203 Robcaste Rd | 10/8/2008 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L11 | 14203 Robcaste Rd | 1/13/2009 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L11 | 14203 Robcaste Rd | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L11 | 14203 Robcaste Rd | 7/15/2009 | | 0.098 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L11 | 14203 Robcaste Rd | 10/8/2009 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L15 | 14204 Robcaste Rd | 2/23/2006 | | 0.76 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L15 | 14204 Robcaste Rd | 3/28/2006 | | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L15 | 14204 Robcaste Rd | 4/25/2006 | | 1.4 | ND(0.50) | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L15 | 14204 Robcaste Rd | 6/15/2006 | | 0.92 | ND(0.50) | 0.31 J | ND(0.50) | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L15 | 14204 Robcaste Rd | 8/18/2006 | | 1.5 | ND(0.50) | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L15 | 14204 Robcaste Rd | 1/25/2007 | | 0.72 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.20 J | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L15 | 14204 Robcaste Rd | 4/9/2007 | | 0.64 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.25 J | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L15 | 14204 Robcaste Rd | 7/19/2007 | | 1.2 | ND(0.50) | 0.28 J | ND(0.50) | 0.12 J | ND(0.50) | 0.92 | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L15 | 14204 Robcaste Rd | 10/22/2007 | | 1.5 | 0.10 J | 0.31 J | ND(0.50) | 0.11 J | ND(0.50) | 0.66 | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L15 | 14204 Robcaste Rd | 1/14/2008 | | 1.2 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L15 | 14204 Robcaste Rd | 4/2/2008 | | 0.95 | ND(0.50) | 0.071 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L15 | 14204 Robcaste Rd | 7/16/2008 | | 0.66 | ND(0.50) | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L15 | 14204 Robcaste Rd | 10/21/2008 | | 0.75 | ND(0.50) | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L15 | 14204 Robcaste Rd | 1/13/2009 | | 0.77 | ND(0.50) | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L15 | 14204 Robcaste Rd | 4/2/2009 | | 0.54 | ND(0.50) | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L15 | 14204 Robcaste Rd | 7/8/2009 | | 0.40 J | ND(0.50) | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L15 | 14204 Robcaste Rd | 10/7/2009 | | 0.66 | ND(0.50) | 0.082 J | ND(0.50) | ND(0.50) | ND(0.50) | 0.34 J | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L10 | 14205 Robcaste Rd | 2/24/2006 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L10 | 14205 Robcaste Rd | 3/27/2006 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L10 | 14205 Robcaste Rd | 4/28/2006 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L10 | 14205 Robcaste Rd | 6/12/2006 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L10 | 14205 Robcaste Rd | 8/14/2006 | | 2.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.33 J | ND(5.0) |
| M35P322L10 | 14205 Robcaste Rd | 1/24/2007 | | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L10 | 14205 Robcaste Rd | 4/9/2007 | | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.18 J | ND(5.0) |
| M35P322L10 | 14205 Robcaste Rd | 7/21/2007 | | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.080 J | ND(5.0) |
| M35P322L10 | 14205 Robcaste Rd | 10/22/2007 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L10 | 14205 Robcaste Rd | 1/21/2008 | | 2.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L10 | 14205 Robcaste Rd | 4/4/2008 | | 2.5 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L10 | 14205 Robcaste Rd | 7/22/2008 | | 3.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L10 | 14205 Robcaste Rd | 10/8/2008 | | 2.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L10 | 14205 Robcaste Rd | 1/12/2009 | | 3.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L10 | 14205 Robcaste Rd | 4/2/2009 | | 2.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L10 | 14205 Robcaste Rd | 7/9/2009 | | 3.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L10 | 14205 Robcaste Rd | 10/9/2009 | | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L16 | 14206 Robcaste Rd | 2/24/2006 | | 0.64 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L16 | 14206 Robcaste Rd | 3/28/2006 | | 0.72 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L16 | 14206 Robcaste Rd | 4/25/2006 | | 0.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L16 | 14206 Robcaste Rd | 6/12/2006 | | 0.69 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L16 | 14206 Robcaste Rd | 8/15/2006 | | 0.71 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L16 | 14206 Robcaste Rd | 1/26/2007 | | 0.89 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L16 | 14206 Robcaste Rd | 4/9/2007 | | 0.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L16 | 14206 Robcaste Rd | 7/16/2007 | | 0.84 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L16 | 14206 Robcaste Rd | 10/22/2007 | | 0.82 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L16 | 14206 Robcaste Rd | 1/14/2008 | | 0.85 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L16 | 14206 Robcaste Rd | 4/1/2008 | | 0.83 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L16 | 14206 Robcaste Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L16 | 14206 Robcaste Rd | 10/9/2008 | | 0.68 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L16 | 14206 Robcaste Rd | 1/12/2009 | | 0.71 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L16 | 14206 Robcaste Rd | 4/1/2009 | | 0.57 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L16 | 14206 Robcaste Rd | 7/8/2009 | | 0.51 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L16 | 14206 Robcaste Rd | 10/8/2009 | | 0.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P329L21 | 14207 Robcaste Rd | 2/23/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P329L21 | 14207 Robcaste Rd | 3/28/2006 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P329L21 | 14207 Robcaste Rd | 4/25/2006 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P329L21 | 14207 Robcaste Rd | 6/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P329L21 | 14207 Robcaste Rd | 8/15/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P329L21 | 14207 Robcaste Rd | 1/25/2007 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P329L21 | 14207 Robcaste Rd | 4/9/2007 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P329L21 | 14207 Robcaste Rd | 8/20/2007 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P329L21 | 14207 Robcaste Rd | 10/22/2007 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P329L21 | 14207 Robcaste Rd | 1/14/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P329L21 | 14207 Robcaste Rd | 4/2/2008 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P329L21 | 14207 Robcaste Rd | 7/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P329L21 | 14207 Robcaste Rd | 10/10/2008 | | 0.11 J | ND(0.50) | 0.069 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P329L21 | 14207 Robcaste Rd | 1/12/2009 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P329L21 | 14207 Robcaste Rd | 4/10/2009 | | 0.14 J | ND(0.50) | 0.063 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P329L21 | 14207 Robcaste Rd | 7/8/2009 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P329L21 | 14207 Robcaste Rd | 10/8/2009 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L17 | 14208 Robcaste Rd | 2/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L17 | 14208 Robcaste Rd | 4/1/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L17 | 14208 Robcaste Rd | 5/1/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L17 | 14208 Robcaste Rd | 6/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L17 | 14208 Robcaste Rd | 8/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L17 | 14208 Robcaste Rd | 1/27/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L17 | 14208 Robcaste Rd | 4/9/2007 | | ND(0.50) | ND(0.50) | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L17 | 14208 Robcaste Rd | 7/21/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L17 | 14208 Robcaste Rd | 10/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L17 | 14208 Robcaste Rd | 1/14/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L17 | 14208 Robcaste Rd | 4/3/2008 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L17 | 14208 Robcaste Rd | 7/16/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L17 | 14208 Robcaste Rd | 10/9/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L17 | 14208 Robcaste Rd | 1/13/2009 | | 0.068 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L17 | 14208 Robcaste Rd | 4/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L17 | 14208 Robcaste Rd | 7/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L17 | 14208 Robcaste Rd | 10/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 3/1/2006 | | 0.23 J | ND(0.50) | 3.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 3/16/2006 | | 0.6 | ND(0.50) | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 3/23/2006 | | 0.45 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 3/30/2006 | | 0.51 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 4/6/2006 | | 0.62 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 4/13/2006 | | 0.53 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 4/20/2006 | | 0.65 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 4/27/2006 | | 0.57 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 5/2/2006 | | 0.56 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 5/9/2006 | | 0.54 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 5/16/2006 | | 0.51 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 5/23/2006 | | 0.58 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 5/30/2006 | | 0.72 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 6/6/2006 | | 0.57 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 6/13/2006 | | 0.54 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 6/20/2006 | | 0.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 6/26/2006 | | 0.45 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 7/6/2006 | | 0.44 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 7/11/2006 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 7/18/2006 | | 0.69 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 7/25/2006 | | 0.73 | ND(0.50) | ND(0.50) | ND(0.50) | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 8/1/2006 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 8/8/2006 | | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 8/15/2006 | | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L18 | 14210 Robcaste Rd | 8/22/2006 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 8/29/2006 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 9/5/2006 | | 0.93 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 9/12/2006 | | 0.74 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 9/19/2006 | | 0.76 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 9/26/2006 | | 0.51 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 10/3/2006 | | 0.55 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 10/10/2006 | | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 10/17/2006 | | 0.47 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 10/24/2006 | | 0.44 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 10/31/2006 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 11/7/2006 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 11/14/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 11/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 12/5/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 12/12/2006 | | 0.46 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 12/19/2006 | | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 1/9/2007 | | 0.53 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 1/23/2007 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 2/6/2007 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 2/20/2007 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 3/6/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 3/20/2007 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 4/3/2007 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 4/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 5/1/2007 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 5/15/2007 | | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L18 | 14210 Robcaste Rd | 5/29/2007 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 6/12/2007 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 6/26/2007 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 7/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 7/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 8/7/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 8/21/2007 | PIO | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 9/4/2007 | PIO | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 9/18/2007 | PIO | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 10/2/2007 | PIO | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 10/16/2007 | PIO | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 10/30/2007 | PIO | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 11/13/2007 | | 0.092 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 11/27/2007 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 12/11/2007 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L18 | 14210 Robcaste Rd | 1/8/2008 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 2/5/2008 | | 0.12 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L18 | 14210 Robcaste Rd | 3/4/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L18 | 14210 Robcaste Rd | 4/8/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L18 | 14210 Robcaste Rd | 5/6/2008 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 6/3/2008 | | 0.086 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L18 | 14210 Robcaste Rd | 7/8/2008 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 8/15/2008 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 9/9/2008 | | 0.091 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 10/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 11/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 12/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L18 | 14210 Robcaste Rd | 1/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 2/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 3/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 4/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 5/5/2009 | | ND(0.50) | ND(0.50) | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 6/2/2009 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 7/7/2009 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 8/4/2009 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 9/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 10/6/2009 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 11/3/2009 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L18 | 14210 Robcaste Rd | 12/8/2009 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L08 | 14211 Robcaste Rd | 2/23/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L08 | 14211 Robcaste Rd | 4/3/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L08 | 14211 Robcaste Rd | 4/25/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L08 | 14211 Robcaste Rd | 6/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L08 | 14211 Robcaste Rd | 8/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L08 | 14211 Robcaste Rd | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L08 | 14211 Robcaste Rd | 4/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L08 | 14211 Robcaste Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L08 | 14211 Robcaste Rd | 10/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L08 | 14211 Robcaste Rd | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L08 | 14211 Robcaste Rd | 7/16/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L08 | 14211 Robcaste Rd | 10/9/2008 | | ND(0.50) | ND(0.50) | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 2/24/2006 | | 0.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 3/30/2006 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 4/6/2006 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L19 | 14212 Robcaste Rd | 4/13/2006 | | 0.48 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 4/27/2006 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 5/1/2006 | | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 5/8/2006 | | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 5/15/2006 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 5/22/2006 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 5/31/2006 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 6/5/2006 | | 0.32 J | ND(0.50) | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 6/13/2006 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 6/19/2006 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 6/26/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 7/6/2006 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 7/10/2006 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 7/17/2006 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 7/31/2006 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 8/7/2006 | | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 8/15/2006 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 8/21/2006 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 8/28/2006 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 9/6/2006 | | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 9/11/2006 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 9/18/2006 | | 0.44 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 9/25/2006 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 10/2/2006 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 10/9/2006 | | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 10/16/2006 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 10/23/2006 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L19 | 14212 Robcaste Rd | 10/30/2006 | | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 11/6/2006 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 11/13/2006 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 11/20/2006 | | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 11/27/2006 | | 0.46 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 12/4/2006 | | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 12/12/2006 | | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 12/18/2006 | | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 1/8/2007 | | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 1/22/2007 | | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 2/5/2007 | | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 2/21/2007 | | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 3/5/2007 | | 0.46 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 3/19/2007 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 4/2/2007 | | 0.52 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 4/16/2007 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 4/30/2007 | | 0.41 J | ND(0.50) | 0.095 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 5/14/2007 | | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 5/30/2007 | | 0.47 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 6/12/2007 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 6/25/2007 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 7/9/2007 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 7/23/2007 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 8/6/2007 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 8/20/2007 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 9/5/2007 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 9/17/2007 | | 0.44 J | ND(0.50) | 0.55 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L19 | 14212 Robcaste Rd | 10/1/2007 | | 0.45 J | ND(0.50) | 0.093 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 10/15/2007 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 10/29/2007 | | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 11/12/2007 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 12/10/2007 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 1/7/2008 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 2/4/2008 | | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 3/3/2008 | | 0.46 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L19 | 14212 Robcaste Rd | 4/7/2008 | | 0.51 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 5/5/2008 | | 0.39 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L19 | 14212 Robcaste Rd | 6/2/2008 | | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 7/14/2008 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 8/5/2008 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 9/8/2008 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 10/6/2008 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 11/3/2008 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 12/1/2008 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 1/6/2009 | | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 2/2/2009 | | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 3/6/2009 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 4/6/2009 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 5/4/2009 | | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 6/1/2009 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 7/6/2009 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 8/3/2009 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 8/31/2009 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 10/5/2009 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L19 | 14212 Robcaste Rd | 11/2/2009 | | 0.47 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L19 | 14212 Robcaste Rd | 12/7/2009 | | 0.51 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L07 | 14213 Robcaste Rd | 2/24/2006 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L07 | 14213 Robcaste Rd | 3/28/2006 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L07 | 14213 Robcaste Rd | 4/24/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L07 | 14213 Robcaste Rd | 6/13/2006 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L07 | 14213 Robcaste Rd | 1/22/2007 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.5 J |
| M35P322L07 | 14213 Robcaste Rd | 4/10/2007 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L07 | 14213 Robcaste Rd | 7/17/2007 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 17.2 |
| M35P322L07 | 14213 Robcaste Rd | 10/23/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L07 | 14213 Robcaste Rd | 4/2/2008 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L07 | 14213 Robcaste Rd | 8/5/2008 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 2.6 J |
| M35P322L07 | 14213 Robcaste Rd | 4/1/2009 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L07 | 14213 Robcaste Rd | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L07 | 14213 Robcaste Rd | 10/7/2009 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L20 | 14214 Robcaste Rd | 2/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L20 | 14214 Robcaste Rd | 4/1/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L20 | 14214 Robcaste Rd | 4/13/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L20 | 14214 Robcaste Rd | 6/20/2006 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L20 | 14214 Robcaste Rd | 8/15/2006 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L20 | 14214 Robcaste Rd | 2/5/2007 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L20 | 14214 Robcaste Rd | 4/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L20 | 14214 Robcaste Rd | 7/21/2007 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L20 | 14214 Robcaste Rd | 10/23/2007 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L20 | 14214 Robcaste Rd | 1/14/2008 | | 0.23 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L20 | 14214 Robcaste Rd | 7/23/2008 | | 0.079 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L20 | 14214 Robcaste Rd | 10/9/2008 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L20 | 14214 Robcaste Rd | 1/13/2009 | | 0.091 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L20 | 14214 Robcaste Rd | 4/3/2009 | | ND(0.50) | ND(0.50) | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L20 | 14214 Robcaste Rd | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L20 | 14214 Robcaste Rd | 10/9/2009 | | ND(0.50) | ND(0.50) | 0.057 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L06 | 14215 Robcaste Rd | 2/24/2006 | | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L06 | 14215 Robcaste Rd | 3/27/2006 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L06 | 14215 Robcaste Rd | 4/26/2006 | | 0.52 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L06 | 14215 Robcaste Rd | 6/16/2006 | | 0.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L06 | 14215 Robcaste Rd | 8/15/2006 | | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L06 | 14215 Robcaste Rd | 1/26/2007 | | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L06 | 14215 Robcaste Rd | 4/9/2007 | | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L06 | 14215 Robcaste Rd | 7/19/2007 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L06 | 14215 Robcaste Rd | 10/22/2007 | | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L06 | 14215 Robcaste Rd | 1/14/2008 | | 0.41 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L06 | 14215 Robcaste Rd | 4/2/2008 | | 0.46 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L06 | 14215 Robcaste Rd | 7/16/2008 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L06 | 14215 Robcaste Rd | 10/8/2008 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L06 | 14215 Robcaste Rd | 1/12/2009 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L06 | 14215 Robcaste Rd | 4/2/2009 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L06 | 14215 Robcaste Rd | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L06 | 14215 Robcaste Rd | 10/7/2009 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L05 | 14217 Robcaste Rd | 2/25/2006 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L05 | 14217 Robcaste Rd | 3/27/2006 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L05 | 14217 Robcaste Rd | 4/25/2006 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L05 | 14217 Robcaste Rd | 6/13/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L05 | 14217 Robcaste Rd | 8/22/2006 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L05 | 14217 Robcaste Rd | 1/23/2007 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L05 | 14217 Robcaste Rd | 4/9/2007 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L05 | 14217 Robcaste Rd | 7/16/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L05 | 14217 Robcaste Rd | 10/22/2007 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L05 | 14217 Robcaste Rd | 1/18/2008 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L05 | 14217 Robcaste Rd | 4/2/2008 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L05 | 14217 Robcaste Rd | 10/8/2008 | | 0.078 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L05 | 14217 Robcaste Rd | 1/14/2009 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L05 | 14217 Robcaste Rd | 4/3/2009 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L05 | 14217 Robcaste Rd | 7/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L05 | 14217 Robcaste Rd | 10/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L04 | 14219 Robcaste Rd | 2/23/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L04 | 14219 Robcaste Rd | 3/27/2006 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L04 | 14219 Robcaste Rd | 4/25/2006 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L04 | 14219 Robcaste Rd | 6/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L04 | 14219 Robcaste Rd | 8/16/2006 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L04 | 14219 Robcaste Rd | 1/25/2007 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L04 | 14219 Robcaste Rd | 4/10/2007 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L04 | 14219 Robcaste Rd | 7/17/2007 | | 0.099 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L04 | 14219 Robcaste Rd | 1/18/2008 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L04 | 14219 Robcaste Rd | 4/3/2008 | | 0.13 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L04 | 14219 Robcaste Rd | 10/6/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L04 | 14219 Robcaste Rd | 1/21/2009 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L04 | 14219 Robcaste Rd | 4/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L04 | 14219 Robcaste Rd | 7/8/2009 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L04 | 14219 Robcaste Rd | 10/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 2/24/2006 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 3/8/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L03 | 14221 Robcaste Rd | 3/15/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 3/22/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 3/29/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 4/5/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 4/12/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 4/20/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 4/26/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 5/2/2006 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 5/9/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 5/16/2006 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 5/23/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 5/31/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 6/6/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 6/13/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 6/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 6/27/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 7/6/2006 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 7/11/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 7/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 7/25/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 8/1/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 8/15/2006 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 8/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 8/29/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 9/5/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 9/12/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 9/19/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L03 | 14221 Robcaste Rd | 9/26/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 10/3/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 10/10/2006 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 10/17/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 10/24/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 11/7/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 11/14/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 11/21/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 11/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 12/5/2006 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 12/12/2006 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 12/19/2006 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 1/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 1/23/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 2/6/2007 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 2/20/2007 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 3/6/2007 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 3/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 4/3/2007 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 4/17/2007 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 5/1/2007 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 5/15/2007 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 5/29/2007 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 6/12/2007 | | 0.088 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 6/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 7/17/2007 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 7/24/2007 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L03 | 14221 Robcaste Rd | 8/7/2007 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 8/21/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 9/4/2007 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 9/18/2007 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 10/2/2007 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 10/16/2007 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 10/30/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 11/13/2007 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 11/27/2007 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 12/11/2007 | | 0.2 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L03 | 14221 Robcaste Rd | 1/8/2008 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 2/5/2008 | | 0.32 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L03 | 14221 Robcaste Rd | 3/4/2008 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 4/8/2008 | | 0.18 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L03 | 14221 Robcaste Rd | 5/6/2008 | | 0.18 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L03 | 14221 Robcaste Rd | 6/3/2008 | | 0.13 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L03 | 14221 Robcaste Rd | 7/8/2008 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 8/5/2008 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 9/9/2008 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 10/7/2008 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 11/4/2008 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 12/2/2008 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 1/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 2/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 3/3/2009 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 4/7/2009 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 5/5/2009 | | 0.090 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L03 | 14221 Robcaste Rd | 6/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 7/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 9/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 10/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 11/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L03 | 14221 Robcaste Rd | 12/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 2/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 3/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 3/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 3/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 3/30/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 4/3/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 4/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 4/10/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 4/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 4/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 4/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 4/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 5/1/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 5/4/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 5/8/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 5/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 5/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 5/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 5/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 5/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L02 | 14223 Robcaste Rd | 5/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 6/1/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 6/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 6/8/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 6/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 6/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 6/26/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 7/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 7/10/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 7/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 7/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 8/7/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 8/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 8/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 9/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 9/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 9/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 9/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 10/2/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 10/9/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 10/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 10/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 10/30/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 11/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 11/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 11/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 11/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L02 | 14223 Robcaste Rd | 12/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 12/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 12/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 1/8/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 2/5/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 2/21/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 3/5/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 3/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 4/2/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 4/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 4/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 5/14/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 5/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 6/11/2007 | | ND(0.50) | ND(0.50) | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 6/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 7/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 7/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 8/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 8/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 9/5/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 9/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 10/1/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 10/15/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 10/29/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 11/12/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 11/26/2007 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L02 | 14223 Robcaste Rd | 12/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 1/7/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L02 | 14223 Robcaste Rd | 2/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 3/3/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L02 | 14223 Robcaste Rd | 4/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 5/5/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 6/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 7/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 8/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 9/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 10/6/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 11/3/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 12/1/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 1/5/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 2/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 3/4/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 4/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 5/4/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 6/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 7/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 8/4/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 8/31/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 10/5/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 11/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L02 | 14223 Robcaste Rd | 12/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 2/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 3/7/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L01 | 14225 Robcaste Rd | 3/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 3/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 3/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 4/4/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 4/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 4/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 5/2/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 5/9/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 5/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 5/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 5/30/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 6/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 6/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 6/20/2006 | | ND(0.50) | ND(0.50) | 0.089 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 7/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 7/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 7/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 7/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 8/1/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 8/8/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 8/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 8/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 8/29/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 9/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 9/12/2006 | | ND(0.50) | ND(0.50) | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 9/26/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L01 | 14225 Robcaste Rd | 10/3/2006 | | ND(0.50) | ND(0.50) | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 10/10/2006 | | ND(0.50) | ND(0.50) | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 10/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 10/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 10/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 11/7/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 11/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 11/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 11/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 12/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 12/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 12/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 1/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 2/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 2/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 3/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 3/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 4/3/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 4/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 5/1/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 5/15/2007 | | ND(0.50) | ND(0.50) | 0.066 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 5/29/2007 | | ND(0.50) | ND(0.50) | 0.097 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 6/12/2007 | | ND(0.50) | ND(0.50) | 0.073 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 7/10/2007 | | ND(0.50) | ND(0.50) | 0.060 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 7/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 8/7/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L01 | 14225 Robcaste Rd | 8/21/2007 | | ND(0.50) | ND(0.50) | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 9/4/2007 | | ND(0.50) | ND(0.50) | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 9/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 10/2/2007 | | ND(0.50) | ND(0.50) | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 10/16/2007 | | ND(0.50) | ND(0.50) | 0.058 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 10/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 11/13/2007 | | ND(0.50) | ND(0.50) | 0.057 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 11/27/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 12/11/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 1/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 2/5/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 3/4/2008 | | 0.09 J | ND(0.5) | 0.11 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 2.1 J |
| M35P322L01 | 14225 Robcaste Rd | 4/8/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L01 | 14225 Robcaste Rd | 5/6/2008 | | ND(0.5) | ND(0.5) | 0.36 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L01 | 14225 Robcaste Rd | 6/3/2008 | | ND(0.5) | ND(0.5) | 0.59 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P322L01 | 14225 Robcaste Rd | 7/8/2008 | | ND(0.50) | ND(0.50) | 0.61 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 8/5/2008 | | ND(0.50) | ND(0.50) | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 9/9/2008 | | ND(0.50) | ND(0.50) | 0.87 | ND(0.50) | 0.087 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 10/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 11/4/2008 | | 0.091 J | ND(0.50) | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 12/2/2008 | | ND(0.50) | ND(0.50) | 0.067 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 1/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 2/3/2009 | | ND(0.50) | ND(0.50) | 0.16 J | ND(0.50) | 0.080 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 3/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 4/7/2009 | | ND(0.50) | ND(0.50) | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 5/5/2009 | | ND(0.50) | ND(0.50) | 0.6 | 0.19 J | 0.68 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 6/2/2009 | | ND(0.50) | ND(0.50) | 0.56 | 0.14 J | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P322L01 | 14225 Robcaste Rd | 7/7/2009 | | ND(0.50) | ND(0.50) | 0.67 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 8/4/2009 | | ND(0.50) | ND(0.50) | 14 | ND(0.50) | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 9/1/2009 | | ND(0.50) | ND(0.50) | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 10/6/2009 | | ND(0.50) | ND(0.50) | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 11/3/2009 | | ND(0.50) | ND(0.50) | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P322L01 | 14225 Robcaste Rd | 12/8/2009 | | ND(0.50) | ND(0.50) | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L03 | 14300 Robcaste Rd | 3/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L03 | 14300 Robcaste Rd | 1/25/2007 | | 3.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L03 | 14300 Robcaste Rd | 4/10/2007 | | 3.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.32 J | ND(5.0) |
| M35P310L03 | 14300 Robcaste Rd | 7/19/2007 | | 3.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.25 J | ND(5.0) |
| M35P310L03 | 14300 Robcaste Rd | 10/22/2007 | | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.094 J | ND(5.0) |
| M35P310L03 | 14300 Robcaste Rd | 1/14/2008 | | 1.1 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P310L03 | 14300 Robcaste Rd | 4/1/2008 | | 0.89 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P310L03 | 14300 Robcaste Rd | 7/16/2008 | | 0.89 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L03 | 14300 Robcaste Rd | 10/9/2008 | | 0.73 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L03 | 14300 Robcaste Rd | 1/12/2009 | | 0.71 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L03 | 14300 Robcaste Rd | 4/1/2009 | | 0.67 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L03 | 14300 Robcaste Rd | 7/8/2009 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P310L03 | 14300 Robcaste Rd | 10/7/2009 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L03 | 14302 Robcaste Rd | 3/15/2006 | | 3.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.20 J | ND(5.0) |
| M35P028L03 | 14302 Robcaste Rd | 1/25/2007 | | 3.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L03 | 14302 Robcaste Rd | 4/9/2007 | | 4.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.27 J | ND(5.0) |
| M35P028L03 | 14302 Robcaste Rd | 7/17/2007 | | 3.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.16 J | ND(5.0) |
| M35P028L03 | 14302 Robcaste Rd | 10/23/2007 | | 4.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.16 J | ND(5.0) |
| M35P028L03 | 14302 Robcaste Rd | 1/14/2008 | | 3.9 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.12 J | ND(5) |
| M35P028L03 | 14302 Robcaste Rd | 4/1/2008 | | 3.1 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.13 J | ND(5) |
| M35P028L03 | 14302 Robcaste Rd | 7/18/2008 | | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P028L03 | 14302 Robcaste Rd | 10/9/2008 | | 2.1 | ND(0.50) | 0.066 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L03 | 14302 Robcaste Rd | 1/14/2009 | | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L03 | 14302 Robcaste Rd | 4/2/2009 | | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L03 | 14302 Robcaste Rd | 7/15/2009 | | 1.5 | ND(0.50) | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L03 | 14302 Robcaste Rd | 10/7/2009 | | 1.5 | ND(0.50) | 0.069 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L09 | 14303 Robcaste Rd | 3/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L09 | 14303 Robcaste Rd | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L09 | 14303 Robcaste Rd | 4/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L09 | 14303 Robcaste Rd | 8/6/2007 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L09 | 14303 Robcaste Rd | 10/29/2007 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L09 | 14303 Robcaste Rd | 1/14/2008 | | 0.24 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P028L09 | 14303 Robcaste Rd | 4/1/2008 | | 0.21 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P028L09 | 14303 Robcaste Rd | 7/17/2008 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L09 | 14303 Robcaste Rd | 10/8/2008 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L09 | 14303 Robcaste Rd | 1/13/2009 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L09 | 14303 Robcaste Rd | 4/1/2009 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L09 | 14303 Robcaste Rd | 7/9/2009 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L09 | 14303 Robcaste Rd | 10/9/2009 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L04 | 14304 Robcaste Rd | 3/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L04 | 14304 Robcaste Rd | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L04 | 14304 Robcaste Rd | 4/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L04 | 14304 Robcaste Rd | 7/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L04 | 14304 Robcaste Rd | 10/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L04 | 14304 Robcaste Rd | 1/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L04 | 14304 Robcaste Rd | 4/1/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P028L04 | 14304 Robcaste Rd | 7/16/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L04 | 14304 Robcaste Rd | 10/9/2008 | | ND(0.50) | ND(0.50) | 0.072 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P028L04 | 14304 Robcaste Rd | 1/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L04 | 14304 Robcaste Rd | 4/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L04 | 14304 Robcaste Rd | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L04 | 14304 Robcaste Rd | 10/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L08 | 14305 Robcaste Rd | 3/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L08 | 14305 Robcaste Rd | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L08 | 14305 Robcaste Rd | 4/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L08 | 14305 Robcaste Rd | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L08 | 14305 Robcaste Rd | 10/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L08 | 14305 Robcaste Rd | 1/14/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P028L08 | 14305 Robcaste Rd | 4/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L08 | 14305 Robcaste Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L08 | 14305 Robcaste Rd | 10/9/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L08 | 14305 Robcaste Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L08 | 14305 Robcaste Rd | 4/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L08 | 14305 Robcaste Rd | 7/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L08 | 14305 Robcaste Rd | 10/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L05 | 14306 Robcaste Rd | 3/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L05 | 14306 Robcaste Rd | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L05 | 14306 Robcaste Rd | 4/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L05 | 14306 Robcaste Rd | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L05 | 14306 Robcaste Rd | 10/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L05 | 14306 Robcaste Rd | 1/14/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P028L05 | 14306 Robcaste Rd | 4/1/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P028L05 | 14306 Robcaste Rd | 7/16/2008 | | ND(0.50) | ND(0.50) | 0.050 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L05 | 14306 Robcaste Rd | 10/9/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L05 | 14306 Robcaste Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P028L05 | 14306 Robcaste Rd | 4/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L05 | 14306 Robcaste Rd | 7/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L05 | 14306 Robcaste Rd | 10/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 3/18/2006 | | 5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.19 J | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 1/25/2007 | | 4.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 4/9/2007 | | 7.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.36 J | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 7/19/2007 | | 13.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.56 | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 8/20/2007 | | 11.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.51 | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 10/2/2007 | | 12.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.49 J | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 10/15/2007 | | 13.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.38 J | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 10/29/2007 | | 12.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.49 J | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 11/12/2007 | | 15 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.43 J | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 12/10/2007 | | 13.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.58 | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 1/7/2008 | | 13.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.46 J | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 1/14/2008 | | 15.1 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.6 | ND(5) |
| M35P028L07 | 14307 Robcaste Rd | 2/5/2008 | | 13.6 | ND(0.50) | 26.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.64 | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 5/5/2008 | | 4.7 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 0.21 J | ND(5) |
| M35P028L07 | 14307 Robcaste Rd | 6/2/2008 | | 3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 7/7/2008 | | 3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 8/4/2008 | | 3.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 9/8/2008 | | 5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.16 J | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 10/6/2008 | | 5.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.17 J | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 11/3/2008 | | 6.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.25 J | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 12/1/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 1/6/2009 | | 6.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.26 J | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 2/2/2009 | | 4.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.18 J | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 3/10/2009 | | 3.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P028L07 | 14307 Robcaste Rd | 4/6/2009 | | 4.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.16 J | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 5/4/2009 | | 4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.20 J | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 6/1/2009 | | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 7/7/2009 | | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 8/3/2009 | | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 8/31/2009 | | 3.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.10 J | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 10/5/2009 | | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 11/2/2009 | | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.074 J | ND(5.0) |
| M35P028L07 | 14307 Robcaste Rd | 12/7/2009 | | 0.68 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L06 | 14308 Robcaste Rd | 3/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L06 | 14308 Robcaste Rd | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L06 | 14308 Robcaste Rd | 4/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L06 | 14308 Robcaste Rd | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L06 | 14308 Robcaste Rd | 10/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L06 | 14308 Robcaste Rd | 1/14/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P028L06 | 14308 Robcaste Rd | 4/1/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P028L06 | 14308 Robcaste Rd | 7/16/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L06 | 14308 Robcaste Rd | 10/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L06 | 14308 Robcaste Rd | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L06 | 14308 Robcaste Rd | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L06 | 14308 Robcaste Rd | 7/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P028L06 | 14308 Robcaste Rd | 10/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P405L02 | 3517 Southside Ave | 5/31/2006 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P405L02 | 3517 Southside Ave | 8/29/2006 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P405L02 | 3517 Southside Ave | 2/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P405L02 | 3517 Southside Ave | 4/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P405L02 | 3517 Southside Ave | 7/21/2007 | | ND(0.50) | ND(0.50) | 0.045 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P405L02 | 3517 Southside Ave | 10/23/2007 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P405L02 | 3517 Southside Ave | 1/18/2008 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P405L02 | 3517 Southside Ave | 4/2/2008 | | 0.072 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P405L02 | 3517 Southside Ave | 7/22/2008 | | ND(0.50) | ND(0.50) | 0.071 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P405L02 | 3517 Southside Ave | 10/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P405L02 | 3517 Southside Ave | 1/16/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P405L02 | 3517 Southside Ave | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P405L02 | 3517 Southside Ave | 7/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P405L02 | 3517 Southside Ave | 10/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P399L01 | 3523 Southside Ave | 3/16/2006 | | 0.44 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P399L01 | 3523 Southside Ave | 6/16/2006 | | 0.76 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P399L01 | 3523 Southside Ave | 8/19/2006 | | 0.74 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P399L01 | 3523 Southside Ave | 1/27/2007 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P399L01 | 3523 Southside Ave | 7/21/2007 | | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P399L01 | 3523 Southside Ave | 10/23/2007 | | 0.47 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P399L01 | 3523 Southside Ave | 1/15/2008 | | 0.36 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P399L01 | 3523 Southside Ave | 4/3/2008 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P399L01 | 3523 Southside Ave | 7/14/2008 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P399L01 | 3523 Southside Ave | 10/9/2008 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P399L01 | 3523 Southside Ave | 1/13/2009 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P399L01 | 3523 Southside Ave | 4/1/2009 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P399L01 | 3523 Southside Ave | 7/14/2009 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P399L01 | 3523 Southside Ave | 10/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L03 | 3525 Southside Ave | 3/2/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L03 | 3525 Southside Ave | 3/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L03 | 3525 Southside Ave | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L03 | 3525 Southside Ave | 6/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P277L03 | 3525 Southside Ave | 8/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L03 | 3525 Southside Ave | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L03 | 3525 Southside Ave | 4/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L03 | 3525 Southside Ave | 7/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L03 | 3525 Southside Ave | 10/23/2007 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L03 | 3525 Southside Ave | 1/18/2008 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L03 | 3525 Southside Ave | 4/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L03 | 3525 Southside Ave | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L03 | 3525 Southside Ave | 10/9/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L03 | 3525 Southside Ave | 1/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L03 | 3525 Southside Ave | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L03 | 3525 Southside Ave | 7/10/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L03 | 3525 Southside Ave | 10/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L02 | 3527 Southside Ave | 3/2/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L02 | 3527 Southside Ave | 3/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L02 | 3527 Southside Ave | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L02 | 3527 Southside Ave | 6/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L02 | 3527 Southside Ave | 8/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L02 | 3527 Southside Ave | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L02 | 3527 Southside Ave | 4/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L02 | 3527 Southside Ave | 7/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L02 | 3527 Southside Ave | 10/23/2007 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L02 | 3527 Southside Ave | 1/17/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P277L02 | 3527 Southside Ave | 4/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L02 | 3527 Southside Ave | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L02 | 3527 Southside Ave | 10/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L02 | 3527 Southside Ave | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P277L02 | 3527 Southside Ave | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L02 | 3527 Southside Ave | 7/10/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L02 | 3527 Southside Ave | 10/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L01 | 3529 Southside Ave | 3/14/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L01 | 3529 Southside Ave | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L01 | 3529 Southside Ave | 8/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L01 | 3529 Southside Ave | 1/24/2007 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L01 | 3529 Southside Ave | 4/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L01 | 3529 Southside Ave | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L01 | 3529 Southside Ave | 10/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L01 | 3529 Southside Ave | 1/22/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P277L01 | 3529 Southside Ave | 4/3/2008 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L01 | 3529 Southside Ave | 7/14/2008 | | 0.10 J | ND(0.50) | 13.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L01 | 3529 Southside Ave | 10/10/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L01 | 3529 Southside Ave | 1/13/2009 | | 0.088 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L01 | 3529 Southside Ave | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L01 | 3529 Southside Ave | 7/21/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P277L01 | 3529 Southside Ave | 10/9/2009 | | 0.085 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P164LNA01 | 3530 Southside Ave | 3/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P164LNA01 | 3530 Southside Ave | 4/19/2006 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P164LNA01 | 3530 Southside Ave | 1/27/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P164LNA01 | 3530 Southside Ave | 7/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P164LNA01 | 3530 Southside Ave | 1/14/2008 | | 0.57 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.5 | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P164LNA01 | 3530 Southside Ave | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P164LNA01 | 3530 Southside Ave | 1/13/2009 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P164LNA01 | 3530 Southside Ave | 7/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P164LNA02 | 3530 Southside Ave | 3/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P164LNA02 | 3530 Southside Ave | 4/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P164LNA02 | 3530 Southside Ave | 1/27/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P164LNA02 | 3530 Southside Ave | 7/18/2007 | | 0.46 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P164LNA02 | 3530 Southside Ave | 1/14/2008 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.32 J | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P164LNA02 | 3530 Southside Ave | 7/14/2008 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P164LNA02 | 3530 Southside Ave | 1/13/2009 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P164LNA02 | 3530 Southside Ave | 7/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P344LNA | 3531 Southside Ave | 3/14/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P344LNA | 3531 Southside Ave | 5/8/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P344LNA | 3531 Southside Ave | 6/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P344LNA | 3531 Southside Ave | 9/11/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P344LNA | 3531 Southside Ave | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P344LNA | 3531 Southside Ave | 1/31/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P344LNA | 3531 Southside Ave | 7/25/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P344LNA | 3531 Southside Ave | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P344LNA | 3531 Southside Ave | 7/22/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P108LNA | 3600 Southside Ave | 3/17/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P108LNA | 3600 Southside Ave | 4/18/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P108LNA | 3600 Southside Ave | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P108LNA | 3600 Southside Ave | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P108LNA | 3600 Southside Ave | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P108LNA | 3600 Southside Ave | 8/15/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P108LNA | 3600 Southside Ave | 1/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P108LNA | 3600 Southside Ave | 7/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P109LNA | 3602 Southside Ave | 3/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P109LNA | 3602 Southside Ave | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P109LNA | 3602 Southside Ave | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P109LNA | 3602 Southside Ave | 7/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P109LNA | 3602 Southside Ave | 1/23/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P109LNA | 3602 Southside Ave | 11/3/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P109LNA | 3602 Southside Ave | 1/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P109LNA | 3602 Southside Ave | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0101 | 3603 Southside Ave | 3/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0101 | 3603 Southside Ave | 4/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0101 | 3603 Southside Ave | 6/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0101 | 3603 Southside Ave | 8/15/2006 | | ND(0.50) | ND(0.50) | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0101 | 3603 Southside Ave | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0101 | 3603 Southside Ave | 4/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0101 | 3603 Southside Ave | 7/18/2007 | | ND(0.50) | ND(0.50) | 6.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0101 | 3603 Southside Ave | 10/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0101 | 3603 Southside Ave | 1/17/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P278L0101 | 3603 Southside Ave | 4/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0101 | 3603 Southside Ave | 7/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0101 | 3603 Southside Ave | 10/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0101 | 3603 Southside Ave | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0101 | 3603 Southside Ave | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0101 | 3603 Southside Ave | 7/10/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0101 | 3603 Southside Ave | 10/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0102 | 3603 Southside Ave | 3/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0102 | 3603 Southside Ave | 4/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0102 | 3603 Southside Ave | 6/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0102 | 3603 Southside Ave | 8/15/2006 | | ND(0.50) | ND(0.50) | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0102 | 3603 Southside Ave | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0102 | 3603 Southside Ave | 4/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P278L0102 | 3603 Southside Ave | 7/18/2007 | | ND(0.50) | ND(0.50) | 0.62 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0102 | 3603 Southside Ave | 10/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0102 | 3603 Southside Ave | 1/17/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P278L0102 | 3603 Southside Ave | 4/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0102 | 3603 Southside Ave | 7/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0102 | 3603 Southside Ave | 10/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0102 | 3603 Southside Ave | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0102 | 3603 Southside Ave | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0102 | 3603 Southside Ave | 7/10/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L0102 | 3603 Southside Ave | 10/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 3/15/2006 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 3/27/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 4/3/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 4/10/2006 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 4/17/2006 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 4/24/2006 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 5/1/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 5/8/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 5/15/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 5/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 5/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 6/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 6/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 7/10/2006 | | 0.51 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 7/17/2006 | | 0.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 7/24/2006 | | 0.93 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 7/31/2006 | | 0.68 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethylbenzene (µg/L) | Total Xylenes (µg/L) | Naphthalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|----------------|--------------------|-------------|-------------------|-------------|----------------|----------------|---------------------|----------------------|--------------------|-------------|-------------|-------------|------------|
| M35P278L02S | 3605 Southside Ave | 8/7/2006 | | 0.68 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 8/14/2006 | | 0.69 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 8/21/2006 | | 0.61 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 8/28/2006 | | 0.55 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 9/6/2006 | | 0.76 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 9/11/2006 | | 0.61 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 9/18/2006 | | 0.53 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 9/25/2006 | | 0.65 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 10/2/2006 | | 0.62 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 10/9/2006 | | 0.63 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 10/16/2006 | | 0.63 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 10/23/2006 | | 0.46 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 10/30/2006 | | 0.59 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 11/6/2006 | | 0.74 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 11/13/2006 | | 0.77 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 11/20/2006 | | 0.75 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 11/27/2006 | | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 12/4/2006 | | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 12/11/2006 | | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 12/19/2006 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 1/8/2007 | | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 1/22/2007 | | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 2/5/2007 | | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 2/21/2007 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 3/5/2007 | | 0.71 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 3/19/2007 | | 0.89 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 6.6 |
| M35P278L02S | 3605 Southside Ave | 4/2/2007 | | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P278L02S | 3605 Southside Ave | 4/16/2007 | | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 4/30/2007 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 5/14/2007 | | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 5/30/2007 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 6/11/2007 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 6/25/2007 | | 0.98 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 7/9/2007 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 7/23/2007 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 8/6/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 8/20/2007 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 9/5/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 9/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 10/1/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 10/15/2007 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 10/29/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 11/12/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 11/26/2007 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P278L02S | 3605 Southside Ave | 12/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 1/7/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P278L02S | 3605 Southside Ave | 2/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 4/7/2008 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 5/5/2008 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 7/7/2008 | | 0.61 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 8/5/2008 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 11/3/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 12/5/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 1/5/2009 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P278L02S | 3605 Southside Ave | 4/6/2009 | | 0.071 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 5/5/2009 | | 0.092 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 6/8/2009 | | 0.56 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 7/6/2009 | | 0.37 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 8/31/2009 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 10/5/2009 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 11/2/2009 | | 0.43 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P278L02S | 3605 Southside Ave | 12/8/2009 | | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 3/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 3/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 4/1/2006 | | ND(0.50) | 0.081 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 4/8/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 4/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 4/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 5/12/2006 | | ND(0.50) | 0.090 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 5/30/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 6/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 6/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 6/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 7/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 7/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 7/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 8/1/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 8/8/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 8/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 8/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 8/29/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P221L01 | 3605A Southside Ave | 9/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 9/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 9/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 9/26/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 10/3/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 10/10/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 10/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 10/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 10/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 11/7/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 11/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 11/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 11/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 12/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 12/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 1/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 2/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 3/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 4/3/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 4/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 5/1/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 5/15/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 5/29/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 6/12/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 6/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 7/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P221L01 | 3605A Southside Ave | 7/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 8/7/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 8/21/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 9/4/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 9/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 10/2/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 10/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 10/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 11/13/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 11/27/2007 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P221L01 | 3605A Southside Ave | 12/11/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 1/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 2/5/2008 | | 0.096 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 3/4/2008 | | 0.071 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P221L01 | 3605A Southside Ave | 4/8/2008 | | 0.1 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P221L01 | 3605A Southside Ave | 5/6/2008 | | 0.095 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P221L01 | 3605A Southside Ave | 6/3/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P221L01 | 3605A Southside Ave | 7/8/2008 | | 0.084 J | ND(0.50) | 0.16 J | ND(0.50) | 0.069 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 8/5/2008 | | 0.087 J | ND(0.50) | 0.086 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 9/9/2008 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 10/7/2008 | | 0.077 J | 0.083 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 11/4/2008 | | 0.096 J | ND(0.50) | 0.070 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 12/2/2008 | | 0.075 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 1/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 2/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 3/5/2009 | | 0.089 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 4/7/2009 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P221L01 | 3605A Southside Ave | 5/5/2009 | | 0.097 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 6/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 7/7/2009 | | 0.084 J | ND(0.50) | 0.079 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 8/4/2009 | | ND(0.50) | 0.18 J | 0.069 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 9/1/2009 | | ND(0.50) | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 10/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 11/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L01 | 3605A Southside Ave | 12/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 3/15/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 3/29/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 4/5/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 4/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 4/19/2006 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 4/26/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 5/2/2006 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 5/9/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 5/16/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 5/23/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 5/30/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 6/6/2006 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 6/13/2006 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.6 J |
| M35P221L02 | 3605B Southside Ave | 6/20/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 4.2 J |
| M35P221L02 | 3605B Southside Ave | 6/27/2006 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 7/18/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 7/25/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 8/1/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 8/29/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P221L02 | 3605B Southside Ave | 9/5/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 9/12/2006 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 9/26/2006 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 10/10/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 10/17/2006 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 10/31/2006 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 11/7/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 11/14/2006 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 11/21/2006 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 12/5/2006 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 12/12/2006 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 12/19/2006 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 1/9/2007 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 2/6/2007 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 2/20/2007 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 3/6/2007 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 3/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 4/17/2007 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 5/1/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 5/15/2007 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 5/29/2007 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 6/12/2007 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 7/24/2007 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 8/7/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 8/21/2007 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 9/4/2007 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P221L02 | 3605B Southside Ave | 9/18/2007 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 10/2/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 10/16/2007 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 10/30/2007 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 11/13/2007 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 11/27/2007 | | 0.2 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P221L02 | 3605B Southside Ave | 12/11/2007 | | 0.19 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P221L02 | 3605B Southside Ave | 1/8/2008 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 2/5/2008 | | 0.24 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 3.5 J |
| M35P221L02 | 3605B Southside Ave | 3/4/2008 | | 0.19 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P221L02 | 3605B Southside Ave | 4/8/2008 | | 0.2 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 2.9 J |
| M35P221L02 | 3605B Southside Ave | 5/6/2008 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 6/3/2008 | | 0.16 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P221L02 | 3605B Southside Ave | 8/5/2008 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 9/9/2008 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 10/20/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 10/20/2008 | PI | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 10/20/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 10/23/2008 | PI | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 11/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 11/4/2008 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 11/4/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 12/4/2008 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 12/4/2008 | PI | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 12/4/2008 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 1/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 1/6/2009 | PI | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P221L02 | 3605B Southside Ave | 1/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 2/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 2/3/2009 | PI | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 2/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 3/3/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 3/3/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 3/3/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 4/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 4/7/2009 | PI | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 4/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 5/5/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 5/5/2009 | PI | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 5/5/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 6/2/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 6/2/2009 | PI | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 6/2/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 7/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 7/7/2009 | PI | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 7/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 8/4/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 8/4/2009 | PI | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 8/4/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 9/1/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 9/1/2009 | PI | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 9/1/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 10/6/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 10/6/2009 | PI | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P221L02 | 3605B Southside Ave | 10/6/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 11/2/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 11/2/2009 | PI | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 11/2/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 12/7/2009 | PE | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 12/7/2009 | PI | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L02 | 3605B Southside Ave | 12/7/2009 | PM | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 3/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 3/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 4/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 4/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 4/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 4/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 5/1/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 5/8/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 5/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 5/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 5/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 6/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 6/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 6/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 6/26/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 7/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 7/10/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 7/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 7/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 8/7/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P221L03 | 3605C Southside Ave | 8/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 8/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 8/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 9/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 9/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 9/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 9/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 10/2/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 10/9/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 10/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 10/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 10/30/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 11/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 11/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 11/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 11/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 12/4/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 12/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 12/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 1/8/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 2/5/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 2/21/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 3/5/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 3/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 4/2/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 4/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P221L03 | 3605C Southside Ave | 4/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 5/14/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 5/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 6/11/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 6/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 7/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 7/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 8/6/2007 | | 0.076 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 8/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 9/5/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 9/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 10/2/2007 | | 0.62 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 10/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 10/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 11/13/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 11/27/2007 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P221L03 | 3605C Southside Ave | 12/11/2007 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P221L03 | 3605C Southside Ave | 1/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 2/5/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P221L03 | 3605C Southside Ave | 3/4/2008 | | ND(0.5) | 0.42 J | 0.19 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P221L03 | 3605C Southside Ave | 4/8/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P221L03 | 3605C Southside Ave | 5/6/2008 | | ND(0.50) | 0.15 J | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 6/3/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P221L03 | 3605C Southside Ave | 7/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 8/5/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 9/9/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 10/7/2008 | | ND(0.50) | 0.19 J | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P221L03 | 3605C Southside Ave | 11/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 12/9/2008 | | ND(0.50) | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 1/6/2009 | | ND(0.50) | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 2/3/2009 | | ND(0.50) | 0.16 J | 0.076 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 3/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 4/8/2009 | | ND(0.50) | 0.16 J | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 6/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 7/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 8/4/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 9/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 10/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L03 | 3605C Southside Ave | 11/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 3/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 3/29/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 4/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 4/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 4/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 4/26/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 5/1/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 5/8/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 5/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 5/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 5/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 6/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 6/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 6/19/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 6/26/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P221L04 | 3605D Southside Ave | 7/5/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 7/10/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 7/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 7/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 7/31/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 8/7/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 8/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 8/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 8/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 9/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 9/11/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 9/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 9/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 10/2/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 10/9/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 10/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 10/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 10/30/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 11/6/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 11/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 11/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 11/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 12/4/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 12/12/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 12/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 1/8/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P221L04 | 3605D Southside Ave | 2/5/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 2/21/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 3/5/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 3/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 4/2/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 4/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 4/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 5/14/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 5/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 6/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 7/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 7/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 8/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 8/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 9/5/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 10/1/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 10/15/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 10/29/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 11/12/2007 | | 0.082 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 11/26/2007 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P221L04 | 3605D Southside Ave | 12/10/2007 | | 0.094 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 1/7/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P221L04 | 3605D Southside Ave | 2/4/2008 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 3/3/2008 | | 0.13 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P221L04 | 3605D Southside Ave | 4/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 5/5/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 6/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P221L04 | 3605D Southside Ave | 7/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 8/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 9/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 10/6/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 11/3/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 12/1/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 1/5/2009 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 2/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 3/10/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 4/6/2009 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 5/4/2009 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 6/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 7/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 8/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 8/31/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 10/5/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 11/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P221L04 | 3605D Southside Ave | 12/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P213LNA | 3607 Southside Ave | 3/14/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P213LNA | 3607 Southside Ave | 4/18/2006 | | 0.46 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P213LNA | 3607 Southside Ave | 6/12/2006 | | 0.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P213LNA | 3607 Southside Ave | 8/17/2006 | | 1.1 | ND(0.50) | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P213LNA | 3607 Southside Ave | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P213LNA | 3607 Southside Ave | 7/17/2007 | | 0.51 | 0.10 J | 0.39 J | ND(0.50) | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P213LNA | 3607 Southside Ave | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P213LNA | 3607 Southside Ave | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P213LNA | 3607 Southside Ave | 1/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P213LNA | 3607 Southside Ave | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P025L01 | 3610 Southside Ave | 3/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P025L01 | 3610 Southside Ave | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P025L01 | 3610 Southside Ave | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P025L01 | 3610 Southside Ave | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P025L01 | 3610 Southside Ave | 1/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P025L01 | 3610 Southside Ave | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P025L01 | 3610 Southside Ave | 1/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P025L01 | 3610 Southside Ave | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P361LNA | 3611 Southside Ave | 3/15/2006 | | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P361LNA | 3611 Southside Ave | 4/17/2006 | | 0.36 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P361LNA | 3611 Southside Ave | 6/15/2006 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P361LNA | 3611 Southside Ave | 8/16/2006 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P361LNA | 3611 Southside Ave | 1/22/2007 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P361LNA | 3611 Southside Ave | 4/10/2007 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P361LNA | 3611 Southside Ave | 8/20/2007 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P361LNA | 3611 Southside Ave | 10/23/2007 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P361LNA | 3611 Southside Ave | 1/21/2008 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P361LNA | 3611 Southside Ave | 4/8/2008 | | 0.21 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P361LNA | 3611 Southside Ave | 7/21/2008 | | 0.11 J | ND(0.50) | 0.061 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P361LNA | 3611 Southside Ave | 10/9/2008 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P361LNA | 3611 Southside Ave | 1/14/2009 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P361LNA | 3611 Southside Ave | 4/2/2009 | | 0.086 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P361LNA | 3611 Southside Ave | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P361LNA | 3611 Southside Ave | 10/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P397L01 | 3613 Southside Ave | 3/14/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P397L01 | 3613 Southside Ave | 4/17/2006 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P397L01 | 3613 Southside Ave | 6/14/2006 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P397L01 | 3613 Southside Ave | 8/16/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P397L01 | 3613 Southside Ave | 1/24/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P397L01 | 3613 Southside Ave | 7/18/2007 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P397L01 | 3613 Southside Ave | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P397L01 | 3613 Southside Ave | 7/14/2008 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P397L01 | 3613 Southside Ave | 2/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P397L01 | 3613 Southside Ave | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P097L03 | 3615 Southside Ave | 3/18/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P097L03 | 3615 Southside Ave | 4/22/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P097L03 | 3615 Southside Ave | 6/17/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P097L03 | 3615 Southside Ave | 8/16/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P097L03 | 3615 Southside Ave | 2/5/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P097L03 | 3615 Southside Ave | 4/10/2007 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P097L03 | 3615 Southside Ave | 8/6/2007 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P097L03 | 3615 Southside Ave | 11/13/2007 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P097L03 | 3615 Southside Ave | 1/21/2008 | | 0.090 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P097L03 | 3615 Southside Ave | 10/9/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P097L03 | 3615 Southside Ave | 10/13/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P073L01 | 3616 Southside Ave | 3/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P073L01 | 3616 Southside Ave | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P073L01 | 3616 Southside Ave | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P073L01 | 3616 Southside Ave | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P073L01 | 3616 Southside Ave | 1/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P073L01 | 3616 Southside Ave | 7/16/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P073L01 | 3616 Southside Ave | 1/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P073L01 | 3616 Southside Ave | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M36P245L02 | 3617 Southside Ave | 3/15/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P245L02 | 3617 Southside Ave | 4/17/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P245L02 | 3617 Southside Ave | 6/14/2006 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P245L02 | 3617 Southside Ave | 8/21/2006 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P245L02 | 3617 Southside Ave | 1/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P245L02 | 3617 Southside Ave | 7/17/2007 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P245L02 | 3617 Southside Ave | 1/16/2008 | | 0.17 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M36P245L02 | 3617 Southside Ave | 7/16/2008 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P245L02 | 3617 Southside Ave | 1/8/2009 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P245L02 | 3617 Southside Ave | 7/9/2009 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P225LNA | 3627 Southside Ave | 3/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P225LNA | 3627 Southside Ave | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P225LNA | 3627 Southside Ave | 6/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P225LNA | 3627 Southside Ave | 8/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P225LNA | 3627 Southside Ave | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P225LNA | 3627 Southside Ave | 4/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P225LNA | 3627 Southside Ave | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P225LNA | 3627 Southside Ave | 10/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P225LNA | 3627 Southside Ave | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M36P225LNA | 3627 Southside Ave | 4/2/2008 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P225LNA | 3627 Southside Ave | 7/14/2008 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P225LNA | 3627 Southside Ave | 10/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P225LNA | 3627 Southside Ave | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P225LNA | 3627 Southside Ave | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P225LNA | 3627 Southside Ave | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P225LNA | 3627 Southside Ave | 10/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P122LNA | 3627A Southside Ave | 3/21/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M36P122LNA | 3627A Southside Ave | 4/19/2006 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P122LNA | 3627A Southside Ave | 6/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P122LNA | 3627A Southside Ave | 8/16/2006 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P122LNA | 3627A Southside Ave | 1/22/2007 | | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P122LNA | 3627A Southside Ave | 4/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P122LNA | 3627A Southside Ave | 7/17/2007 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P122LNA | 3627A Southside Ave | 10/24/2007 | | 0.54 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P122LNA | 3627A Southside Ave | 1/15/2008 | | 0.76 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M36P122LNA | 3627A Southside Ave | 4/3/2008 | | 0.76 | ND(0.50) | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P122LNA | 3627A Southside Ave | 7/14/2008 | | 0.48 J | ND(0.50) | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P122LNA | 3627A Southside Ave | 10/8/2008 | | 0.68 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P122LNA | 3627A Southside Ave | 1/13/2009 | | 0.92 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P122LNA | 3627A Southside Ave | 4/2/2009 | | 0.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P122LNA | 3627A Southside Ave | 7/9/2009 | | 0.64 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P122LNA | 3627A Southside Ave | 10/8/2009 | | 0.89 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P123LNA | 3629 Southside Ave | 3/14/2006 | | 0.22 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P123LNA | 3629 Southside Ave | 4/17/2006 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P123LNA | 3629 Southside Ave | 6/15/2006 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P123LNA | 3629 Southside Ave | 8/16/2006 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P123LNA | 3629 Southside Ave | 1/25/2007 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P123LNA | 3629 Southside Ave | 7/17/2007 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P123LNA | 3629 Southside Ave | 1/23/2008 | | 0.16 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M36P123LNA | 3629 Southside Ave | 7/14/2008 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P123LNA | 3629 Southside Ave | 1/13/2009 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P123LNA | 3629 Southside Ave | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P073L04 | 3630 Southside Ave | 3/22/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P073L04 | 3630 Southside Ave | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|--------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M36P073L04 | 3630 Southside Ave | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P073L04 | 3630 Southside Ave | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P073L04 | 3630 Southside Ave | 1/17/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M36P073L04 | 3630 Southside Ave | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P073L04 | 3630 Southside Ave | 1/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P073L04 | 3630 Southside Ave | 7/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P179LNA | 3631 Southside Ave | 3/14/2006 | | 0.71 | ND(0.50) | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P179LNA | 3631 Southside Ave | 4/17/2006 | | 3.8 | 0.19 J | 0.98 | 0.14 J | 0.33 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P179LNA | 3631 Southside Ave | 4/21/2006 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P179LNA | 3631 Southside Ave | 6/12/2006 | | 0.62 | ND(0.50) | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P179LNA | 3631 Southside Ave | 8/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P179LNA | 3631 Southside Ave | 1/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P179LNA | 3631 Southside Ave | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P179LNA | 3631 Southside Ave | 1/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P179LNA | 3631 Southside Ave | 7/15/2008 | | 0.086 J | ND(0.50) | 0.098 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P179LNA | 3631 Southside Ave | 1/14/2009 | | 0.11 J | ND(0.50) | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P179LNA | 3631 Southside Ave | 7/17/2009 | | ND(0.50) | ND(0.50) | 0.30 J | ND(0.50) | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P076LNA | 3633 Southside Ave | 3/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P076LNA | 3633 Southside Ave | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P076LNA | 3633 Southside Ave | 6/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P076LNA | 3633 Southside Ave | 8/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P076LNA | 3633 Southside Ave | 1/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P076LNA | 3633 Southside Ave | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P076LNA | 3633 Southside Ave | 1/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P076LNA | 3633 Southside Ave | 7/18/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P076LNA | 3633 Southside Ave | 1/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P076LNA | 3633 Southside Ave | 7/15/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M36P189LNA | 3634 Southside Ave | 3/20/2006 | | 0.68 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P189LNA | 3634 Southside Ave | 4/17/2006 | | 0.75 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P189LNA | 3634 Southside Ave | 1/24/2007 | | 0.59 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P189LNA | 3634 Southside Ave | 7/17/2007 | | 0.52 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P189LNA | 3634 Southside Ave | 1/15/2008 | | 0.38 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M36P189LNA | 3634 Southside Ave | 7/16/2008 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P189LNA | 3634 Southside Ave | 1/15/2009 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P189LNA | 3634 Southside Ave | 7/9/2009 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P226LNA | 3635 Southside Ave | 3/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P226LNA | 3635 Southside Ave | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P226LNA | 3635 Southside Ave | 6/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P226LNA | 3635 Southside Ave | 8/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P226LNA | 3635 Southside Ave | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P226LNA | 3635 Southside Ave | 7/17/2007 | | ND(0.50) | ND(0.50) | 0.39 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P226LNA | 3635 Southside Ave | 1/15/2008 | | ND(0.5) | ND(0.5) | 0.4 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M36P226LNA | 3635 Southside Ave | 7/14/2008 | | 0.086 J | ND(0.50) | 0.060 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P226LNA | 3635 Southside Ave | 1/14/2009 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P226LNA | 3635 Southside Ave | 7/14/2009 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L03S | 3505 Stansbury Mill Rd | 3/18/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L03S | 3505 Stansbury Mill Rd | 4/22/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L03S | 3505 Stansbury Mill Rd | 1/24/2007 | | 0.51 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L03S | 3505 Stansbury Mill Rd | 7/19/2007 | | 0.87 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L03S | 3505 Stansbury Mill Rd | 1/15/2008 | | 0.76 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P033L03S | 3505 Stansbury Mill Rd | 7/15/2008 | | 0.79 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L03S | 3505 Stansbury Mill Rd | 1/13/2009 | | 0.57 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L03S | 3505 Stansbury Mill Rd | 7/9/2009 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P235LNA | 3506 Stansbury Mill Rd | 4/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P235LNA | 3506 Stansbury Mill Rd | 1/22/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P235LNA | 3506 Stansbury Mill Rd | 7/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P235LNA | 3506 Stansbury Mill Rd | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P235LNA | 3506 Stansbury Mill Rd | 7/22/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P235LNA | 3506 Stansbury Mill Rd | 1/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P235LNA | 3506 Stansbury Mill Rd | 7/14/2009 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L04 | 3507 Stansbury Mill Rd | 3/17/2006 | | 0.55 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L04 | 3507 Stansbury Mill Rd | 4/19/2006 | | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L04 | 3507 Stansbury Mill Rd | 8/6/2007 | | 0.42 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L04 | 3507 Stansbury Mill Rd | 1/21/2008 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L04 | 3507 Stansbury Mill Rd | 1/14/2009 | | 0.40 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P196LNA | 3509 Stansbury Mill Rd | 3/17/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P196LNA | 3509 Stansbury Mill Rd | 4/18/2006 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P196LNA | 3509 Stansbury Mill Rd | 1/22/2007 | | 0.44 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P196LNA | 3509 Stansbury Mill Rd | 7/18/2007 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P196LNA | 3509 Stansbury Mill Rd | 1/15/2008 | | 0.18 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P196LNA | 3509 Stansbury Mill Rd | 7/15/2008 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P196LNA | 3509 Stansbury Mill Rd | 1/13/2009 | | 0.21 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P196LNA | 3509 Stansbury Mill Rd | 7/9/2009 | | 0.27 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L05 | 3511 Stansbury Mill Rd | 3/17/2006 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L05 | 3511 Stansbury Mill Rd | 4/18/2006 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L05 | 3511 Stansbury Mill Rd | 1/22/2007 | | 0.53 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L05 | 3511 Stansbury Mill Rd | 7/18/2007 | | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L05 | 3511 Stansbury Mill Rd | 1/15/2008 | | 0.18 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P033L05 | 3511 Stansbury Mill Rd | 7/15/2008 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L05 | 3511 Stansbury Mill Rd | 1/13/2009 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P033L05 | 3511 Stansbury Mill Rd | 7/9/2009 | | 0.15 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|------------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P200LNA | 3513 Stansbury Mill Rd | 1/22/2007 | | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P200LNA | 3513 Stansbury Mill Rd | 7/18/2007 | | 1.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P200LNA | 3513 Stansbury Mill Rd | 1/15/2008 | | 1.4 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P200LNA | 3513 Stansbury Mill Rd | 7/15/2008 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P200LNA | 3513 Stansbury Mill Rd | 1/13/2009 | | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P200LNA | 3513 Stansbury Mill Rd | 7/9/2009 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P398L01 | 3517 Stansbury Mill Rd | 5/16/2006 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P398L01 | 3517 Stansbury Mill Rd | 7/18/2007 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P398L01 | 3517 Stansbury Mill Rd | 1/15/2008 | | 0.16 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P398L01 | 3517 Stansbury Mill Rd | 7/15/2008 | | 0.35 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P398L01 | 3517 Stansbury Mill Rd | 1/15/2009 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P398L01 | 3517 Stansbury Mill Rd | 7/9/2009 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P061LNA | 3519 Stansbury Mill Rd | 3/20/2006 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P061LNA | 3519 Stansbury Mill Rd | 4/18/2006 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P061LNA | 3519 Stansbury Mill Rd | 1/22/2007 | | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P061LNA | 3519 Stansbury Mill Rd | 7/18/2007 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P061LNA | 3519 Stansbury Mill Rd | 1/15/2008 | | 2.3 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P061LNA | 3519 Stansbury Mill Rd | 7/15/2008 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P061LNA | 3519 Stansbury Mill Rd | 1/13/2009 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.10 J | ND(5.0) |
| M35P061LNA | 3519 Stansbury Mill Rd | 7/9/2009 | | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P193LNA | 3410 Sweet Air Rd | 3/9/2006 | PEO | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P193LNA | 3410 Sweet Air Rd | 3/9/2006 | PIO | 77.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 22.6 | 0.28 J | ND(5.0) |
| M35P193LNA | 3410 Sweet Air Rd | 3/9/2006 | PMO | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P193LNA | 3410 Sweet Air Rd | 4/19/2006 | PIO | 23.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 3 | ND(0.50) | ND(5.0) |
| M35P193LNA | 3410 Sweet Air Rd | 6/14/2006 | PIO | 32 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 1.5 | ND(0.50) | ND(5.0) |
| M35P198LNA | 3411 Sweet Air Rd | 3/15/2006 | | 3.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P169LNA | 3418 Sweet Air Rd | 3/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P169LNA | 3418 Sweet Air Rd | 4/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P169LNA | 3418 Sweet Air Rd | 6/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P169LNA | 3418 Sweet Air Rd | 8/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 3/10/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 4/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 8/15/2006 | | ND(0.50) | ND(0.50) | 0.30 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 1/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 2/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 2/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 3/6/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 3/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 4/3/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 4/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 5/1/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 5/15/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 5/29/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 6/12/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 6/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 7/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 7/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 8/6/2007 | | ND(0.50) | ND(0.50) | 0.057 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 8/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 9/4/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 9/18/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 10/2/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 10/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P121LNA | 3422 Sweet Air Rd | 10/30/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 11/13/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 11/27/2007 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P121LNA | 3422 Sweet Air Rd | 12/11/2007 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P121LNA | 3422 Sweet Air Rd | 1/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 2/5/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P121LNA | 3422 Sweet Air Rd | 3/4/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P121LNA | 3422 Sweet Air Rd | 4/8/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P121LNA | 3422 Sweet Air Rd | 5/6/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P121LNA | 3422 Sweet Air Rd | 6/3/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P121LNA | 3422 Sweet Air Rd | 7/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 8/5/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 9/9/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 10/7/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 11/4/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 12/2/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 1/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 2/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 3/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 3/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 4/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 5/5/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 6/2/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 7/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 8/4/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 9/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 10/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P121LNA | 3422 Sweet Air Rd | 11/3/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P121LNA | 3422 Sweet Air Rd | 12/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P365LNA | 3430 Sweet Air Rd | 3/3/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P365LNA | 3430 Sweet Air Rd | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P365LNA | 3430 Sweet Air Rd | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P365LNA | 3430 Sweet Air Rd | 6/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P365LNA | 3430 Sweet Air Rd | 8/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P365LNA | 3430 Sweet Air Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P365LNA | 3430 Sweet Air Rd | 4/9/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P365LNA | 3430 Sweet Air Rd | 7/19/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P365LNA | 3430 Sweet Air Rd | 10/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P365LNA | 3430 Sweet Air Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P365LNA | 3430 Sweet Air Rd | 4/4/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P365LNA | 3430 Sweet Air Rd | 7/15/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P365LNA | 3430 Sweet Air Rd | 7/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P365LNA | 3430 Sweet Air Rd | 10/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P365LNA | 3430 Sweet Air Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P365LNA | 3430 Sweet Air Rd | 4/6/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P365LNA | 3430 Sweet Air Rd | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P365LNA | 3430 Sweet Air Rd | 10/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P107LNA | 3440 Sweet Air Rd | 3/3/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P107LNA | 3440 Sweet Air Rd | 3/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P107LNA | 3440 Sweet Air Rd | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P107LNA | 3440 Sweet Air Rd | 6/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P107LNA | 3440 Sweet Air Rd | 8/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P107LNA | 3440 Sweet Air Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P107LNA | 3440 Sweet Air Rd | 4/10/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P107LNA | 3440 Sweet Air Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P107LNA | 3440 Sweet Air Rd | 10/22/2007 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P107LNA | 3440 Sweet Air Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P107LNA | 3440 Sweet Air Rd | 4/1/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P107LNA | 3440 Sweet Air Rd | 10/8/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P107LNA | 3440 Sweet Air Rd | 1/12/2009 | | 0.081 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P107LNA | 3440 Sweet Air Rd | 4/1/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P107LNA | 3440 Sweet Air Rd | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P107LNA | 3440 Sweet Air Rd | 10/7/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P378LNA01 | 3499 Sweet Air Rd | 3/15/2006 | | 0.83 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P378LNA02 | 3499 Sweet Air Rd | 3/15/2006 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.16 J | ND(5.0) |
| M35P378LNA03 | 3499 Sweet Air Rd | 3/15/2006 | | 0.72 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA01 | 3500 Sweet Air Rd | 3/3/2006 | | 0.64 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA01 | 3500 Sweet Air Rd | 3/28/2006 | | 0.49 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA01 | 3500 Sweet Air Rd | 4/19/2006 | | 2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA01 | 3500 Sweet Air Rd | 6/15/2006 | | 0.57 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA01 | 3500 Sweet Air Rd | 8/16/2006 | | 0.56 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA01 | 3500 Sweet Air Rd | 1/23/2007 | | 0.41 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA01 | 3500 Sweet Air Rd | 4/10/2007 | | 1.7 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA01 | 3500 Sweet Air Rd | 7/16/2007 | | 1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA01 | 3500 Sweet Air Rd | 10/22/2007 | | 0.89 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA01 | 3500 Sweet Air Rd | 1/15/2008 | | 2.3 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P117LNA01 | 3500 Sweet Air Rd | 4/1/2008 | | 2.2 | ND(0.5) | 1.1 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P117LNA01 | 3500 Sweet Air Rd | 7/15/2008 | | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA01 | 3500 Sweet Air Rd | 4/1/2009 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA01 | 3500 Sweet Air Rd | 7/9/2009 | | 1.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA01 | 3500 Sweet Air Rd | 10/7/2009 | | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA02 | 3500 Sweet Air Rd | 3/3/2006 | | 1.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P117LNA02 | 3500 Sweet Air Rd | 3/28/2006 | | 2.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA02 | 3500 Sweet Air Rd | 4/18/2006 | | 2.3 | ND(0.50) | 0.087 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA02 | 3500 Sweet Air Rd | 6/15/2006 | | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA02 | 3500 Sweet Air Rd | 8/16/2006 | | 1.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA02 | 3500 Sweet Air Rd | 1/23/2007 | | 1.9 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA02 | 3500 Sweet Air Rd | 4/10/2007 | | 1.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA02 | 3500 Sweet Air Rd | 7/16/2007 | | 2.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA02 | 3500 Sweet Air Rd | 10/22/2007 | | 2.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA02 | 3500 Sweet Air Rd | 1/15/2008 | | 2.3 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P117LNA02 | 3500 Sweet Air Rd | 4/1/2008 | | 2.2 | ND(0.5) | 1.2 | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P117LNA02 | 3500 Sweet Air Rd | 7/15/2008 | | 2.5 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA02 | 3500 Sweet Air Rd | 10/8/2008 | | 1.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA02 | 3500 Sweet Air Rd | 1/12/2009 | | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA02 | 3500 Sweet Air Rd | 4/1/2009 | | 1.4 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA02 | 3500 Sweet Air Rd | 7/9/2009 | | 1.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P117LNA02 | 3500 Sweet Air Rd | 10/7/2009 | | 1.3 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P137LNA | 3501 Sweet Air Rd | 3/15/2006 | | 2.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P030L01 | 3505 Sweet Air Rd | 3/16/2006 | | 6.1 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P113LNA | 3506 Sweet Air Rd | 3/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P113LNA | 3506 Sweet Air Rd | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P113LNA | 3506 Sweet Air Rd | 6/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P113LNA | 3506 Sweet Air Rd | 8/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P113LNA | 3506 Sweet Air Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P113LNA | 3506 Sweet Air Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P113LNA | 3506 Sweet Air Rd | 1/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P113LNA | 3506 Sweet Air Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P113LNA | 3506 Sweet Air Rd | 2/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P030L03 | 3509 Sweet Air Rd | 3/18/2006 | | 1.6 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P112LNA | 3510 Sweet Air Rd | 3/14/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P112LNA | 3510 Sweet Air Rd | 4/18/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P112LNA | 3510 Sweet Air Rd | 6/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P112LNA | 3510 Sweet Air Rd | 8/16/2006 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P112LNA | 3510 Sweet Air Rd | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P112LNA | 3510 Sweet Air Rd | 7/16/2007 | | 0.16 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P112LNA | 3510 Sweet Air Rd | 1/22/2008 | | 0.1 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P112LNA | 3510 Sweet Air Rd | 7/15/2008 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P112LNA | 3510 Sweet Air Rd | 1/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P112LNA | 3510 Sweet Air Rd | 7/14/2009 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P030L04 | 3511 Sweet Air Rd | 3/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P114LNA | 3512 Sweet Air Rd | 3/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P114LNA | 3512 Sweet Air Rd | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P114LNA | 3512 Sweet Air Rd | 6/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P114LNA | 3512 Sweet Air Rd | 8/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P114LNA | 3512 Sweet Air Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P114LNA | 3512 Sweet Air Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P114LNA | 3512 Sweet Air Rd | 1/15/2008 | | 0.18 J | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P114LNA | 3512 Sweet Air Rd | 7/17/2008 | | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P114LNA | 3512 Sweet Air Rd | 1/12/2009 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P114LNA | 3512 Sweet Air Rd | 7/9/2009 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P030L05 | 3513 Sweet Air Rd | 3/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P189LNA | 3518 Sweet Air Rd | 3/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P189LNA | 3518 Sweet Air Rd | 3/22/2006 | | ND(1.0) | ND(1.0) | 0.32 J | ND(1.0) | ND(1.0) | ND(5.0) | ND(5.0) | ND(5.0) | ND(5.0) | ND(25) |
| M35P189LNA | 3518 Sweet Air Rd | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P189LNA | 3518 Sweet Air Rd | 6/13/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|-------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M35P189LNA | 3518 Sweet Air Rd | 8/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P189LNA | 3518 Sweet Air Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P189LNA | 3518 Sweet Air Rd | 7/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P189LNA | 3518 Sweet Air Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P189LNA | 3518 Sweet Air Rd | 7/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P189LNA | 3518 Sweet Air Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P189LNA | 3518 Sweet Air Rd | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P197LNA | 3526 Sweet Air Rd | 3/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P197LNA | 3526 Sweet Air Rd | 1/27/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P197LNA | 3526 Sweet Air Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | 6.8 |
| M35P197LNA | 3526 Sweet Air Rd | 7/17/2008 | | ND(0.50) | ND(0.50) | 0.084 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P197LNA | 3526 Sweet Air Rd | 1/14/2009 | | 0.094 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P172LNA | 3530 Sweet Air Rd | 3/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P172LNA | 3530 Sweet Air Rd | 4/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P172LNA | 3530 Sweet Air Rd | 6/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P172LNA | 3530 Sweet Air Rd | 8/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P172LNA | 3530 Sweet Air Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P172LNA | 3530 Sweet Air Rd | 1/17/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M35P172LNA | 3530 Sweet Air Rd | 7/18/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P172LNA | 3530 Sweet Air Rd | 1/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M35P172LNA | 3530 Sweet Air Rd | 7/21/2009 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P103LNA | 3608 Sweet Air Rd | 3/28/2006 | | 2.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.59 | ND(5.0) |
| M36P103LNA | 3608 Sweet Air Rd | 4/18/2006 | | 2.2 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.54 | ND(5.0) |
| M36P103LNA | 3608 Sweet Air Rd | 6/17/2006 | | 1.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.40 J | ND(5.0) |
| M36P103LNA | 3608 Sweet Air Rd | 8/29/2006 | | 0.79 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | 0.17 J | ND(5.0) |
| M36P103LNA | 3608 Sweet Air Rd | 3/5/2007 | | 0.62 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P103LNA | 3608 Sweet Air Rd | 8/7/2007 | | 0.52 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethylbenzene (µg/L) | Total Xylenes (µg/L) | Naphthalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|----------------|---------------------|-------------|-------------------|-------------|----------------|----------------|---------------------|----------------------|--------------------|-------------|-------------|-------------|------------|
| M36P103LNA | 3608 Sweet Air Rd | 1/18/2008 | | 0.81 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P084LNA | 3612 Sweet Air Rd | 3/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P084LNA | 3612 Sweet Air Rd | 4/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P084LNA | 3612 Sweet Air Rd | 6/14/2006 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P084LNA | 3612 Sweet Air Rd | 8/15/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P084LNA | 3612 Sweet Air Rd | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P084LNA | 3612 Sweet Air Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P084LNA | 3612 Sweet Air Rd | 1/15/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M36P084LNA | 3612 Sweet Air Rd | 7/15/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P084LNA | 3612 Sweet Air Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M36P084LNA | 3612 Sweet Air Rd | 7/9/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B | 3300 Whitesworth Rd | 2/25/2006 | | 0.91 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B | 3300 Whitesworth Rd | 3/27/2006 | | 0.64 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B | 3300 Whitesworth Rd | 4/25/2006 | | 0.8 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B | 3300 Whitesworth Rd | 8/18/2006 | | 0.55 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B | 3300 Whitesworth Rd | 1/24/2007 | | 0.61 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B | 3300 Whitesworth Rd | 7/16/2007 | | 0.57 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B | 3300 Whitesworth Rd | 1/14/2008 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B | 3300 Whitesworth Rd | 7/14/2008 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B | 3300 Whitesworth Rd | 1/14/2009 | | 0.57 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B | 3300 Whitesworth Rd | 7/13/2009 | | 0.81 | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B2 | 3300 Whitesworth Rd | 2/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B2 | 3300 Whitesworth Rd | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B2 | 3300 Whitesworth Rd | 4/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B2 | 3300 Whitesworth Rd | 8/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B2 | 3300 Whitesworth Rd | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B2 | 3300 Whitesworth Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M43P299L0B2 | 3300 Whitesworth Rd | 1/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B2 | 3300 Whitesworth Rd | 7/18/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B2 | 3300 Whitesworth Rd | 1/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0B2 | 3300 Whitesworth Rd | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0D | 3300 Whitesworth Rd | 2/25/2006 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0D | 3300 Whitesworth Rd | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0D | 3300 Whitesworth Rd | 4/25/2006 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0D | 3300 Whitesworth Rd | 8/18/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0D | 3300 Whitesworth Rd | 1/24/2007 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0D | 3300 Whitesworth Rd | 7/16/2007 | | 0.18 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0D | 3300 Whitesworth Rd | 1/14/2008 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0D | 3300 Whitesworth Rd | 7/14/2008 | | 0.17 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0D | 3300 Whitesworth Rd | 1/8/2009 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0D | 3300 Whitesworth Rd | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03 | 3302 Whitesworth Rd | 2/24/2006 | | 0.34 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03 | 3302 Whitesworth Rd | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03 | 3302 Whitesworth Rd | 4/25/2006 | | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03 | 3302 Whitesworth Rd | 8/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03 | 3302 Whitesworth Rd | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03 | 3302 Whitesworth Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03 | 3302 Whitesworth Rd | 1/14/2008 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03 | 3302 Whitesworth Rd | 7/14/2008 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03 | 3302 Whitesworth Rd | 1/12/2009 | | 0.29 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03 | 3302 Whitesworth Rd | 7/10/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02 | 3304 Whitesworth Rd | 2/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02 | 3304 Whitesworth Rd | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02 | 3304 Whitesworth Rd | 4/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M43P225L02 | 3304 Whitesworth Rd | 8/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02 | 3304 Whitesworth Rd | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02 | 3304 Whitesworth Rd | 7/17/2007 | | ND(0.50) | ND(0.50) | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02 | 3304 Whitesworth Rd | 1/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02 | 3304 Whitesworth Rd | 7/14/2008 | | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02 | 3304 Whitesworth Rd | 1/15/2009 | | 0.065 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02 | 3304 Whitesworth Rd | 7/9/2009 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02A | 3305 Whitesworth Rd | 3/2/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02A | 3305 Whitesworth Rd | 3/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02A | 3305 Whitesworth Rd | 4/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02A | 3305 Whitesworth Rd | 8/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02A | 3305 Whitesworth Rd | 1/24/2007 | | 0.25 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02A | 3305 Whitesworth Rd | 7/16/2007 | | 0.38 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02A | 3305 Whitesworth Rd | 1/14/2008 | | 0.31 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02A | 3305 Whitesworth Rd | 7/14/2008 | | 0.23 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02A | 3305 Whitesworth Rd | 1/8/2009 | | 0.41 J | ND(0.50) | 0.071 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L02A | 3305 Whitesworth Rd | 7/10/2009 | | 0.32 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L01 | 3306 Whitesworth Rd | 2/24/2006 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L01 | 3306 Whitesworth Rd | 3/28/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L01 | 3306 Whitesworth Rd | 4/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L01 | 3306 Whitesworth Rd | 8/16/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L01 | 3306 Whitesworth Rd | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L01 | 3306 Whitesworth Rd | 7/20/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L01 | 3306 Whitesworth Rd | 7/17/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L01 | 3306 Whitesworth Rd | 1/14/2009 | | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L01A | 3307 Whitesworth Rd | 3/2/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L01A | 3307 Whitesworth Rd | 3/29/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethylbenzene (µg/L) | Total Xylenes (µg/L) | Naphthalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|----------------|---------------------|-------------|-------------------|-------------|----------------|----------------|---------------------|----------------------|--------------------|-------------|-------------|-------------|------------|
| M43P225L01A | 3307 Whitesworth Rd | 4/24/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L01A | 3307 Whitesworth Rd | 8/16/2006 | | ND(0.50) | ND(0.50) | 0.094 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L01A | 3307 Whitesworth Rd | 1/27/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L01A | 3307 Whitesworth Rd | 7/17/2007 | | ND(0.50) | ND(0.50) | 0.14 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L01A | 3307 Whitesworth Rd | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M43P225L01A | 3307 Whitesworth Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | 0.11 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L01A | 3307 Whitesworth Rd | 1/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L01A | 3307 Whitesworth Rd | 7/10/2009 | | ND(0.50) | ND(0.50) | 0.12 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03A | 3309 Whitesworth Rd | 3/4/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03A | 3309 Whitesworth Rd | 4/1/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03A | 3309 Whitesworth Rd | 4/26/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03A | 3309 Whitesworth Rd | 8/17/2006 | | 0.26 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03A | 3309 Whitesworth Rd | 1/24/2007 | | 0.28 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03A | 3309 Whitesworth Rd | 7/16/2007 | | 0.19 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03A | 3309 Whitesworth Rd | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M43P225L03A | 3309 Whitesworth Rd | 7/14/2008 | | 0.10 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03A | 3309 Whitesworth Rd | 1/14/2009 | | 0.13 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P225L03A | 3309 Whitesworth Rd | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L04 | 3311 Whitesworth Rd | 4/4/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L04 | 3311 Whitesworth Rd | 4/27/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L04 | 3311 Whitesworth Rd | 1/24/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L04 | 3311 Whitesworth Rd | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L04 | 3311 Whitesworth Rd | 1/21/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L04 | 3311 Whitesworth Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L04 | 3311 Whitesworth Rd | 1/12/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L04 | 3311 Whitesworth Rd | 7/10/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L03 | 3313 Whitesworth Rd | 3/23/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
14258 Jarrttsville Pike
Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M43P299L03 | 3313 Whitesworth Rd | 4/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L03 | 3313 Whitesworth Rd | 8/17/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L03 | 3313 Whitesworth Rd | 1/25/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L03 | 3313 Whitesworth Rd | 7/17/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L03 | 3313 Whitesworth Rd | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M43P299L03 | 3313 Whitesworth Rd | 7/18/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L03 | 3313 Whitesworth Rd | 1/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L03 | 3313 Whitesworth Rd | 7/13/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L02 | 3315 Whitesworth Rd | 3/20/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L02 | 3315 Whitesworth Rd | 4/25/2006 | | 1.2 | ND(0.50) | 0.20 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L02 | 3315 Whitesworth Rd | 8/14/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L02 | 3315 Whitesworth Rd | 1/23/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L02 | 3315 Whitesworth Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L02 | 3315 Whitesworth Rd | 1/17/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M43P299L02 | 3315 Whitesworth Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | 0.18 J | ND(0.50) | 0.095 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L02 | 3315 Whitesworth Rd | 1/14/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L02 | 3315 Whitesworth Rd | 7/10/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0101 | 3317 Whitesworth Rd | 3/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0101 | 3317 Whitesworth Rd | 4/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0101 | 3317 Whitesworth Rd | 8/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0101 | 3317 Whitesworth Rd | 1/26/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0101 | 3317 Whitesworth Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0101 | 3317 Whitesworth Rd | 1/16/2008 | | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(0.5) | ND(5) |
| M43P299L0101 | 3317 Whitesworth Rd | 7/14/2008 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0101 | 3317 Whitesworth Rd | 1/8/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0101 | 3317 Whitesworth Rd | 7/10/2009 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0102 | 3317 Whitesworth Rd | 3/21/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |

Attachment A - Historic Private Supply Well Analytical Table

Inactive Exxon Facility #28077
 14258 Jarrttsville Pike
 Phoenix, MD

| Map/Parcel/ Lot | Address | Sample Date | POET Sample Point | MTBE (µg/L) | Benzene (µg/L) | Toluene (µg/L) | Ethyl- benzene (µg/L) | Total Xylenes (µg/L) | Naph- thalene (µg/L) | DIPE (µg/L) | ETBE (µg/L) | TAME (µg/L) | TBA (µg/L) |
|--------------------|---------------------|----------------|-------------------------|----------------|-------------------|-------------------|-----------------------------|----------------------------|----------------------------|----------------|----------------|----------------|---------------|
| M43P299L0102 | 3317 Whitesworth Rd | 4/25/2006 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0102 | 3317 Whitesworth Rd | 8/21/2006 | | 0.24 J | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |
| M43P299L0102 | 3317 Whitesworth Rd | 7/16/2007 | | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(0.50) | ND(5.0) |