

# Brownfield Master Inventory (BMI) Report - Archived Sites, By County

1/4/2017

## Allegany

**BMI #:** MD1259 Allegany Technology, Inc. (SI Technologies, Vishay SI Technologies)  
 11400 Pittsburg Plate Glass Road (Mexico Cumberland  
 Farms Industrial Park)  
 Glass Road (Mexico Farms Industrial Park)

Assoc. Entity:

VCP Status:

### Site Status

Assessment Ongoing: No Remediation Ongoing No Determination:  
 FIS: -1 Factsheet:

### Regulatory Interest

Brownfield: State Master\*: Voluntary Cleanup Program (VCP):  
 Site Assessment: Non Master\*: National Priority List (NPL):  
 Formerly Used Federal Facility: Groundwater Investigation Site (GWI): Yes  
 Defense Site (FUDS):

**BMI #:** MD0952 Country Club Mall ( )  
 1262 Vocke Road Lavale

Assoc. Entity: Lavale Associates By J. J. Gumberg Co./Agent

VCP Status: RP

### Site Status

Assessment Ongoing: No Remediation Ongoing No Determination: NFRD  
 FIS: -1 Factsheet: <http://www.mde.state.md.us/assets/document/brownfields/countryclub.pdf>

### Regulatory Interest

Brownfield: State Master\*: Voluntary Cleanup Program (VCP): Yes  
 Site Assessment: Non Master\*: National Priority List (NPL):  
 Formerly Used Federal Facility: Groundwater Investigation Site (GWI):  
 Defense Site (FUDS):

**BMI #:** MD0915 Former PPG - Works No. 7 (Pittsburg Plate Glass) (PPG Industries/Mexico  
 Farms Industrial Park)  
 11601 Pittsburg Plate Glass Road Cumberland

Assoc. Entity: PPG Industries, Inc.

VCP Status: RP

### Site Status

Assessment Ongoing: No Remediation Ongoing No Determination: NFRD  
 FIS: -1 Factsheet: [http://www.mde.state.md.us/assets/document/brownfields/PPG\\_Works.pdf](http://www.mde.state.md.us/assets/document/brownfields/PPG_Works.pdf)

### Regulatory Interest

Brownfield: Yes State Master\*: Voluntary Cleanup Program (VCP): Yes  
 Site Assessment: Non Master\*: National Priority List (NPL):  
 Formerly Used Federal Facility: Groundwater Investigation Site (GWI): Yes  
 Defense Site (FUDS):

\* State Master and Non Master Lists replaced by Brownfield Master Inventory

# Brownfield Master Inventory (BMI) Report - Archived Sites, By County

1/4/2017

## Allegany

**BMI #:** MD0915 Former PPG - Works No. 7 (Pittsburg Plate Glass) (PPG Industries/Mexico Farms Industrial Park)

11601 Pittsburg Plate Glass Road

Cumberland

Assoc. Entity: Hunter Douglas Northeast, Inc.

VCP Status: IP

### Site Status

Assessment Ongoing: No    Remediation Ongoing: No    Determination: NFRD

FIS: -1    Factsheet: [http://www.mde.state.md.us/assets/document/brownfields/PPG\\_Works.pdf](http://www.mde.state.md.us/assets/document/brownfields/PPG_Works.pdf)

### Regulatory Interest

Brownfield: Yes	State Master*:	Voluntary Cleanup Program (VCP): Yes
Site Assessment:	Non Master*:	National Priority List (NPL):
Formerly Used Defense Site (FUDS):	Federal Facility:	Groundwater Investigation Site (GWI): Yes

**BMI #:** MD0915

11601 Pittsburg Plate Glass Road

Cumberland

Assoc. Entity: Allegany County Commissioners

VCP Status: RP

### Site Status

Assessment Ongoing: No    Remediation Ongoing: No    Determination: NFRD

FIS: -1    Factsheet: [http://www.mde.state.md.us/assets/document/brownfields/PPG\\_Works.pdf](http://www.mde.state.md.us/assets/document/brownfields/PPG_Works.pdf)

### Regulatory Interest

Brownfield: Yes	State Master*:	Voluntary Cleanup Program (VCP): Yes
Site Assessment:	Non Master*:	National Priority List (NPL):
Formerly Used Defense Site (FUDS):	Federal Facility:	Groundwater Investigation Site (GWI): Yes

**BMI #:** MD0458 Aetna Lumber ( )

Route 220 - 7 Miles South/Southwest of  
Cumberland

Cumberland

Assoc. Entity:

VCP Status:

### Site Status

Assessment Ongoing: No    Remediation Ongoing: No    Determination:

FIS: -1    Factsheet: <http://www.mde.state.md.us/assets/document/brownfields/aetna.pdf>

### Regulatory Interest

Brownfield:	State Master*:	Voluntary Cleanup Program (VCP):
Site Assessment:	Non Master*:	National Priority List (NPL):
Formerly Used Defense Site (FUDS):	Federal Facility:	Groundwater Investigation Site (GWI):

\* State Master and Non Master Lists replaced by Brownfield Master Inventory



# Brownfield Master Inventory (BMI) Report - Archived Sites, By County

1/4/2017

## Allegany

**BMI #:** MD0195 Cumberland Gas Light Company ( )

200-214 North Mechanic Street

Cumberland

Assoc. Entity: Standard Bank

VCP Status:

### Site Status

Assessment Ongoing: No    Remediation Ongoing: No    Determination: NFA

FIS: -1 Factsheet: <http://www.mde.state.md.us/programs/Land/MarylandBrownfieldVCP/mapping/Documents/Cumberland%20Gas%20Light.pdf>

### Regulatory Interest

Brownfield:	State Master*:	Voluntary Cleanup Program (VCP):
Site Assessment: Yes	Non Master*:	National Priority List (NPL):
Formerly Used Defense Site (FUDS):	Federal Facility:	Groundwater Investigation Site (GWI):

**BMI #:** MD0122 Midland Sunoco Station ( )

14823 Broadway Avenue, SW

Midland

Assoc. Entity:

VCP Status:

### Site Status

Assessment Ongoing: No    Remediation Ongoing: No    Determination:

FIS: -1 Factsheet: No Fact Sheet Available.

### Regulatory Interest

Brownfield:	State Master*:	Voluntary Cleanup Program (VCP):
Site Assessment: Yes	Non Master*:	National Priority List (NPL):
Formerly Used Defense Site (FUDS):	Federal Facility:	Groundwater Investigation Site (GWI):

\* State Master and Non Master Lists replaced by Brownfield Master Inventory