



SUMMARY INFORMATION ON UNDERGROUND STORAGE TANKS

Public Record Posted Date: November 1, 2019

This report is compiled annually per the US Environmental Protection Agency (EPA) grant requirements for implementing the public record provision of the Energy Policy Act of 2005. The report was created per the document *Grant Guidelines To States For Implementing The Public Record Provision Of The Energy Policy Act Of 2005*, EPA 510-R-19-002, Sept. 2019.

GENERAL INFORMATION

Federally Regulated Motor Fuel and Used Oil Systems

Total Number of UST Facilities:	<u>2,732</u>
Total Number of USTs:	<u>7,367</u>

SUMMARY INFROMATION FOR ON-SITE INSPECTIONS

Number of UST Facilities Inspected:	<u>922</u>
Inspection Period Dates:	<u>October 1, 2018</u> to <u>September 30, 2019</u>

Percent Compliance (Combined Measure): <u>76.7%</u>

Note: Tank, facility, and on-site inspection information is based on reports from MDE inspection staff and reports from certified UST third-party inspectors. On-site inspections measure compliance with Code of Maryland Regulations 26.10, "Oil Pollution and Tank Management," which require release detection, financial responsibility, corrosion protection, and spill/overfill prevention.

SUMMARY INFORMATION FOR RELEASES

Number of Confirmed UST Releases:

Release Reporting Period Dates:

October 1, 2018 to September 30, 2019



180

Maryland Department of the Environment 1800 Washington Boulevard | Baltimore, MD 21230-1718 | <u>www.mde.maryland.gov</u> 410-537-3000 | 800-633-6101 | TTY Users: 800-735-2258 Oil Control Program | November 2019

			Cause													
Source		Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown*		
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	34	39	0	0	0	0	3	9	26	76	0	0	3	9	2	6
Piping	8	9	0	0	0	0	3	38	4	50	0	0	0	0	1	12
Dispenser	7	9	0	0	1	14	1	14	0	0	0	0	1	14	4	58
STP	1	1	0	0	0	0	1	100	0	0	0	0	0	0	0	0
Delivery Problem	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Other	3	3	0	0	0	0	0	0	0	0	0	0	3	100	0	0
Unknown*	34	39	0	0	0	0	0	0	0	0	0	0	0	0	34	100
Totals	87 **	100	0	0	1	1	8	8	30	30	0	0	7	7	41	41

SUMMARY INFORMATION FOR RELEASE SOURCES AND CAUSES

= number, % = percent of total number, STP = Submersible Turbine Pump Area

Note: Release source and cause information is based on federally regulated tanks. Source and cause data were collected using the best available information from MDE inspection staff, owners, operators, certified installers/inspectors, and consultants.

* To the best of their ability, owners, operators, certified installers/inspectors, and consultants report the source of the release. However, in most instances, the exact source and cause of the release is not able to be determined.

** The 87 sites are those sites that a conclusion on release source has been determined. Not all sites reported to EPA as confirmed releases are included in this summary.

ADDDITIONAL INFORMATION

Additional information may be obtained from the Maryland Department of Environment's Oil Control Program at 410-537-3442.