



**Brownfield Master Inventory (BMI) Report - Archived Sites, By County**  
July 02, 2018

**Allegany**

**BMI #:** MD0915 Former PPG - Works No. 7 (Pittsburg Plate Glass) - PPG Industries/Mexico Farms Industrial Park: 11601 Pittsburg Plate Glass Road, Cumberland

Allegany County Commissioners, 701 Kelly Road, Cumberland MD 21502	RESPONSIBLE PERSON
Hunter Douglas Northeast, Inc., 11401 PPG Road, S.E., Cumberland MD 21502	INCULPABLE PERSON
PPG Industries, Inc., One PPG Place, Pittsburgh MD 15272	RESPONSIBLE PERSON

**Assessment Ongoing:** No      **Remediation Ongoing:** No      **Determination Issued:** Yes  
**Withdrawn from VCP:** No      **Site Closed/Archived:** Yes  
**Factsheet URL:** [http://mde.maryland.gov/programs/Land/MarylandBrownfieldVCP/Documents/www.mde.state.md.us/assets/document/brownfields/PPG\\_Works.pdf](http://mde.maryland.gov/programs/Land/MarylandBrownfieldVCP/Documents/www.mde.state.md.us/assets/document/brownfields/PPG_Works.pdf)

Voluntary Cleanup Program (VCP): <u>Yes</u>	Fed Facility: <u>No</u>	State Master List*: <u>No</u>
Groundwater Investigation Site (GWI) <u>Yes</u>	Frm. Used Def. Site (FUDS): <u>No</u>	Non-Master List*: <u>No</u>
Brownfield Assessment Project: <u>Yes</u>	National Priority List (NPL): <u>No</u>	Site Assessment Project: <u>No</u>

**BMI #:** MD0952 Country Club Mall - : 1262 Vocke Road, Lavale

Lavale Associates By J. J. Gumberg Co./Agent, Brinton Executive Center, 1051 Brinton Road, Pittsburgh PA 15221	RESPONSIBLE PERSON
--	--------------------

**Assessment Ongoing:** No      **Remediation Ongoing:** No      **Determination Issued:** Yes  
**Withdrawn from VCP:** No      **Site Closed/Archived:** Yes  
**Factsheet URL:** <http://mde.maryland.gov/programs/Land/MarylandBrownfieldVCP/Documents/www.mde.state.md.us/assets/document/brownfields/countryclub.pdf>

Voluntary Cleanup Program (VCP): <u>Yes</u>	Fed Facility: <u>No</u>	State Master List*: <u>No</u>
Groundwater Investigation Site (GWI) <u>No</u>	Frm. Used Def. Site (FUDS): <u>No</u>	Non-Master List*: <u>No</u>
Brownfield Assessment Project: <u>No</u>	National Priority List (NPL): <u>No</u>	Site Assessment Project: <u>No</u>

**BMI #:** MD0457 Willison Oil Co. - : Baltimore Pike, Route 2 Box 101, Cresaptown

**Assessment Ongoing:** No      **Remediation Ongoing:** No      **Determination Issued:** No  
**Withdrawn from VCP:** No      **Site Closed/Archived:** Yes  
**Factsheet URL:** No Fact Sheet Available.

Voluntary Cleanup Program (VCP): <u>No</u>	Fed Facility: <u>No</u>	State Master List*: <u>No</u>
Groundwater Investigation Site (GWI) <u>No</u>	Frm. Used Def. Site (FUDS): <u>No</u>	Non-Master List*: <u>No</u>
Brownfield Assessment Project: <u>No</u>	National Priority List (NPL): <u>No</u>	Site Assessment Project: <u>No</u>

**BMI #:** MD0458 Aetna Lumber - : Route 220 - 7 Miles South/Southwest of Cumberland, Cumberland

**Assessment Ongoing:** No      **Remediation Ongoing:** No      **Determination Issued:** No  
**Withdrawn from VCP:** No      **Site Closed/Archived:** Yes  
**Factsheet URL:** <http://www.mde.state.md.us/assets/document/brownfields/aetna.pdf>

Voluntary Cleanup Program (VCP): <u>No</u>	Fed Facility: <u>No</u>	State Master List*: <u>No</u>
Groundwater Investigation Site (GWI) <u>No</u>	Frm. Used Def. Site (FUDS): <u>No</u>	Non-Master List*: <u>No</u>
Brownfield Assessment Project: <u>No</u>	National Priority List (NPL): <u>No</u>	Site Assessment Project: <u>No</u>



**Brownfield Master Inventory (BMI) Report - Archived Sites, By County**  
July 02, 2018

**Allegany**

<b>BMI #:</b> <u>MD0122</u> Midland Sunoco Station - : 14823 Broadway Avenue, SW, Midland			
<b>Assessment Ongoing:</b> <u>No</u>	<b>Remediation Ongoing:</b> <u>No</u>	<b>Determination Issued:</b> <u>Yes</u>	
<b>Withdrawn from VCP:</b> <u>No</u>	<b>Site Closed/Archived:</b> <u>Yes</u>		
<b>Factsheet URL:</b> <u>No Fact Sheet Available.</u>			
Voluntary Cleanup Program (VCP): <u>No</u>	Fed Facility: <u>No</u>	State Master List*: <u>No</u>	
Groundwater Investigation Site (GWI) <u>No</u>	Frm. Used Def. Site (FUDS): <u>No</u>	Non-Master List*: <u>No</u>	
Brownfield Assessment Project: <u>No</u>	National Priority List (NPL): <u>No</u>	Site Assessment Project: <u>Yes</u>	
<b>BMI #:</b> <u>MD0339</u> Precise Metals & Plastics, Inc. (Cumberland Division) - : Day Road SE (in Mexico Farms Industrial Park), Cumberland			
<b>Assessment Ongoing:</b> <u>No</u>	<b>Remediation Ongoing:</b> <u>No</u>	<b>Determination Issued:</b> <u>No</u>	
<b>Withdrawn from VCP:</b> <u>No</u>	<b>Site Closed/Archived:</b> <u>Yes</u>		
<b>Factsheet URL:</b> <u>No Fact Sheet Available.</u>			
Voluntary Cleanup Program (VCP): <u>No</u>	Fed Facility: <u>No</u>	State Master List*: <u>No</u>	
Groundwater Investigation Site (GWI) <u>Yes</u>	Frm. Used Def. Site (FUDS): <u>No</u>	Non-Master List*: <u>No</u>	
Brownfield Assessment Project: <u>No</u>	National Priority List (NPL): <u>No</u>	Site Assessment Project: <u>Yes</u>	
<b>BMI #:</b> <u>MD0328</u> Lavale Warehouse Fire - Former Surplus City Facility: Boughman Surplus: 1210 National Highway, Lavale			
<b>Assessment Ongoing:</b> <u>No</u>	<b>Remediation Ongoing:</b> <u>No</u>	<b>Determination Issued:</b> <u>No</u>	
<b>Withdrawn from VCP:</b> <u>No</u>	<b>Site Closed/Archived:</b> <u>Yes</u>		
<b>Factsheet URL:</b> <u>No Fact Sheet Available.</u>			
Voluntary Cleanup Program (VCP): <u>No</u>	Fed Facility: <u>No</u>	State Master List*: <u>No</u>	
Groundwater Investigation Site (GWI) <u>No</u>	Frm. Used Def. Site (FUDS): <u>No</u>	Non-Master List*: <u>No</u>	
Brownfield Assessment Project: <u>No</u>	National Priority List (NPL): <u>No</u>	Site Assessment Project: <u>No</u>	
<b>BMI #:</b> <u>MD0195</u> Cumberland Gas Light Company - : 200-214 North Mechanic Street, Cumberland			
<b>Assessment Ongoing:</b> <u>No</u>	<b>Remediation Ongoing:</b> <u>No</u>	<b>Determination Issued:</b> <u>Yes</u>	
<b>Withdrawn from VCP:</b> <u>No</u>	<b>Site Closed/Archived:</b> <u>Yes</u>		
<b>Factsheet URL:</b> <a href="http://mde.maryland.gov/programs/Land/MarylandBrownfieldVCP/Documents/Cumberland%20Gas%20Lig ht.pdf">http://mde.maryland.gov/programs/Land/MarylandBrownfieldVCP/Documents/Cumberland%20Gas%20Lig ht.pdf</a>			
Voluntary Cleanup Program (VCP): <u>No</u>	Fed Facility: <u>No</u>	State Master List*: <u>No</u>	
Groundwater Investigation Site (GWI) <u>No</u>	Frm. Used Def. Site (FUDS): <u>No</u>	Non-Master List*: <u>No</u>	
Brownfield Assessment Project: <u>No</u>	National Priority List (NPL): <u>No</u>	Site Assessment Project: <u>Yes</u>	



**Brownfield Master Inventory (BMI) Report - Archived Sites, By County**  
July 02, 2018

**Allegany**

**BMI #:** MD1259 Allegany Technology, Inc. - SI Technologies, Vishay SI Technologies: 11400 Pittsburg Plate Glass Road (Mexico Farms Industrial Park)  
Glass Road (Mexico Farms Industrial Park), Cumberland

**Assessment Ongoing:** No      **Remediation Ongoing:** No      **Determination Issued:** No

**Withdrawn from VCP:** No      **Site Closed/Archived:** Yes

**Factsheet URL:** <http://mde.maryland.gov/programs/Land/MarylandBrownfieldVCP/Documents/Allegany%20Technology.pdf>

Voluntary Cleanup Program (VCP): No      Fed Facility: No      State Master List\*: No

Groundwater Investigation Site (GWI) Yes      Frm. Used Def. Site (FUDS): No      Non-Master List\*: No

Brownfield Assessment Project: No      National Priority List (NPL): No      Site Assessment Project: No